

Rose-Coss, Dylan H, EMNRD

From: Rose-Coss, Dylan H, EMNRD
Sent: Monday, June 17, 2019 11:44 AM
To: 'DeAnn Grant'; Mann, Ryan
Cc: Jennifer Knowlton; Ike Tavaréz; Robert McNeill; Sheldon Hitchcock; Dakota Neel; Rebecca Haskell
Subject: RE: (C-141 Initial) Corazon State Unit CTB 05-19-2019

All,

The NMOCD tracking number for this release is 1RP-5545.

Thanks,

Dylan Rose-Coss

Environmental Scientist
Oil Conservation Division
1220 South St. Francis Drive
Santa Fe, New Mexico 87505

(505) 476-3488

From: DeAnn Grant <agrant@concho.com>
Sent: Monday, June 3, 2019 4:38 PM
To: Rose-Coss, Dylan H, EMNRD <DylanH.Rose-Coss@state.nm.us>; Mann, Ryan <rmann@slo.state.nm.us>
Cc: Jennifer Knowlton <jknowlton@concho.com>; Ike Tavaréz <itavarez@concho.com>; Robert McNeill <RMcNeill@concho.com>; Sheldon Hitchcock <SLHitchcock@concho.com>; Dakota Neel <DNeel2@concho.com>; Rebecca Haskell <RHaskell@concho.com>; DeAnn Grant <agrant@concho.com>
Subject: [EXT] (C-141 Initial) Corazon State Unit CTB 05-19-2019

Mr. Rose-Coss/Mr. Mann,

Please find the attached C-141 for your consideration. Also, attached is the calculation sheet to determine the estimated release volume for Falcon Lined facilities. The liquid lost estimate is based on the spill dimensions and estimated depth of fluid in the liner. The spreadsheet will calculate the volume lost into the liner. No gravel was present in this lined facility as it is a Falcon Liner. The unrecovered volume is a residue left behind on the liner and equipment which will be cleaned by pressure wash. If you have any questions or concerns please do not hesitate to contact me

Thank you,

DeAnn Grant

HSE Administrative Assistant

agrant@concho.com

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443



