

3R -

9

**GENERAL
CORRESPONDENCE**

YEAR(S):

1999

BP Amoco



Amoco Production Company
San Juan Operations Center
200 Amoco Court
Farmington, New Mexico 87401

June 15, 1999

Bureau of Land Management
1235 La Plata Hwy
Farmington, NM 87401

Attention: Ruben Sanchez

Florance 16A Seep

Listed below is Amoco's proposed plan for the above subject wellsite. Please review and advise your concurrence/comments/suggestions.

1. Install sump to collect seepage
2. Divert runoff above the seep(East)
3. Remediate the wash area
4. Fence water areas to protect wildlife
5. Sample spring(s) for water quality/BTEX
6. Evaluate coring to flush the area of hydrocarbons

I am also sending a copy to the NMOCD for their input and approval! Thank you for your help and cooperation in this matter.

A handwritten signature in cursive script that reads "Buddy Shaw".

Buddy Shaw
Environmental Coordinator
(505) 326-9219

CC: NMOCD-Aztec/Santa Fe



STATE OF NEW MEXICO
ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

2040 S. PACHECO
SANTA FE, NEW MEXICO 87505
(505) 827-7131

May 5, 1999

CERTIFIED MAIL
RETURN RECEIPT NO. Z-274-520-651

Mr. B.D. Shaw
Amoco Production Company
200 Amoco Court
Farmington, New Mexico 87401

**RE: GROUND WATER CONTAMINATION
FLORANCE GAS COM #16A WELL SITE**

Dear Mr. Shaw:

The New Mexico Oil Conservation Division (OCD) recently inspected Amoco's Florance Gas Com #16A well site located in Unit P, Section 6, Township 30 North, Range 9 West, NMPM, San Juan County, New Mexico. During the inspection it was noted that product and water was seeping out of the top of a bedrock contact approximately 300 feet from the well pad. This bedrock underlies the Florance Gas Com #16A well pad and it appears that the fluids are originating from this site.

A review of OCD files on this site shows that both Amoco and Williams Field Services (WFS) had unlined pits at this location for the disposal of oilfield wastes. The OCD requires that both Amoco and WFS address whether this soil and ground water contamination is a result of their activities. The OCD requires that Amoco investigate and remediate any contamination related to their activities pursuant to Amoco's previously approved soil and ground water investigation and remediation plans.

The OCD requests that Amoco work in conjunction with WFS in implementing investigation and remediation of the site.

If you have any questions or comments, please call me at (505) 827-7154.

Sincerely,

A handwritten signature in black ink that reads "William C. Olson".

William C. Olson
Hydrologist
Environmental Bureau

xc: OCD Aztec District Office
Bill Liess, BLM Farmington District Office
Ingrid A. Deklau, Williams Field Services



STATE OF NEW MEXICO
ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE



GARY E. JOHNSON
GOVERNOR

JENNIFER A. SALISBURY
CABINET SECRETARY

1900 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-4178 FAX (505) 334-4170

FAX TRANSMITTAL SHEET

DATE: April 30, 1999

TO: Bill Olson FROM: Denny Foust
Nmoco

COMMENTS: Amoco Florence Gas com 16A
P-06-30N-09W

NUMBER OF PAGES INCLUDING COVER: 2

FLORANCE #16A EXCAVATION

06/26/96

