

From: [Eads, Cristina, EMNRD](#)
To: "Bob Asher"
Cc: [Mike EMNRD Bratcher \(mike.bratcher@state.nm.us\)](#); [Robert EMNRD Hamlet \(Robert.Hamlet@state.nm.us\)](#); [Victoria EMNRD Venegas \(Victoria.Venegas@state.nm.us\)](#)
Subject: NRM2004834379 BOYKIN ACV #1 BATTERY @ 30-015-25334
Date: Friday, September 4, 2020 2:41:00 PM
Attachments: [\(C-141 Remediation Plan\) NRM2004834379.pdf](#)
[image003.png](#)

NRM2004834379 BOYKIN ACV #1 BATTERY @ 30-015-25334

Bob,

The OCD has approved the Site Characterization and Remediation Plan for incident # NAB1927162165 with the following conditions:

- A liner inspection will be performed within the lined area of the release. If any holes or tears are discovered in the liner, the responsible party will perform a soil investigation underneath the liner. Any contamination discovered will be reported and remediated in a similar manner as described in this remediation plan.

The signed C-141 can be found in the online image data base under the incident #. Please let me know if you have any questions.

Thanks,

Cristina Eads

Environmental Bureau

EMNRD – Oil Conservation Division

5200 Oakland Avenue NE, Suite 100

Albuquerque, New Mexico 87113

505.670-5601

email: Cristina.Eads@state.nm.us



OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.