

## Bratcher, Mike, EMNRD

---

**From:** Bratcher, Mike, EMNRD  
**Sent:** Thursday, October 01, 2015 9:38 AM  
**To:** 'Blair, Yvonne B'  
**Cc:** Landenberger, Dan R; Case, Nicholas L  
**Subject:** RE: FW: 20200 line leak

Thank you. OCD tracking number for this event is **2RP-3299**. Please reference this number in future correspondence.

Mike Bratcher  
NMOCD District 2  
811 S. First Street  
Artesia, NM 88210  
O: 575-748-1283 X108  
C: 575-626-0857  
F: 575-748-9720

---

**From:** Blair, Yvonne B [<mailto:YBBlair@dcpmidstream.com>]  
**Sent:** Wednesday, September 30, 2015 10:35 AM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Landenberger, Dan R; Case, Nicholas L  
**Subject:** RE: FW: 20200 line leak

Mike

This is our remediation plan for now. Our construction crew is still assessing the damage and root cause of pipeline failure. We may need to replace additional pipe so we will provide an update as soon possible.  
DCP will stay on pipeline ROW.

Yvonne

---

**From:** Bratcher, Mike, EMNRD [<mailto:mike.bratcher@state.nm.us>]  
**Sent:** Wednesday, September 30, 2015 7:15 AM  
**To:** Blair, Yvonne B  
**Subject:** RE: FW: 20200 line leak

Ms. Blair,

Please copy me on your remediation proposal.

Thank you,

**From:** Pair, Randal [<mailto:rpair@blm.gov>]  
**Sent:** Tuesday, September 29, 2015 4:46 PM  
**To:** Blair, Yvonne B

**Cc:** Dade, Randy, EMNRD; Bratcher, Mike, EMNRD; Gall, Sarah; Valencia, Israel; Landenberger, Dan R; Case, Nicholas L; Walker, Clayton D

**Subject:** Re: FW: 20200 line leak

Most of the area surrounding this Lat-Long has been surveyed for archeology. However, about 70-ft to the NE (azimuth 45-degrees) is an area that has not been surveyed. If your spill might extend more than 70-ft to the NE, please send me a site diagram. I will need to review archeology before I can approve this remediation plan. Otherwise, I approve this proposal. Contact me with confirmation lab results prior to backfilling.

Randal "Randy" Pair  
Envir. Protection Specialist - Realty Compliance  
office: 575.234.6240  
cell: 575.361.0062  
email: [rpair@blm.gov](mailto:rpair@blm.gov)

On Wed, Sep 23, 2015 at 3:56 PM, Blair, Yvonne B <[YBBlair@dcpmidstream.com](mailto:YBBlair@dcpmidstream.com)> wrote:

Mr. Pair and Mr. Dade

Please see the attached action plan for remediation and repair of the 20200 Line leak off Red Rd in Eddy County.

Yvonne Blair

Compliance Coordinator

DCP Midstream

575-361-2406