

FIELD SPILL REPORT

Distribution List: CJ Barry, TA Savoie, RL Gawlik, JR Smitherman, SF Johnson, FD Schoch

DATE: May 7, 2013

LOCATION OF SPILL SITE: PLU 68 Btry

GPS COORDINATES (Lat & Long): 32 12'27.57" N 103 47'53.78" W

ESTIMATED VOLUMES (Oil & Water Separately):

**If BBLs Recovered are not available at time of Initial Report: Send in Followup report when numbers are known*

Volume spilled:		BBLs Spilled	*BBLs Recovered	Net Spilled			BBLs Spilled	*BBLs Recovered	Net Spilled
On ground /or earth berm -	Oil:	5	0	5	Water:				0
Contained in impervious liner -	Oil:			0	Water:				0
Total:	Oil:	5	0	5	Water:	0	0	0	0

DESCRIPTION (What happened?):

Flange on pig receive had loose bolts.

SPILL RESPONSE (How was the spill cleaned up?):

Pipeline personal report spill and contacted backhoe to remove contaminated caliche off pad.

PICTURE ATTACHMENT:



