

**From:** Patterson, Heather, EMNRD  
**To:** ["Blevins, Bradley"; Bratcher, Mike, EMNRD](#)  
**Subject:** RE: PLU CVX JV BS 0008H 2RP-3271  
**Date:** Monday, March 28, 2016 10:26:00 AM  
**Attachments:** image001.png

---

Bradley,

We will need a field screen confirmation sample to show the area was scraped and cleaned.

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

If you have any questions or concerns, and for notification, please contact me.

Heather Patterson  
Environmental Specialist  
NMOCD District II  
Office (575)748-1283 ext.101  
Cell (575)703-0228

---

**From:** Blevins, Bradley [mailto:BBlevins@BassPet.Com]  
**Sent:** Tuesday, March 22, 2016 9:44 AM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD  
**Cc:** Blevins, Bradley  
**Subject:** PLU CVX JV BS 0008H 2RP-3271

Mike/ Heather

Attached you will find the initial C-141 for the release that occurred on the PLU CVX JV BS 008H 2RP-3271 when the packing gland failed on the triplex pump. As seen in the attached internal spill report 49 barrels was released inside the lined containment, 48 barrels of same fluid was recovered. One barrel of fluid did escape the lined containment through a pinhole of containment. Since only one barrel or less was released to the ground surface I would like to request closure of 2RP-3271. If approved I will submit a final C-141 and closure report. Please let me know if you have any questions or concerns. Thank you.



Brad Blevins  
BOPCO, LP  
522 W. Mermod, Suite 704  
Carlsbad, NM 88220  
Office-575-887-7329  
Cell-1-432-214-3704  
[bblevins@basspet.com](mailto:bblevins@basspet.com)