

Bratcher, Mike, EMNRD

From: Blaney, Karolina <Karolina.Blaney@wpxenergy.com>
Sent: Wednesday, February 1, 2017 3:20 PM
To: Weaver, Crystal, EMNRD; Bratcher, Mike, EMNRD; 'stucker@blm.gov'
Subject: RE: WPX RDU 14 - characterization plan
Attachments: RDU 14 Characterization Plan .docx

Hello,
Attached is the characterization plan for the RDU 14 spill.
Please let me know if you have any questions or concerns.
Thank you and have a great afternoon,

Karolina Blaney
Environmental Specialist
WPX Energy
Office: (575) 885-7514
Cell: (970) 589-0743
karolina.blaney@wpxenergy.com

From: Weaver, Crystal, EMNRD [mailto:Crystal.Weaver@state.nm.us]
Sent: Tuesday, January 03, 2017 10:52 AM
To: Blaney, Karolina <Karolina.Blaney@wpxenergy.com>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; 'stucker@blm.gov' <stucker@blm.gov>
Subject: RE: WPX RDU 14 - spill notification - correction

RE: WPX Energy, Inc. * RDU #14 * 30-015-25208 * 2RP-4047

Karolina,

I have included a scanned copy of the signed Initial C-141 Remediation Permit along with an attached Conditions of Approval. The OCD tracking number for this event is 2RP-4047.

Thank you,

Crystal Weaver
Environmental Specialist
OCD – Artesia District II
811 S. 1st Street
Artesia, NM 88210
Office: 575-748-1283 ext. 101
Cell: 575-840-5963
Fax: 575-748-9720

From: Blaney, Karolina [<mailto:Karolina.Blaney@wpxenergy.com>]
Sent: Friday, December 16, 2016 2:59 PM
To: Patterson, Heather, EMNRD <Heather.Patterson@state.nm.us>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; 'stucker@blm.gov' <stucker@blm.gov>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>
Subject: RE: WPX RDU 14 - spill notification - correction

Attached is the C-141 for the produced water and oil spill that occurred at the RDU 14 well pad.
Please let me know if you have any questions or suggestions.

I will be gone for the holidays starting this Sunday, 12/18 returning to work on January 9th. I will be checking my email so please don't hesitate to contact me if anything comes up.

Happy Holidays!!!!

Karolina Blaney
Environmental Specialist
WPX Energy
Office: (575) 885-7514
Cell: (970) 589-0743
karolina.blaney@wpxenergy.com

From: Blaney, Karolina
Sent: Monday, December 12, 2016 1:19 PM
To: 'Patterson, Heather, EMNRD' <Heather.Patterson@state.nm.us>; 'Bratcher, Mike, EMNRD' <mike.bratcher@state.nm.us>; 'stucker@blm.gov' <stucker@blm.gov>
Subject: RE: WPX RDU 11 - spill notification - correction

Good afternoon,

I need to make a correction to the notification below; not all fluids were contained inside the SPCC berm; less than 2 bbls misted outside the containment but it's all contained on the well pad.
Thank you,

Karolina Blaney
Environmental Specialist
WPX Energy
Office: (575) 885-7514
Cell: (970) 589-0743
karolina.blaney@wpxenergy.com

From: Blaney, Karolina
Sent: Monday, December 12, 2016 11:34 AM
To: Patterson, Heather, EMNRD <Heather.Patterson@state.nm.us>; 'Bratcher, Mike, EMNRD' <mike.bratcher@state.nm.us>; 'stucker@blm.gov' <stucker@blm.gov>
Subject: WPX RDU 11 - spill notification

Good morning,

Yesterday, 12/11/16, WPX had a spill at the RDU 14 well pad, API # 30-015-25208; L-S26-T26S-R30E. The cause of this spill is equipment failure. A pump failed causing tank to overfill. Estimated 130 bbls of oil was spilled into dirt SPCC containment berm; 105 bbls were recovered. None of the fluids have left the containment. The C-141 report will be submitted within 15 days from the incident.

Please let me know if you have any questions or concerns.

Thank you and have a great week!

Karolina Blaney

Environmental Specialist

WPX Energy

Cell: (970) 589-0743

karolina.blaney@wpxenergy.com