Bratcher, Mike, EMNRD

From: Geoff Leking <geoff@etechenv.com>
Sent: Wednesday, August 30, 2017 12:34 PM

To: Bratcher, Mike, EMNRD
Cc: stucker@blm.gov

Subject: RE: Chisolm Neptune 31 Fedearal #1 **Attachments:** 8.30.17 addtl AH locations.jpg

Mike

For your review, attached is a map displaying the proposed locations for two additional auger holes labeled Proposed AH 9 and Proposed AH 10 at which further delineation will be performed prior to remediation. I look forward to your response. Thanks, Mike.

Geoff Leking

Etech Environmental & Safety Solutions, Inc.

PO Box 62228

Midland, Texas 79711

Office: (432)563-2200 ext. 212

Mobile: (432)425-7160 Fax: (432)563-2213

CONFIDENTIAL

This e-mail message, including any attachments, is intended solely for the individual(s) named above. It contains confidential and/or propriety information. If you are not the intended recipient, please do not read, copy or distribute it or any information it contains. Please immediately notify the sender by return mail and delete it.

From: Bratcher, Mike, EMNRD [mailto:mike.bratcher@state.nm.us]

Sent: Wednesday, August 30, 2017 12:11 PM

To: Geoff Leking

Subject: RE: Chisolm Neptune 31 Fedearal #1

Geoff,

The delineation needs to be done up front. OCD wants to migrate towards the attached COA document.

From: Geoff Leking [mailto:geoff@etechenv.com]
Sent: Wednesday, August 30, 2017 8:52 AM

To: Bratcher, Mike, EMNRD < mike.bratcher@state.nm.us>

Subject: Chisolm Neptune 31 Fedearal #1

Mike

May I do further delineation on the pad and at the well head at the time of excavation. Thank you.

Geoff Leking

Etech Environmental & Safety Solutions, Inc.

PO Box 62228

Midland, Texas 79711

Office: (432)563-2200 ext. 212

Mobile: (432)425-7160 Fax: (432)563-2213

CONFIDENTIAL

This e-mail message, including any attachments, is intended solely for the individual(s) named above. It contains confidential and/or propriety information. If you are not the intended recipient, please do not read, copy or distribute it or any information it contains. Please immediately notify the sender by return mail and delete it.