

From: [Weaver, Crystal, EMNRD](#)
To: [DeLeon, Josepha](#); [Bratcher, Mike, EMNRD](#); [Mark Naranjo](#); [Honea, Tammy](#)
Cc: [Barringer, Andrew J](#); [Debeyessey, Svetlana](#); [Herrera-Murillo, Cindy O](#)
Subject: RE: Spill at SKEEN CTB
Date: Friday, February 23, 2018 1:19:00 PM
Attachments: [2RP-4578.pdf](#)

RE: Chevron * Skeen CTB (DOR 1/3/18) * 30-015-41047 * 2RP-4578

Josie,

I included SLO on this email just as I had done on the last one, since both of the Skeen releases - Skeen CTB (DOR 1/3/18) and Skeen CTB (DOR 1/19/18) that you all have reported are listed at the same location which when I check my records I show this location to be SLO surface ownership and SLO mineral ownership.

Thank you,

Crystal Weaver

Environmental Specialist
OCD – Artesia District II
811 S. 1st Street
Artesia, NM 88210
Office: 575-748-1283 ext. 101
Cell: 575-840-5963
Fax: 575-748-9720

-----Original Message-----

From: DeLeon, Josepha [mailto:JDxD@chevron.com]
Sent: Thursday, January 18, 2018 2:05 PM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>
Cc: Barringer, Andrew J <Andrew.Barringer@chevron.com>; Debeyessey, Svetlana <LDebeyessey@chevron.com>; Herrera-Murillo, Cindy O <CHerreraMurillo@chevron.com>
Subject: RE: Spill at SKEEN CTB

Thank you Mike for your help. Attached is the revised form (4/3/2017) with the updated API # of the well closest to the CTB. I conferred with our Regulatory Specialist and now realize that flaring events and spill events are different in submitting API #'s. Going forward, I will ensure one API # for spills with Long/Lat GPS coordinates as instructed.

Thank you Cindy for your assistance in obtaining correct API number for spills.

-----Original Message-----

From: Bratcher, Mike, EMNRD [mailto:mike.bratcher@state.nm.us]

Sent: Thursday, January 18, 2018 1:22 PM

To: DeLeon, Josepha <JDxD@chevron.com>; Weaver, Crystal, EMNRD
<Crystal.Weaver@state.nm.us>

Cc: Barringer, Andrew J <Andrew.Barringer@chevron.com>; Debeysey, Svetlana
<LDebeysey@chevron.com>

Subject: [**EXTERNAL**] RE: Spill at SKEEN CTB

Hello Josepha,

I am sending a link to the "forms" page on the OCD website. Please download the revised edition of Form C-141 for future use. There isn't any major changes, but it does request the Lat/Long to be in decimal degree/NAD 83 format.

In regard to the current C-141, the Lat/Long will need to be converted from its current format. Also, the form lists five API numbers. We can only use one API number for data entry purposes, so I would suggest using the API number closest to the CTB. All of the listed API numbers have an admin order number assigned for a CTB (they are all, or a combination of, CTB 684-A, CTB 684-B, and, CTB 684-O). The latest image currently on Google Earth is from 2014, but shows a battery of tanks adjacent (west) of the Skeen 2-26-27 St 2H (API: 30-015-41047). Please determine if this is the battery that had the release and resubmit the C-141 on the updated form, using the requested Lat/Long and one API number only. After COB today, I will go ahead and submit the C-141 you sent, for processing using the API number for the 2H. It will be entered as an Initial only, until a corrected copy is received.

Also, I appreciate your including photos of the battery and the statement as to liner integrity. While OCD would prefer photos of the battery after clean up, the statement attesting to liner integrity is required to process the form as "Initial/Final".

Here is the link to the latest version of the form: <http://www.emnrd.state.nm.us/OCD/forms.html>

It was revised 4/3/2017 and is available in PDF and Word format.

If you have any questions or concerns, please contact me or Crystal Weaver.

Thank you,

Mike Bratcher
NMOCD District 2
811 South First Street

Artesia, NM 88210
575-748-1283 Ext 108

-----Original Message-----

From: DeLeon, Josepha [mailto:JDXD@chevron.com]
Sent: Thursday, January 18, 2018 10:19 AM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>
Cc: Barringer, Andrew J <Andrew.Barringer@chevron.com>; Debeysey, Svetlana <LDebeysey@chevron.com>
Subject: RE: Spill at SKEEN CTB

Mike / Crystal, attached is the C-141 for the spill at Skeen CTB that occurred on January 3, 2018.

-----Original Message-----

From: Bratcher, Mike, EMNRD [mailto:mike.bratcher@state.nm.us]
Sent: Thursday, January 04, 2018 6:43 AM
To: DeLeon, Josepha <JDXD@chevron.com>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; jamos@blm.gov; Shelly Tucker <stucker@blm.gov>
Subject: [****EXTERNAL****] RE: Spill at SKEEN CTB

Thank you for the notification.

Mike Bratcher
NMOCD District 2
811 South First Street
Artesia, NM 88210
575-748-1283 Ext 108

-----Original Message-----

From: DeLeon, Josepha [mailto:JDXD@chevron.com]
Sent: Thursday, January 4, 2018 6:27 AM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; jamos@blm.gov; Shelly Tucker <stucker@blm.gov>
Subject: Spill at SKEEN CTB

We had a spill late yesterday. Please accept this as my immediate notification I will submit C141

Date of Spill: 1/3/2018
Group: Delaware basin
Location: Carlsbad

State / County: NM. EDDY COUNTY

API Number or;

Permit Number: N/A

GPS: 32° 4'45.77"N; 104° 9'49.26"W

Incident: Spill to secondary containment Type of secondary containment, if applicable: lined berm, none outside of berm. Pictures are forthcoming.

Material spilled: oil

Volume: 12.3 bbls

Volume Recovered: approx. 8.5 bbls, still vac

Description: Failure of victaulic clamp on top of check valve.

Sent from my iPhone