

From: [Weaver, Crystal, EMNRD](mailto:Crystal.Weaver@state.nm.us)
To: "Wade_Dittrich@oxy.com"; stucker@blm.gov
Cc: [Bratcher, Mike, EMNRD](mailto:mike.bratcher@state.nm.us); ben@trinityoilfieldservices.com; duskie@trinityoilfieldservices.com; Jennifer_Smith@oxy.com
Subject: RE: Lost Tank 33 Fed. 2 SWD
Date: Friday, January 19, 2018 4:03:00 PM
Attachments: [1. 4542 - COAs and signed C-141 Initial.pdf](#)

RE: OXY * Lost Tank 33 Federal #2 SWD * 30-015-29330 * 2RP-4542

Wade,

I have included a scanned copy of the signed Initial C-141 Remediation Permit along with an attached Conditions of Approval (COA). The OCD tracking number for this event is 2RP-4542, please refer to this tracking number on any and all submissions sent in to the OCD. Please remit a site characterization plan (see COA document included in attachment) or advise OCD of plan of action by no later than 1/26/18.

Thank you,

Crystal Weaver

Environmental Specialist
OCD – Artesia District II
811 S. 1st Street
Artesia, NM 88210
Office: 575-748-1283 ext. 101
Cell: 575-840-5963
Fax: 575-748-9720

From: Wade_Dittrich@oxy.com [mailto:Wade_Dittrich@oxy.com]
Sent: Wednesday, December 27, 2017 1:18 PM
To: Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; stucker@blm.gov
Cc: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; ben@trinityoilfieldservices.com; duskie@trinityoilfieldservices.com; Jennifer_Smith@oxy.com
Subject: RE: Lost Tank 3 Fed. 2 SWD

Crystal,

Here is the corrected C141 for this spill. Sorry about all the confusion. Thank you.

Wade Dittrich
Environmental Specialist

Oxy Permian-New Mexico

575-390-2828 cell

575-397-8214 office

Wade_Dittrich@Oxy.com

From: Weaver, Crystal, EMNRD [<mailto:Crystal.Weaver@state.nm.us>]

Sent: Wednesday, December 27, 2017 12:32 PM

To: Tucker, Shelly <stucker@blm.gov>; Dittrich, John W <Wade_Dittrich@oxy.com>

Cc: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Ben J. Arguijo <ben@trinityoilfieldservices.com>; duskie@trinityoilfieldservices.com; Smith, Jennifer A <Jennifer_Smith@oxy.com>

Subject: [EXTERNAL] RE: Lost Tank 3 Fed. 2 SWD

Hello all,

Even though the titling of the email says the release was for Lost Tank 3 Federal #2 SWD it was actually for Lost Tank 33 Federal SWD #2, if I am not mistaken. A C-141 form was submitted back on 11/21/17 and OCD rejected it on 11/27/17 due to the form having inconsistencies that caused for OCD to be unable to process it. Wade offered to resubmit a corrected one on 11/27/17 but to my knowledge that has not yet been received.

Please resubmit this form by no later than 1/2/18.

Thank you,

Crystal Weaver

Environmental Specialist

OCD – Artesia District II

811 S. 1st Street

Artesia, NM 88210

Office: 575-748-1283 ext. 101

Cell: 575-840-5963

Fax: 575-748-9720

From: Tucker, Shelly [<mailto:stucker@blm.gov>]

Sent: Wednesday, December 27, 2017 12:22 PM

To: Wade Dittrich <Wade_Dittrich@oxy.com>

Cc: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; Ben J. Arguijo <ben@trinityoilfieldservices.com>; duskie@trinityoilfieldservices.com; Jennifer_Smith@oxy.com

Subject: Re: Lost Tank 3 Fed. 2 SWD

Also, have you submitted a C-141?

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly J Tucker

Environmental Protection Specialist
O&G Spill/Release Coordinator

Bureau of Land Management
620 E. Greene St
Carlsbad, NM 88220

575.234.5905 - Direct
575.361.0084 - Cellular
575.234.6235 - Emergency Spill Number

stucker@blm.gov

The **BLM acceptance/approval does not** relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

On Wed, Nov 15, 2017 at 7:51 AM, <Wade_Dittrich@oxy.com> wrote:

Correction.

All,

This is to inform you that Oxy Permian had a **Reportable** release in **Eddy County** at the **Lost Tank 33 Federal 2 SWD** on **10/30/2017**.

- **Release Location:** Legal -33-21S-31E, API: 30-015-29330
- **Release Volume:** .5 bbls of Oil and 110 bbls of Produced Water.
- **Recovered:** TBD- bbls recovered
- **Cause of Release:** Tanks overflowed inside berm and onto pad and off location
- **Approximate Area impacted by release:** 150x150, 100x100(measurements are subject to change with GPS tracking)
- **GPS Coordinates and Driving Direction:** **32.428630 , -103.789610** OFF OF HWY 128 ON WHIPP RD GO NORTH TO GOVERNMENT FACILITY, GO 4-5 MILES. GO 1/4 MILE PAST MILE MARKER 4

TURN LEFT AT UP RIGHTS. AT CATTLEGUARD TURN RIGHT, AT 1ST BATTERY GO WEST, SWD IS 300 YDS PAST 4-1 BATTERY

Please let me know if you have any questions.

Wade Dittrich

Environmental Specialist

Oxy Permian-New Mexico

575-390-2828 cell

575-397-8214 office

Wade_Dittrich@Oxy.com

From: Dittrich, John W

Sent: Monday, October 30, 2017 3:10 PM

To: 'Bratcher, Mike, EMNRD' <mike.bratcher@state.nm.us>; 'Weaver, Crystal, EMNRD' <Crystal.Weaver@state.nm.us>

Cc: Ben J. Arguijo <ben@trinityoilfieldservices.com>; Duskie Bennett <duskie@trinityoilfieldservices.com>; 'stucker@blm.gov' <stucker@blm.gov>; Smith, Jennifer A <Jennifer_Smith@oxy.com>

Subject: Lost Tank 3 Fed. 2 SWD

All,

This is to inform you that Oxy Permian had a **Reportable** release in **Eddy County** at the **Lost Tank 33 Federal 2 SWD** on 10/30/2017.

- **Release Location:** Legal -33-21S-31E, API: 30-015-29330
- **Release Volume:** 0 bbls of Oil and 75 bbls of Produced Water.
- **Recovered:** TBD- bbls recovered
- **Cause of Release:** Tanks overflowed inside berm
- **Approximate Area impacted by release:** 150x150 (measurements are subject to change with GPS tracking)
- **GPS Coordinates and Driving Direction:** **32.428630 , -103.789610** OFF OF HWY 128 ON WHIPP RD GO NORTH TO GOVERNMENT FACILITY, GO 4-5 MILES. GO 1/4 MILE PAST MILE MARKER 4 TURN LEFT AT UP RIGHTS. AT CATTLEGUARD TURN RIGHT, AT 1ST BATTERY GO WEST, SWD IS 300 YDS PAST 4-1 BATTERY

Please let me know if you have any questions.

Wade Dittrich

Environmental Specialist

Oxy Permian-New Mexico

575-390-2828 cell

575-397-8214 office

Wade_Dittrich@Oxy.com