

**From:** [Weaver, Crystal, EMNRD](#)  
**To:** ["Blaney, Karolina"; Bratcher, Mike, EMNRD; "Tucker, Shelly"](#)  
**Cc:** [Raley, Jim](#)  
**Subject:** RE: Site Characterization - North Brushy Draw 35-6  
**Date:** Thursday, April 5, 2018 3:42:00 PM  
**Attachments:** [image001.png](#)

---

RE: WPX/RKI \* North Brushy Draw Federal 35-6H \* 30-015-42293 \* 2RP-4634

Karolina,

I just wanted to get a little clarification on this one. So in the characterization plan it states that the areas sampled were ones that you all saw "clearly visible impact", is all that other area on your map just misting? Did something get done on the misted areas to relieve the vegetation?

Please advise.

Otherwise this site characterization plan is approved.

Thank you,

## Crystal Weaver

Environmental Specialist  
OCD – Artesia District II  
811 S. 1<sup>st</sup> Street  
Artesia, NM 88210  
Office: 575-748-1283 ext. 101  
Cell: 575-840-5963  
Fax: 575-748-9720

---

**From:** Blaney, Karolina <Karolina.Blaney@wpxenergy.com>  
**Sent:** Thursday, April 5, 2018 8:01 AM  
**To:** Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; 'Tucker, Shelly' <stucker@blm.gov>  
**Cc:** Raley, Jim <James.Raley@wpxenergy.com>  
**Subject:** Site Characterization - North Brushy Draw 35-6

Good morning,  
Attached is the characterization plan with the correct map. I apologize for this mistake.  
Thank you,

*Karolina Blaney*

Environmental Specialist  
WPX Energy  
Office: (575) 885-7514  
Cell: (970) 589-0743  
[karolina.blaney@wpxenergy.com](mailto:karolina.blaney@wpxenergy.com)

---

**From:** Blaney, Karolina  
**Sent:** Wednesday, April 04, 2018 4:03 PM  
**To:** Weaver, Crystal, EMNRD <[Crystal.Weaver@state.nm.us](mailto:Crystal.Weaver@state.nm.us)>; Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>; Tucker, Shelly <[stucker@blm.gov](mailto:stucker@blm.gov)>  
**Cc:** Raley, Jim <[james.raleigh@wpxenergy.com](mailto:james.raleigh@wpxenergy.com)>  
**Subject:** Site Characterization - North Brushy Draw 35-6

Good afternoon,  
Attached is the site characterization/remediation plan for the North Brushy 35-6 site. Please let me know if you have any questions, concerns or suggestions.  
Thank you,

*Karolina Blaney*  
Environmental Specialist  
WPX Energy  
Office: (575) 885-7514  
Cell: (970) 589-0743  
[karolina.blaney@wpxenergy.com](mailto:karolina.blaney@wpxenergy.com)

---

**From:** Weaver, Crystal, EMNRD [<mailto:Crystal.Weaver@state.nm.us>]  
**Sent:** Monday, April 02, 2018 4:23 PM  
**To:** Raley, Jim <[james.raleigh@wpxenergy.com](mailto:james.raleigh@wpxenergy.com)>; Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>  
**Cc:** Tucker, Shelly <[stucker@blm.gov](mailto:stucker@blm.gov)>; Blaney, Karolina <[Karolina.Blaney@wpxenergy.com](mailto:Karolina.Blaney@wpxenergy.com)>  
**Subject:** RE: [EXTERNAL] RE: Initial Notification - North Brushy Draw 35-6

WPX/RKI \* North Brushy Draw Federal 35-6H \* 30-015-42293 \* 2RP-4634

Jim,

I have included a scanned copy of the signed Initial C-141 Remediation Permit along with an attached Conditions of Approval (COA). The OCD tracking number for this event is 2RP-4634, please refer to this tracking number on any and all submissions sent in to the OCD. Please remit a site characterization plan (see COA document included in attachment) or advise OCD of plan of action immediately since this one has a due date of 3/22/18 and that has passed.

Thank you,

**Crystal Weaver**

Environmental Specialist  
OCD – Artesia District II  
811 S. 1<sup>st</sup> Street  
Artesia, NM 88210  
Office: 575-748-1283 ext. 101  
Cell: 575-840-5963  
Fax: 575-748-9720

---

**From:** Raley, Jim [<mailto:James.Raley@wpxenergy.com>]  
**Sent:** Thursday, February 22, 2018 8:16 AM  
**To:** Weaver, Crystal, EMNRD <[Crystal.Weaver@state.nm.us](mailto:Crystal.Weaver@state.nm.us)>; Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>  
**Cc:** Tucker, Shelly <[stucker@blm.gov](mailto:stucker@blm.gov)>; Blaney, Karolina <[Karolina.Blaney@wpxenergy.com](mailto:Karolina.Blaney@wpxenergy.com)>  
**Subject:** RE: [EXTERNAL] RE: Initial Notification - North Brushy Draw 35-6

Please find attached C-141.

**Jim Raley** | Environmental Specialist - Permian Basin  
5315 Buena Vista Dr., Carlsbad, NM 88220  
C: (575)689-7597 | [james.ralej@wpxenergy.com](mailto:james.ralej@wpxenergy.com)



---

**From:** Weaver, Crystal, EMNRD [<mailto:Crystal.Weaver@state.nm.us>]  
**Sent:** Thursday, February 08, 2018 3:12 PM  
**To:** Raley, Jim <[James.Raley@wpxenergy.com](mailto:James.Raley@wpxenergy.com)>; Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>  
**Cc:** Tucker, Shelly <[stucker@blm.gov](mailto:stucker@blm.gov)>  
**Subject:** [EXTERNAL] RE: Initial Notification - North Brushy Draw 35-6

---

CAUTION: This email was sent from an EXTERNAL source. Use caution when clicking links or opening attachments.

---

Jim,

Thank you for the notification. If surfactant wont do you a whole lot of good then OCD is agreeable with your proactive immediate response, however, please note approval of your request would defer primarily to BLM since this release has impacted federal surface. Therefore, OCD defers to and concurs with whatever recommendation BLM provides to you all for immediate response on this incident.

Thank you,

## Crystal Weaver

Environmental Specialist  
OCD – Artesia District II  
811 S. 1<sup>st</sup> Street  
Artesia, NM 88210  
Office: 575-748-1283 ext. 101  
Cell: 575-840-5963  
Fax: 575-748-9720

---

**From:** Raley, Jim [<mailto:James.Raley@wpxenergy.com>]

**Sent:** Thursday, February 8, 2018 9:15 AM

**To:** Weaver, Crystal, EMNRD <[Crystal.Weaver@state.nm.us](mailto:Crystal.Weaver@state.nm.us)>; Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>

**Cc:** Tucker, Shelly <[stucker@blm.gov](mailto:stucker@blm.gov)>

**Subject:** Initial Notification - North Brushy Draw 35-6

This email is in regards to voicemail left with Crystal Weaver on 2/7/2018 at 5:16 P.M. giving verbal notification of an unauthorized release at the North Brushy 35-6H well pad.

API 30-015-42292, Lat 32.0929574, Long -103.953377

This incident occurred approx. 4 A.M. during the morning of 2/7/2017. A seal on the heater treater fire tube failed and allowed approx. 25 bbls of fluids to be released to the pad surface and land off-location. The impacts to the land off location are misting on to brush and soil. Approx. 10 bbls was able to be recovered.

WPX would like permission to remove the heavily impacted brush and remove 6" of soil from approx. 1 acre of BLM off location land.

A C-141 will be delivered within 15 days. Please let me know if you have any additional questions.

**Jim Raley** | Environmental Specialist - Permian Basin  
5315 Buena Vista Dr., Carlsbad, NM 88220  
C: (575)689-7597 | [james.raley@wpxenergy.com](mailto:james.raley@wpxenergy.com)

