From: Dittrich, John W

To: <u>Bratcher, Mike, EMNRD</u>; <u>Pruett, Maria, EMNRD</u>

Cc: Shelly Tucker; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; Kathy Purvis; Jennifer Gilkey;

Moore, Rebecca A

**Subject**: Federal 10 1 Battery

Date: Thursday, August 9, 2018 3:04:59 PM

## All,

This is to inform you that Oxy Permian had a **Reportable** release in **Eddy County** at the **Federal 10 1 Battery** on 8/8/2018.

• Release Location: Legal -10-24S-31E, API: 30-015-26649

• Release Volume: 0 bbls of Oil and 200 bbls of Produced Water.

• **Recovered**: 0 bbl recovered

• Cause of Release: 3 inch poly water line failure

• **Approximate Area impacted by release**: 30ft x 900ft (measurements are subject to change with GPS tracking)

• **GPS Coordinates and Driving Direction: 32.321852**,-**104.080415-Leak GPS** is 150ft Northeast of **Federal 10 3** well. At the Int. of 31 and Nymeyer Rd., go West on 31 for .1, turn right(N) thru cattle guard and go .5,

• turn right and go .3 to the Federal 10 3 well. Leak is 150ft Northeast of the well in the pasture.

Please let me know if you have any questions.

## Wade Dittrich

Environmental Specialist

Oxy Permian-New Mexico

575-390-2828 cell 575-397-8214 office

Wade Dittrich@Oxy.com