

**From:** [Cordero, Gilbert, EMNRD](#)  
**To:** [jamos@blm.gov](mailto:jamos@blm.gov)  
**Cc:** [Bratcher, Mike, EMNRD](#); [Pruett, Maria, EMNRD](#); [Smolik, Danny, EMNRD](#)  
**Subject:** FW: discharge  
**Date:** Wednesday, September 12, 2018 2:48:34 PM

---

Jim,

We found some problems on the Hudson Puckett lease. The Puckett A 004, 30-015-05379 was found yesterday and they had it covered up today. I also found a flow line leak today on the Puckett A 026, 30-015-10302 and on that one they had sand on top but the leak was starting to flow again. They also have a lot of contaminated material on the edge of some of the locations. There is a pipeline leak north of the Puckett B 019, 30-015-05409 and I contacted Oscar with DCP (575-973-8631) and was informed that it had been turned in to be fixed.

Thank you,

Gilbert Cordero  
Staff Manager  
NMOCD District II  
Office 575.748.1283 ext.114  
Cell 575.626.0830

-----Original Message-----

From: Smolik, Danny, EMNRD  
Sent: Tuesday, September 11, 2018 1:20 PM  
To: Pruet, Maria, EMNRD <Maria.Pruett@state.nm.us>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>  
Cc: Cordero, Gilbert, EMNRD <Gilbert.Cordero@state.nm.us>  
Subject: FW: discharge

We found this today. I think it's something you need.

-----Original Message-----

From: Smolik, Danny, EMNRD  
Sent: Tuesday, September 11, 2018 1:13 PM  
To: Smolik, Danny, EMNRD <Danny.Smolik@state.nm.us>  
Subject: