

**From:** [Cliff Brunson](#)  
**To:** [Pruett, Maria, EMNRD](#); ["Ryan Mann"](#)  
**Cc:** ["Wade Dittrich"](#); ["Becky Moore"](#); ["Ken Swinney"](#); ["Jennifer Gilkey"](#); ["Kathy Purvis"](#); [Bratcher, Mike, EMNRD](#)  
**Subject:** RE: Conditional Approval RE: [EXT] OXY Turkey Track CTB (2RP-4949) - Delineation Workplan  
**Date:** Thursday, November 22, 2018 6:19:24 PM

---

Maria,

I do have some comments and we disagree with the conditions that you presented. The following are our responses to the conditions:

1. The location is not in a medium karst area according to the Google Earth map provided to us by the BLM. It is in a low karst area and therefore is in an area per Table 1 DTW>100'. Therefore, there is no requirement to excavate to 5' at SP7.
2. GPS photos of the spill are not required per Rule 19.15.29. until closure is submitted. This is also per Jim Griswold in the public meeting in Carlsbad, NM.
3. There is no requirement for all off pad areas to be excavated to 4 feet if the contaminants are in the <50 DTW ranges. If the chloride content is less than 600 ppm in shallower than 4' then there is no requirement to excavate clean soil in order to backfill with clean soil. At this site, everything off pad is well below 600 ppm at 1' foot. Also, Table 1 clearly states the limits are either the Table 1 limits or natural background level whichever is greater. This site meets this criterion. In addition, on more than one conference call Jim Griswold has stated these facts as well.
4. The remediation plan as presented meets this condition.

I believe if you will review this plan as presented, you will agree with my responses. Oxy looks forward to hearing back from you.

Thanks, Cliff

Cliff P. Brunson, CEI, CRS  
President  
BBC International, Inc.  
World-Wide Environmental Specialists  
Mailing Address:  
P. O. Box 805  
Hobbs, NM 88241-0805 USA  
Shipping Address:  
1324 W. Marland St.  
Hobbs, NM 88240 USA  
Phone: (575) 397-6388  
Fax: (575) 397-0397  
E-Mail: [cbrunson@bbcinternational.com](mailto:cbrunson@bbcinternational.com)



\*\*\*\*\*

Confidentiality Notice: This electronic transmission (and any attached documents) is intended only for the person(s) to whom it is addressed and may contain information that is privileged, confidential, or otherwise protected from disclosure. If you have received this transmission in error, please immediately notify the sender by e-mail or by telephone call to (575) 397-6388 for handling instructions.

Any disclosure or distribution of the contents of this transmission by anyone other than the named recipient(s) is strictly prohibited.

\*\*\*\*\*

---

**From:** Pruett, Maria, EMNRD <Maria.Pruett@state.nm.us>

**Sent:** Wednesday, November 21, 2018 2:24 PM

**To:** Cliff Brunson <cbrunson@bbcinternational.com>; Ryan Mann <rmann@slo.state.nm.us>

**Cc:** 'Wade Dittrich' <Wade\_Dittrich@oxy.com>; 'Becky Moore' <rebecca\_moore@oxy.com>; 'Ken Swinney' <kswinney@bbcinternational.com>; 'Jennifer Gilkey' <jgilkey@bbcinternational.com>; 'Kathy Purvis' <kathy@bbcinternational.com>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>

**Subject:** Conditional Approval RE: [EXT] OXY Turkey Track CTB (2RP-4949) - Delineation Workplan

Hello Mr. Brunson,

OCD has received the remediation plan for 2RP-4949, thank you! This plan is conditional approved with the following:

1. Location is in medium karst area, therefore remediation is to Table 1 DTW < 50'. Area around SP7 excavated to 5'.
2. GPS photos of spill required so OCD may determine which areas are on/off pad.
3. All off pad areas to contain a minimum 4' "uncontaminated", "non-waste containing" material. This may require additional sidewall samples and further delineation.
4. Restoration, reclamation and re-vegetation to 19.15.29.13 NMAC.

Please let me know if you have any questions.

Best Regards,

*Maria Pruett*

Environmental Specialist  
N.M. Oil Conservation Division  
District 2  
811 S. 1<sup>st</sup> Street  
Artesia, NM 88210  
Desk: 575 748-1283 X 101  
Cell: 575 840-5963  
Fax: 575 748-9720

*OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.*

---

**From:** Cliff Brunson <[cbrunson@bbcinternational.com](mailto:cbrunson@bbcinternational.com)>  
**Sent:** Monday, November 5, 2018 9:53 AM  
**To:** Pruett, Maria, EMNRD <[Maria.Pruett@state.nm.us](mailto:Maria.Pruett@state.nm.us)>; Ryan Mann <[rmann@slo.state.nm.us](mailto:rmann@slo.state.nm.us)>  
**Cc:** 'Wade Dittrich' <[Wade\\_Dittrich@oxy.com](mailto:Wade_Dittrich@oxy.com)>; 'Becky Moore' <[rebecca\\_moore@oxy.com](mailto:rebecca_moore@oxy.com)>; 'Ken Swinney' <[kswinney@bbcinternational.com](mailto:kswinney@bbcinternational.com)>; 'Jennifer Gilkey' <[jgilkey@bbcinternational.com](mailto:jgilkey@bbcinternational.com)>; 'Kathy Purvis' <[kathy@bbcinternational.com](mailto:kathy@bbcinternational.com)>; Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>  
**Subject:** [EXT] OXY Turkey Track CTB (2RP-4949) - Delineation Workplan

Maria and Ryan,

Please find the attached Delineation Workplan and remediation proposal for the Oxy Turkey Track CTB (2RP-4949). Oxy is requesting that you review this plan and is looking forward to the OCD's and SLO's approval.

If you have any questions, please let me know.

Thanks, Cliff

Cliff P. Brunson, CEI, CRS  
President  
BBC International, Inc.  
World-Wide Environmental Specialists  
Mailing Address:  
P. O. Box 805  
Hobbs, NM 88241-0805 USA  
Shipping Address:  
1324 W. Marland St.  
Hobbs, NM 88240 USA  
Phone: (575) 397-6388  
Fax: (575) 397-0397  
E-Mail: [cbrunson@bbcinternational.com](mailto:cbrunson@bbcinternational.com)



\*\*\*\*\*

Confidentiality Notice: This electronic transmission (and any attached documents) is intended only for the person(s) to whom it is addressed and may contain information that is privileged, confidential, or otherwise protected from disclosure. If you have received this transmission in error, please immediately notify the sender by e-mail or by telephone call to (575) 397-6388 for handling instructions. Any disclosure or distribution of the contents of this transmission by anyone other than the named recipient(s) is strictly prohibited.

\*\*\*\*\*