## **Bratcher, Mike, EMNRD**

From: Rebecca Haskell < RHaskell@concho.com>

Sent: Friday, January 4, 2019 9:22 AM

**To:** Bratcher, Mike, EMNRD; DeAnn Grant; Mann, Ryan

Cc: Ike Tavarez; Robert McNeill; Sheldon Hitchcock; Dakota Neel; Hamlet, Robert, EMNRD; Venegas,

Victoria, EMNRD

**Subject:** [EXT] RE: (C-141 Initial) Myox 8 State #004H 12-22-2018

Mr. Bratcher,

The Myox 8 State #4H Tank Battery is on the same pad as the SRO State Com #43, please use the API # for the Myox 8 State #4H. Let me know if you have any additional questions or concerns.

## Thank You,

Becky Haskell
Senior HSE Coordinator
COG Operating LLC
600 W Illinois Avenue | Midland, TX 79701

Direct: 432-818-2372 | Main: 432.683.7443

Cell: 432-556-5130 rhaskell@concho.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

From: Bratcher, Mike, EMNRD [mailto:mike.bratcher@state.nm.us]

Sent: Friday, January 04, 2019 10:11 AM

To: DeAnn Grant <agrant@concho.com>; Mann, Ryan <rmann@slo.state.nm.us>

Cc: Ike Tavarez <itavarez@concho.com>; Robert McNeill <RMcNeill@concho.com>; Sheldon Hitchcock <SLHitchcock@concho.com>; Dakota Neel <DNeel2@concho.com>; Rebecca Haskell <RHaskell@concho.com>; Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>; Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us>

Subject: [External] RE: (C-141 Initial) Myox 8 State #004H 12-22-2018

\*\*\*\* External email. Use caution. \*\*\*\*
DeAnn,

I noticed there was not an API number listed on this C-141. Running the lat/long, it appears the release was on the SRO St Com 43H (30-015-41141), but evidently from a flowline originating at the Myox 8 St 4H (30-015-41924) as listed on the form. The Myox is approximately 1500 yds to the north of the SRO. Do you want us to use one of these API numbers to enter this spill report under?

Thanks,

Mike Bratcher NMOCD District 2 811 South First Street Artesia, NM 88210 575~748~1283 Ext 108

From: DeAnn Grant <agrant@concho.com>
Sent: Friday, January 4, 2019 8:33 AM

**To:** Bratcher, Mike, EMNRD <<u>mike.bratcher@state.nm.us</u>>; Mann, Ryan <<u>rmann@slo.state.nm.us</u>> **Cc:** Ike Tavarez <<u>itavarez@concho.com</u>>; Robert McNeill <<u>RMcNeill@concho.com</u>>; Sheldon Hitchcock

<<u>SLHitchcock@concho.com</u>>; Dakota Neel <<u>DNeel2@concho.com</u>>; Rebecca Haskell <<u>RHaskell@concho.com</u>>; DeAnn

Grant <agrant@concho.com>

Subject: [EXT] (C-141 Initial) Myox 8 State #004H 12-22-2018

Mr. Bratcher/Mr. Mann,

Please find the attached C-141 for your consideration. Also, attached is the calculation sheet to determine the estimated release volume. The liquid lost estimate is based on the spill dimensions, estimated depth of fluid (wet soil depth) and type of formation. The spreadsheet will calculate the volume lost in the ground and does not include the recovered amount in the calculation. The calculated volume in the ground and the volume recovered were added together and reported on the C-141. If you have any questions or concerns please do not hesitate to contact me.

Thank you,

## DeAnn Grant

HSE Administrative Assistant
agrant@concho.com
COG Operating LLC#
600 W Illinois Avenue | Midland, TX 79701
Direct: 432-253-4513 | Main: 432.683.7443