Submit 3 Copies To Appropriate District Office	State of New Mexico			Form C-103 Revised May 08, 2003		
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources			WELL API NO.		
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION			30-015-23942		
District III	1220 South St. Francis Dr.			5. Indicate Type of Lease STATE X FEE		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505			6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505	DHC-3042			LG-1637		
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name or Unit Agreement Name		Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH						
PROPOSALS.)	ALS.)			NEW MEXICO DC STATE  8. Well Number		
1. Type of Well:	RECEIVED			8. Well Number		
Oil Well X Gas Well	MAR 1 0 7004			1		
2. Name of Operator MARBOB ENERGY CORPORA	TTON			9. OGRID Number 14049		
3. Address of Operator OCD-ARTESIA				10. Pool name or Wildcat		
PO BOX 227, ARTESIA, NM 88211-0227			PALMILLO; UPPER PENN &			
4. Well Location				PALMILLO;	WOLFCAMP, WE	ST
Unit Letter H :	1980 feet from the	NORT	H line and	660 feet fro	om the EAST	line
Section 18	Township 19		inge 29E	NMPM	County EDD	Y
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3379' KB						
12. Check A	ppropriate Box to Inc		ature of Notice.	Report or Other	· Data	
NOTICE OF INT				SEQUENT RE		
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK		ALTERING CASIN	<b>√</b> IG □
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRII	LLING OPNS.	PLUG AND	
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AN	ID 🗆	ABANDONMENT	
OTHER.		П	OTHER, DOTH	DHC-3042	T THE	<b>67</b> 1
OTHER:  13. Describe proposed or complete	ated operations (Clearly	_		HOLE COMMING		Tod data
of starting any proposed wor						
or recompletion.		•	•		• •	•
DOLDHOL II. GOLGAT						
DOWNHOLE COMMI	NGLE AS FOLLOWS:					
2/18/04 - RETRIEVE RBP.						
2/20/04 - ACIDIZE PERFS @ 9558' - 9962' WITH 3000 GAL 15% NEFE ACID						
WITH 1000 GAL XYLENE MIXED WITH IT. ACIDIZE PERFS @ 9178' - 9291' WITH 1500 GAL 15% NEFE ACID WITH 500 GAL						
XYLENE MIXED WITH IT.						
2/24/04 - LEFT WELL PUMPING TO BATTERY.						
DOWNHOLE COMMINGLING @ 8941' - 9962'.						
SEE ADMINISTRATIVE ORDER DHC-3042.						
SEE .	ADPOINTSTRATIVE OF	KIJEK IJ	NG-3042.			
I hereby certify that the information a	ove is true and complete	to the be	est of my knowledge	and belief.		
SIGNATURE / IA AA	$\frac{1}{1}$ $\frac{1}$	uri e	PRODUCTION AN	ΔΙ.ΥςΤ	_DATE3/9/0	<b>L</b>
SIGNATURE CONTROL OF THE SIGNATURE		IILE	110000110W AN	21.71 O 1	_DATE	<del>-</del>
	J. CANNON			Teleph	none No. (505)	748–3303
(This space for State use)						
APPPROVED BY		ITLE			DATE MAR 1	6 2004
Conditions of approval, if any:	- FOR RECT	ords	ONLY		_DATE	