Submit 3 Copies To Appropriate Di	strict	State of 1	Form C-103						
Office District I		Energy, Minerals and Natural Resources			Revised March 25, 1999				
1625 N. French Dr., Hobbs, NM 88	240					WELL API NO.			
District II 811 South First, Artesia, NM 88210	M 88210 OIL CONSERVATION DIVISION					30-005-20339			
District III		1220 South St. Francis Dr.				5. Indicate Type of Lease  STATE FEE   STATE			
1000 Rio Brazos Rd., Aztec, NM 87 District IV	Santa Fe, NM 87505								
1220 S. St. Francis Dr., Santa Fe, N 87505	M				6. State C	ni & Gas	Lease No.		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A						7. Lease Name or Unit Agreement Name:			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)						Double L Queen Unit			
1. Type of Well: Oil Well Gas Well X Other RECEIVED								Ì	
2. Name of Operator APR 1 4 7004						8. Well No.			
Tipton Oil & Gas Acquisitions, Inc.				ADTEQIA	004Q				
3. Address of Operator			OCD-ARTESIA		9. Pool name or Wildcat				
P.O. Box 1234, Lovington, NM 88260					Double L Queen; Assoc.				
4. Well Location					***************************************		william manight manight manight		
Unit Letter F	_:23	feet from the	North	line and	2265 f	eet from th	ne <u>West</u>	line	
Section	6	Township 15S	Ran	ge 30E	NMPM	Chaves,	Cour	nty	
		10. Elevation (Show w	vhether DI	R, RKB, RT, GR, et	c.)				
多型基础的基础的						<b>第4</b> 4	10.8 4		
11. Ch	eck A	ppropriate Box to Inc	dicate Na	ature of Notice,	Report or (	Other Da	ta		
		TENTION TO:			SEQUEN				
PERFORM REMEDIAL WO	RK 🗀	PLUG AND ABANDON		REMEDIAL WOF	RK	□ A	LTERING CA	SING 🗆	
TEMPORARILY ABANDON		CHANGE PLANS		COMMENCE DR	ILLING OPN		LUG AND	,,	
PULL OR ALTER CASING		MULTIPLE COMPLETION		CASING TEST A	.ND		BANDONME	NI	
OTHER: CONVERT INJ	ECTOR	TO PRODUCER	$\mathbf{x}$	OTHER:					
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date									
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.									
•									
Release tbg. from permanent packer. POOH with tbg. GIH with work string and bailer. Knock packer to bottom of hole.									
POOH with work string and bailer. Run new rods, pump, and tbg. Set pumping unit and commence production.									
				4	Accepted for	record - 1	NMOCD		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.									
SIGNATURE Della	Mg	Kelin agent TITLE	Agent, Fo	r Ryan Tipton (Pre	esident), Princ	ipal	_DATE_	110/04	
Type or print name	Ryan Ti								
(This space for State use)			300			<del></del>			
APPPROVED BY			TITLE			1	DATE		
Conditions of approval, if an	 ıy:		_11126		<del></del>		~		