Submit 3 Copies To Appropriate District	State of New Mexico			Form C-103	
Office District I	Energy, Minerals and Natural Resources		March 4, 2004		
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	-231/24	
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type	-33408	
District III	1220 South St. Francis Dr.		5. maicaie Type STATE	☐ FEE ☒	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa He NIMI X / 303		6. State Oil & G		
1220 S. St. Francis Dr., Santa Fe, NM				o. butto on to c	
87505 SUNDRY NOTICES AND REPORTS ON WELLS				7 Lease Name	or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Romulus Fee		
PROPOSALS.)	•			8. Well Number	
1. Type of Well: Oil Well ☐ Gas Well ☒ C	<b>Y</b> ther	F	RECEIVED	1	
2. Name of Operator	7HICE			9. OGRID Num	her
Nadel and Gussman Permian. LLC			JUN 2 1 2004	155614	
3. Address of Operator		90	D-ARTESIA	10. Pool name o	r Wildcat
601 N. Marienfeld, Suite 508 Midland	d, TX 79701			<b>Loving Morrow</b>	(North) (80695)
4. Well Location					
Unit LetterD :660feet from theWest line and840 feet from theNorthline					
Section 17	Township 2	3-8	Range 28-E	NMPM	County Eddy
	11. Elevation (Show who				County Lady
	3032'	214,	, , , , , , , , , , , , , , , , , , , ,		
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)					
Pit Location: UL_D_Sect_17_Twp_23S_Rng_28E_Pit type_Drilling Pit_Depth to Groundwater_50'-100'_Distance from nearest fresh water well >200"					
Distance from nearest surface water>1000' Below-grade Tank Location UL Sect Twp Rng ;					
feet from the line and feet from the line					
		-			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INT				SEQUENT RE	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	L	REMEDIAL WOR	<	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRI	LLING OPNS.	PLUG AND  ABANDONMENT
	MULTIPLE COMPLETION		CASING TEST AN CEMENT JOB	ID 🛛	
OTHER:			OTHER:		
13. Describe proposed or completed operat		ent details,	l and give pertinent dates,		<del>-</del>
	pletions: Attach wellbore diag	ent details,	l and give pertinent dates,		<del>-</del>
13. Describe proposed or completed operations SEE RULE 1103. For Multiple Completed 96/16/04 - Ran 230 joints 7" SP-110 26# 8rd LT	pletions: Attach wellbore diag &C' set @ 10,349'.	ent details, gram of pro	l and give pertinent dates, posed completion or reco	empletion.	te of starting any proposed work).
13. Describe proposed or completed operating SEE RULE 1103. For Multiple Computed 16/16/04 - Ran 230 joints 7" SP-110 26# 8rd LTG 16/17/04 - Cement 1st stage w/ 300sx 35/65 poz/1.2%D46 + .4%D13 Plug DN 7:00pm. Drop Bom	pletions: Attach wellbore diag &C' set @ 10,349'. H + 6% D20 + .2% D64 + 5% nb open DV tool & circ. Light	ent details, gram of pro D44(BWO cement to s	and give pertinent dates, posed completion or reco	mpletion. 1908x PVL +1.75% D1 1908x PVL +1.75% D2/1	te of starting any proposed work).  44 (BWOW).3%D167 + .2%D65 + H + 6%D20 + .2%D46 + 5%D44
13. Describe proposed or completed operating SEE RULE 1103. For Multiple Completed 06/16/04 - Ran 230 joints 7" SP-110 26# 8rd LTG 06/17/04 - Cement 1st stage w/ 300sx 35/65 poz/1.2%D46 + .4%D13 Plug DN 7:00pm. Drop Borr (BWOW) 510sx PVL + 1#sx D44 + .31 D167 +	pletions: Attach wellbore diag &C' set @ 10,349'. H + 6% D20 + .2% D64 + 5% nb open DV tool & circ. Light .2%D65 + .21D46 + .15/D13.	pent details, gram of pro D44(BWO cement to s	and give pertinent dates, posed completion or reconstruction of the posed completion of the posed comp	mpletion. 1908x PVL +1.75% D1 1908x PVL +1.75% D2/1	te of starting any proposed work).  44 (BWOW).3%D167 + .2%D65 + H + 6%D20 + .2%D46 + 5%D44
13. Describe proposed or completed operating SEE RULE 1103. For Multiple Computed 16/16/04 - Ran 230 joints 7" SP-110 26# 8rd LTG 16/17/04 - Cement 1st stage w/ 300sx 35/65 poz/1.2%D46 + .4%D13 Plug DN 7:00pm. Drop Bom	pletions: Attach wellbore diag &C' set @ 10,349'. H + 6% D20 + .2% D64 + 5% nb open DV tool & circ. Light .2%D65 + .21D46 + .15/D13.	pent details, gram of pro D44(BWO cement to s	and give pertinent dates, posed completion or reconstruction of the posed completion of the posed comp	mpletion. 1908x PVL +1.75% D1 1908x PVL +1.75% D2/1	te of starting any proposed work).  44 (BWOW).3%D167 + .2%D65 + H + 6%D20 + .2%D46 + 5%D44
13. Describe proposed or completed operating SEE RULE 1103. For Multiple Completed 06/16/04 - Ran 230 joints 7" SP-110 26# 8rd LTG 06/17/04 - Cement 1st stage w/ 300sx 35/65 poz/1.2%D46 + .4%D13 Plug DN 7:00pm. Drop Borr (BWOW) 510sx PVL + 1#sx D44 + .31 D167 +	pletions: Attach wellbore diag &C' set @ 10,349'. H + 6% D20 + .2% D64 + 5% nb open DV tool & circ. Light .2%D65 + .21D46 + .15/D13. 10 min and upper kelly valve 2	pent details, gram of pro D44(BWO cement to s	and give pertinent dates, posed completion or reconstruction of the posed completion of the posed comp	mpletion. 1908x PVL +1.75% D1 1908x PVL +1.75% D2/1	te of starting any proposed work).  44 (BWOW).3%D167 + .2%D65 + H + 6%D20 + .2%D46 + 5%D44
13. Describe proposed or completed operators SEE RULE 1103. For Multiple Computed 06/16/04 - Ran 230 joints 7" SP-110 26# 8rd LTd 06/17/04 - Cement 1st stage w/ 300sx 35/65 poz/1.2%D46 + .4%D13 Plug DN 7:00pm. Drop Bom (BWOW) 510sx PVL + 1#sx D44 + .31 D167 + min. Tested annular 250psi 10min and 5000psi 3 06/14/04 - Visited w/ Mr. Arrant about 7" setting I hereby certify that the information about 10/16/14/04 - Visited w/ Mr. Arrant about 10/16/1	pletions: Attach wellbore diag &C' set @ 10,349'.  H + 6% D20 + .2% D64 + 5% nb open DV tool & circ. Light .2%D65 + .21D46 + .15/D13. 00 min and upper kelly valve 2 g depth.	D44(BWO cement to: ND BOP: 50psi 10 m	and give pertinent dates, posed completion or recovery (1998) + .15%D13 Tail w/4 surface. Cement 2 <sup>nd</sup> stag set slips and cut off 7" ca in -5000psi 30 min.	empletion.  100sx PVL +1.75% D1  2 w/ 584sx 35/65 poz/I  sing. Tested choke ma	te of starting any proposed work).  44 (BWOW).3%D167 + .2%D65 + H + 6%D20 + .2%D46 + 5%D44 anifold 250psi 10 min. 5000psi 30
13. Describe proposed or completed operations SEE RULE 1103. For Multiple Computed 06/16/04 - Ran 230 joints 7" SP-110 26# 8rd LTd 06/17/04 - Cement 1st stage w/ 300sx 35/65 poz/2.2%D46 + .4%D13 Plug DN 7:00pm. Drop Bom (BWOW) 510sx PVL + 1#sx D44 + .31 D167 + min. Tested annular 250psi 10min and 5000psi 3 06/14/04 - Visited w/ Mr. Arrant about 7" setting I hereby certify that the information abgrade tank has been/will be constructed or clo	pletions: Attach wellbore diag &C' set @ 10,349'.  H + 6% D20 + .2% D64 + 5% mb open DV tool & circ. Light .2%D65 + .21D46 + .15/D13. 00 min and upper kelly valve 2 g depth.  Ove is true and complete used according to NMOCD g	D44(BWO cement to: ND BOP: 50psi 10 m	and give pertinent dates, posed completion or recovery (a) + .15%D13 Tail w/4 surface. Cement 2 <sup>nd</sup> stages set slips and cut off 7" cain -5000psi 30 min.	empletion.  900sx PVL +1.75% D1  e w/ 584sx 35/65 poz/l  sing. Tested choke ma  c and belief. I further an (attached) alter	te of starting any proposed work).  44 (BWOW).3%D167 + .2%D65 + H + 6%D20 + .2%D46 + 5%D44 unifold 250psi 10 min. 5000psi 30  therefore certify that any pit or belownative OCD-approved plan
13. Describe proposed or completed operators SEE RULE 1103. For Multiple Computed 06/16/04 - Ran 230 joints 7" SP-110 26# 8rd LTd 06/17/04 - Cement 1st stage w/ 300sx 35/65 poz/1.2%D46 + .4%D13 Plug DN 7:00pm. Drop Bom (BWOW) 510sx PVL + 1#sx D44 + .31 D167 + min. Tested annular 250psi 10min and 5000psi 3 06/14/04 - Visited w/ Mr. Arrant about 7" setting I hereby certify that the information about 10/16/14/14/14 - Visited w/ Mr. Arrant about 7" setting I hereby certify that the information about 10/16/14/14/14 - Visited w/ Mr. Arrant about 7" setting I hereby certify that the information about 10/16/14/14/14/14/14/14/14/14/14/14/14/14/14/	pletions: Attach wellbore diag &C' set @ 10,349'.  H + 6% D20 + .2% D64 + 5% mb open DV tool & circ. Light .2%D65 + .21D46 + .15/D13. 00 min and upper kelly valve 2 g depth.  Ove is true and complete used according to NMOCD g	D44(BWO cement to: ND BOP: 50psi 10 m	and give pertinent dates, posed completion or recovery (1998) + .15%D13 Tail w/4 surface. Cement 2 <sup>nd</sup> stag set slips and cut off 7" ca in -5000psi 30 min.	empletion.  900sx PVL +1.75% D1  e w/ 584sx 35/65 poz/l  sing. Tested choke ma  c and belief. I further an (attached) alter	te of starting any proposed work).  44 (BWOW).3%D167 + .2%D65 + H + 6%D20 + .2%D46 + 5%D44 anifold 250psi 10 min. 5000psi 30
13. Describe proposed or completed operations SEE RULE 1103. For Multiple Computed 06/16/04 - Ran 230 joints 7" SP-110 26# 8rd LTd 06/17/04 - Cement 1st stage w/ 300sx 35/65 poz/2.2%D46 + .4%D13 Plug DN 7:00pm. Drop Bom (BWOW) 510sx PVL + 1#sx D44 + .31 D167 + min. Tested annular 250psi 10min and 5000psi 3 06/14/04 - Visited w/ Mr. Arrant about 7" setting I hereby certify that the information abgrade tank has been/will be constructed or clo	pletions: Attach wellbore diag &C' set @ 10,349'.  H + 6% D20 + .2% D64 + 5% nb open DV tool & circ. Light .2%D65 + .21D46 + .15/D13.  O min and upper kelly valve 2 g depth.  Ove is true and complete used according to NMOCD g	D44(BWO cement to s ND BOP s 50psi 10 m	and give pertinent dates, posed completion or recovery (a) + .15%D13 Tail w/4 surface. Cement 2 <sup>nd</sup> stages set slips and cut off 7" cain -5000psi 30 min.	empletion.  100sx PVL +1.75% D1  2 w/ 584sx 35/65 poz/l  2 sing. Tested choke ma  2 and belief. I furtion an (attached) alter	te of starting any proposed work).  44 (BWOW).3%D167 + .2%D65 + H + 6%D20 + .2%D46 + 5%D44 unifold 250psi 10 min. 5000psi 30  therefore certify that any pit or belownative OCD-approved plan

FOR RECORDS ONLTITLE

APPPROVED BY

Conditions of approval, if any:

\_DATE\_ JUN 2 7 2004