continued:

WLHU TRACT 1 #3 Sec 7-18S-30E 1980' FSL 660' FWL Eddy County, NM

on to 5.5" csg & establish circ; attempt to circ cement to surface w/ an additional 60 sx Class C cement w/ 2% CaCl2. 7. Spot 15 sk Class C cement plug @ surface.

- 8. Remove all surface equipment & weld dry hole marker per regulations.