Submit 3 Copies To Appropriate Dis Office	Sittle (of New Mexico	Form C-103
District I	35 ·	lls and Natural Resources	May 27, 2004 WELL API NO.
1625 N. French Dr., Hobbs, NM 882 District II		DALATION DIVIGIONI	30-015-10801
1301 W. Grand Ave., Artesia, NM 88 District III	0210	RVATION DIVISION	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Francis Dr. Santa Fe, NM 87505		STATE X FEE 6. State Oil & Gas Lease No.	
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM		1 6, 14141 67303	6. State Oil & Gas Lease No. E-9891
87505	NOTICES AND DEPORTS	ONWELLO	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "A PROPOSALS.)	APPLICATION FOR PERMIT" (F	ORM C-101) FOR SUCH	ATOKA STATE
1. Type of Well: Oil Well	X Gas Well Other	RECEIVED	8. Well Number #2
2. Name of Operator	*	OCT 0 7 2004	9. OGRID Number 015445
3. Address of Operator P.O. BOX 840			10. Pool name or Wildcat
AR	TESIA, NM 88211-0840		ATOKA-SAN ANDRES
4. Well Location	1650	golfri	1650 C. C. d. FAST II
Unit Letter J	: 1650 feet from t		1650 feet from the EAST line
Section 16	Township	18S Range 26E whether DR, RKB, RT, GR, etc.	NMPM EDDY CountyNM
	3362' GR	whether DR, RRD, R1, OR, etc	
Pit or Below-grade Tank Application	on or Closure		
Pit typeDepth to Gr	oundwaterDistance from	nearest fresh water well Di	stance from nearest surface water
Pit Liner Thickness:	mil Below-Grade Tank:	Volume bbls; (Construction Material
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE O	F INTENTION TO:	SU	SSEQUENT REPORT OF:
PERFORM REMEDIAL WOR			
TEMPORARILY ABANDON	☐ CHANGE PLANS		RILLING OPNS. P AND A
PULL OR ALTER CASING	☐ MULTIPLE COMPL	☐ CASING/CEMEN	NT JOB
OTHER:		☐ OTHER:	
			nd give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
or recompletion.			
*CEE ATTACHED DECCDU	DTION AND WELLBODE	DIACDAM	
*SEE ATTACHED DESCRIPTION AND WELLBORE DIAGRAM			
I homely contifue that the information		-1	11.11.6
grade tank has been/will be construction	tation above is true and comp cted or closed according to NMO	Diete to the best of my knowled CD guidelines [], a general permit [ge and belief. I further certify that any pit or below-] or an (attached) alternative OCD-approved plan [].
SIGNATURE Craig	Bailer	TITLEENGINEER	DATE 10/06/2004
			•
Type or print name CRAIG B For State Use Only	AILEY	E-mail address: chailey@pp	coinc.com Telephone No. (505)748-4280
TO State USE Only		A / / / /	// //3
		Juld	DOGT 2 9 2004

ATOKA STATE #2 30-015-10801 T18S, R26E, SEC. 16 UNIT J, 1650' FSL & 1650' FEL EDDY COUNTY, NM

13.

- 1) Notified Jerry Guy w/ NMOCD @ 3:30 p.m. on 9/20/04 of intention to begin plugging operations.
- 2) RU PU, Manual BOP, Rig Mat, Bit, Scrapper & TIW valve.
- 3) RU a steel pit instead of utilizing an earthen pit.
- 4) TOH w/ rods & pump.
- 5) ND Tree, NU BOP
- 6) TOH w/ 2-3/8" tbg. and lay down
- 7) TIH w/ 2-3/8" workstring and make bit and scrapper run to 1204'
- 8) TOH w/ 2-3/8" tbg. workstring, lay down tools and stand 1198' of tbg. in derrick.
- 9) TIH w/ 2-3/8" tbg. workstring and cement retainer and set retainer @ 1200'.
- 10) Test 2-3/8" tbg. to 850 psi.
- 11) Sting out of retainer & break circulation up backside.
- 12) Sting into retainer and establish injection rate
- 13) Squeeze 100 sxs Class C cement into OH.
- 14) Sting out of retainer and pump 100 sxs Class C cement down tbg. and out backside w/ returns to steel pit.
- 15) TOH w/ tbg. and lay down workstring.
- 16) ND BOP
- 17) Dry hole marker installed ready for inspection.
- *Due to heavy rains waiting on location to dry out, will notify NMOCD for inspection.

I

ATOKA STATE #2

MYCOINDUSTRIES, INC.

UNIT LETTER "J" SEC. 16-T185-R26E

EDDY CO., NEW MEXICO

1650'FEL: 1650'FSL

API#30-015-10801

SPUD: 6-29-66 (PENNSYLVANIAN

DRLG. CO.)

E-LOG TOPS:

PREMIER = 850'

S/A = 889'

ARTESIA = 1030'

"A" ZONE = 1436'
"C" ZONE = 1576'

TD = 2127'

CUM. PROD.

OIL = 21,137 BBLS.


GAS = 168,704 MCF

WATER = 44, 294 BBLS.

11-19-66 S/A 2000-2040 1000 GAL, 15% HCL

12-1-66 3 STAGE FRAC 4500 BBLS. GELLED WATER W/163,500 # 20/40 SAND

TESTED 12-16-66 56 BOPD-45BWPD



PLUG + ABANDON

9-22-04 - 100 sx:"C"NEAT FROM 1200-2127" - 100 sx."C"NEAT FROM 1200 - SURFACE (CIRC.)



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON
Governor

10.28.04 OK TO RELEASE Jo. Joanna Prukop
Cabinet Secretary
Acting Director
Oil Conservation Division

8 October 2004

RECEIVED

OCT 2 6 7004

Myco Industries P. O. Box 840

OOP:APTESIA

Artesia, New Mexico 88211-0840

Form C-103 Report of Plugging for your Atoka State # 2 J-16-18-26 API 30-015-10801 Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- 1. All pits have been filled and leveled.
- 2. Rat hole and cellar have been filled and leveled.
- 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- 5. The dead men and tie downs have been cut and removed.
- 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
- 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Vaig Bailey

Field Rep. II

Operations Engineer