

## NEW MEXICO ENERGY, MINERALS NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

Field Inspection Program

"Preserving the Integrity of Our Engleonment"

14-Dec-04

**RAY WESTALL** PO BOX 4 LOCO HILLS NM 88255

**NOTICE OF VIOLATION - Inspection** 

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

T 3 7 7 T	TOTTON	D 1700 4 FF	an amena
INNP	PR.C. I ICIN	DELAIL.	SECTION

**MYRTLE MYRA No.002** 

J-9-21S-27E

30-015-21146-00-00

Inspection

Date

Type Inspection

Inspector

Violation?

\*Significant Corrective Action Due By: Non-Compliance?

Inspection No.

12/13/2004

Routine/Periodic

Mike Bratcher

Yes

No

1/13/2005

iMLB0434837287

**Violations** 

Surface Leaks/Spills

Comments on Inspection:

Some contamination at wellhead area. Tank battery has some hydrocarbon and chloride saturated

areas. Remediation required. Violation Rule 13 and Rule 116

**MYRTLE MYRA No.001** 

C-16-21S-27E

30-015-26179-00-00

Inspection 12/13/2004

Date

Type Inspection Routine/Periodic Inspector Mike Bratcher Violation? Yes

\*Significant Non-Compliance? No

Corrective Action Due By: 1/13/2005

Inspection No.

iMLB0434836720

Violations

Surface Leaks/Spills

Comments on Inspection:

Area at wellhead is contaminated with oil and produced water. Stuffing box is leaking at time of

inspection. Delineation and remediation of chloride contamination required. Area along flowline just South and East of this well has been site of release from flowline. Line has been patched. Delineation and remediation of chloride contamination required. Both sites are in violation of Rule

13 and Rule 116. No well sign. Violation Rule 103.

**MYRTLE MYRA No.006** 

P-9-21S-27E

30-015-27073-00-00

Inspection

Date 12/13/2004

Type Inspection Routine/Periodic Inspector

Violation?

\*Significant Non-Compliance?

Corrective Action Due By:

Inspection No.

Mike Bratcher

Yes

1/13/2005 No

iMLB0434835648

Violations

Surface Leaks/Spills

Comments on Inspection:

Large area of contamination at wellhead area. Pile of contaminated soil stockpiled on location.

Remediation required. Violation Rule 13 and Rule 116.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely.

Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. \*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.