RECEIVED

Form 3160-5 (September 2001)

UNITED STATES DEPARTMENT OF THE INTERIOR

NOV 0 4 2004

FORM APPROVED OMB No. 1004-0135 Expires January 31, 2004

Do not use th	RY NOTICES AND REF his form for proposals ell. Use Form 3160-3 (A	5. Lease Serial No. NMLC029426B 6. If Indian, Allottee or Tribe Name				
SUBMIT IN TR	IPLICATE - Other ins	tructions on reverse	side	7. If Unit or Ca	A/Agreement, Name and/or No.	
1. Type of Well Oil Well Gas Well	Other			8. Well Name	and No.	
2. Name of Operator MARBOB ENERGY CORPORATION					OXY BUTTER PECAN FEDERAL # 9. API Well No.	
3a. Address 3b. Phone No. (include area code) PO BOX 227, ARTESIA, NM 88211-0227 (505) 748-3303					30-015-32316 10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec.	, T., R., M., or Survey Descript	ion)		FREN;	WOLFCAMP Parish, State	
660 FSL 890 FWL, SEC. 10-T17S-R31E, UNIT M					EDDY CO., NM	
12. CHECK AP	PROPRIATE BOX(ES)	TO INDICATE NATU	RE OF NOTICE, R	EPORT, OR O	THER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
☐ Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production (Star		Water Shut-Off Well Integrity	
Subsequent Report	☐ Casing Repair ☐ Change Plans	✓ New Construction✓ Plug and Abandon	Recomplete Temporarily Ab	oandon	Other	
Final Abandonment Notice	Convert to Injection	X Plug Back	Water Disposal			
 Describe Proposed or Complete If the proposal is to deepen dire Attach the Bond under which the 	ctionally or recomplete horizor	ntally, give subsurface location	ons and measured and tra	ue vertical depths of	and approximate duration thereof. of all pertinent markers and zones. ports shall be filed within 30 days	

following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

RECOMPLETED TO THE WOLFCAMP AS FOLLOWS:

SET CICR @ 10146'. SQZ PERFS @ 10180'-10281' W/ 220 SX CMT. DRILL OUT CICR @ 10146' & CMT THRU SQZD PERFS IN CISCO @ 10180'-10281'. PERF THE MORROW @ 11956'-11959' (24 SHOTS). ACIDIZE THE MORROW W/ 500 GAL CLAY SAFE H ACID. SET CIBP @ 11900'. PERF THE STRAWN @ 11169'-11187' (9 SHOTS). DUMP 35' CMT ON CIBP @ 11900'. ACIDIZE THE STRAWN W/ 1500 GAL 15% ACID. SET CIBP @ 11100'. PERF THE CISCO @ 9308'-9583' (15 SHOTS). DUMP 35' CMT ON CIBP @ 11100'. ACIDIZE THE CISCO W/ 3000 GAL 15% ACID. SET CIBP @ 9240'. PERF THE WOLFCAMP @ 8449'-8703' (20 SHOTS). DUMP 35' CMT ON CIBP @ 9240'. ACIDIZE THE WOLFCAMP W/ 5000 GAL NEFE 15% HCL ACID. FRAC THE WOLFCAMP @ 8449'-8566' W/ 128040 GAL FLUID & 100K LBS PROPPANT. AIR 40 BPM. AIP 4000#. TAG PBTD @ 9205'. HUNG WELL ON PUMP ON 10/27/04.

14. I hereby certify that the foregoing is to Name (Printed/Typed)	ue and correct							
DIANA & CANNON Title		tle PRO	PRODUCTION ANALYST					
Signature	anna D	ate NOV	EMBER 3, 2004					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved by		Title	Date					
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.								

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.