Oil Cons

N.M. DIV-Dist. 2

Form 3160-5 (June 1990)

Final Abandonment Notice

1301 W. Grand Avenue UNITED STATES DEPARTMENT OF THE INTERMISESIA, NM 88210 **BUREAU OF LAND MANAGEMENT**

FORM APPROVED						
	Bu	dget Bur	Mu No.	1004-0135		
		Expires:	March	31, 1993		
5.	Lease	Designat	on and	Serial No.	-	

NM 34467 6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals

Non-Routine Fracturing Water Shut-Off

Conversion to Injection

Dispose Water (Note: Report results of multiple con

SUBMI	7. If Unit or CA, Agreement Designation	
I. Type of Well Oil Gas Well Well Other	T IN TRIPLICATE	RNM-021
2. Name of Operator Fasken Oil and Ranch, Ltd.	/3° NO 2003	Indian Hills Com No. 1
3. Address and Telephone No. 303 W. Wall, Suite 1800, Midland, TX 7970	w -ccived	A 30-015-20195
4. Location of Well (Footage, Sec., T., R., M., or Survey I		
Unit J, 1650' FSL, 1750' FEL, Section 8, T21	IS, R24E	11. County or Parish, State Eddy, NM
12. CHECK APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOTICE,	
TYPE OF SUBMISSION	TYPE OF A	
Notice of Intent	Abandonment	Change of Plans
Subsequent Report	Recompletion Physician Reck	New Construction

epiction or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Fasken Oil and Ranch, Ltd. proposes to downhole commingle the subject well after the recompletion decribed in the attached procedure to the Undesignated Indian Basin Upper Penn (Associated), Indian Basin Strawn and Undesignated Seven Rivers Hills Atoka Pools. A Downhole Commingle application has been filed on Febraury 25, 2003 with the Santa Fe office of the New Mexico Oil Conservation Division.

Downhole Commingle

SUBJECT TO LIKE APPROVAL BY NMOCD

APPROVED FEB 2 7 2003 LES BABYAK PETROLEUM ENGINEER

4. I hereby certify that the foregoing is true still correct Signed Museum	Title Regulatory Affairs Coordinator	Date	2/25/2003
(This space for Pederal of State office use)			
Approved by	Title	Date	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

Workover Procedure Indian Hills Com No. 1 1650' FSL & 1750' FEL Sec 8, T21S, R24E A.F.E. 647

Objective: Recomplete to Atoka, Strawn, Canyon

KB: 16 above GL Completed 11-5-73

TD: 10,190

PBTD: CIBP @ 10,070' 1976, original 10,163'. Casing: 13-3/8" 48#/ft @ 314' cmt w/350 sx.

8-5/8" 24# & 32#/ft @ 3288'w/1290 sx lost pump, TOC 1900' by CBL, perf 2 shots @ 1850' could not pump in @ 2500psi, Ran Temp TOC 340', pump 68 sx

between 13-3/8" and 8-5/8".

4-1/2" 11.6#/ft J-55 and N-80 TD @ 10,190' with 450 sx, Calculated TOC 7600'. Perfs:

Orig. Sep 70 Morrow 9926-28', 9982-84', 9956-60', Add Morrow 8-16-71 9948-49',

9971'-78', 10016-17', 10033-42', 10080-81', 10101-106' total 120 holes.

4-1/2" Baker Model "R" (assumed re-ran same model 8-7-81 workover) at 9901.6' Pkr: with SN.

325 jts 2-3/8" 4.7#/ft EUE 8rd (assumed N-80) Tbg:

Last pulled August 1981

- 1. RUPU. Kill well with 35 bbls 3% KCL water containing packer fluid and ½ gpt BJ's ClayMaster 5C (or equivalent).
- 2. ND x-mas tree, install BOP (might need to cut bolts with welder's torch).
- 3. Release Baker Model "R" packer and POW w/2-3/8" 8rd EUE N-80 tubing, SN and packer.
- 4. RU wireline lubricator. RIW with 3.75" guage ring to 9900'. RIW with 4-1/2" CIBP and set at 9875". Spot 35' Class "H" cement on CIBP with dump bailer for PBTD of 9840'.
- 5. Fill casing with 3% KCL water containing packer fluid and ½ gpt BJ's ClayMaster 5C (or equiv.). Pressure test CIBP, casing and BOP to 1500 psi.
- 6. RIW w/ wireline entry guide, 4-1/2" Arrowset I 10k packer w/TOSSD w/1.781' "F" profile, 2-3/8" 4.7#/ft EUE 8rd N-80 tubing testing in hole to 8000 psi above slips. Set packer at
- 7. ND BOP, NU 2-3/8" 5000 psi wellhead landing tubing with packer in 12,000 lbs compression. Pressure test packer, casing and tree to 1500 psi.
- 8. Swab tubing fluid level to 8000'+/-.

9. RU wireline company and lubricator. Run GR-CCL log 9840' to 8600'. Perforate the following intervals with 1-11/16" strip gun by Welex Compensated Acoustic Velocity Log log dated 8-24-70:

8708'-8710' Canyon lime 1 jspf (3 holes) 8738'-8747' Canyon lime 1 jspf (10 holes) 8831'-8835' Strawn lime 1 jspf (5 holes) total 18 holes

10. If further stimulation required RU BJ Services. Install tree saver. Pressure tbg-csg annulus to 500 psi. Stimulate with 1500 gal 15% NEFE acid with 1000 scf/bbl nitrogen and dropping 36 ball sealers for diversion. Max pressure 8000 psi. BJ Additives are:

> 0.5 gal/M Clay Master-5C 2 gal/M FAW-18w, surfactant 2 gal/M NE-13, Non-emulsifier 1 gal/M CI-27, organic inhibitor 6 gal/M Ferrotrol-270L 2 gal/M Ferrotrol-271L Flush with 3% KCL water containing and NE-13 surfactant and 1000 scf/bbl nitrogen.

- 11. Flow and swab back load and acid water to pit until flare will burn.
- 12. Return well to sales and evaluate whether to add Strawn sand 9057-62', 9155-58' and Atoka sand zone 9468'-9474'.
- 13. RU wireline company and lubricator. Perforate with 1spf 1-11/16"strip gun at 9057-62' (6 h), 9155-58' (4 h), 9468'-9474' (7h) by Welex Compensated Acoustic Velocity Log log dated 8-24-70.
- 15. If stimulation required. RU BJ Services. RU tree saver. RU pump truck and trap 1500 psi on tubing casing annulus. Acidize perfs 8475'-9474' with 1500 gal mixture of 7-1/2% HCL +25% methanol with 1000 scf/bbl nitrogen dropping 40 7/8" 1.3 sg RCN ball sealers ahead of all acid then 25 RCNBS evenly spaced in the last 750 gallons. Max surface pressure 7500 psi.

Acid additives:

2 gpt CI-27, 1 gpt Ne-940 Non-emulsifier, 1 gpt Inflo-150 Surface Tension reducer, 6 gpt FE-270 Iron Control, 2 gpt FE-271 Iron Control activator, 0.5 gpt Clay Master-5C Clay Control. Replace 25% of the acid mix water with methanol. 1500 gallons of 7.5% HCL requires 1215 gals water and 285 gals 28 Baume HCL, so mix with 911 gals water, 285 gals raw acid, 304 gals methanol. Flush with 3% kcl water containing 0.5 gpt Clay Master-5C with 1000 scf/bbl nitrogen.

16. Swab and flow acid water to pit until fire will burn. Return to sales.

CWB 2-7-03 (IHC1 afe647 pro.doc)