

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
March 4, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-015-33557
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name DiMaggio
8. Well Number 11
9. OGRID Number 017891
10. Pool name or Wildcat Brushy Draw Delaware

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator  
Pogo Producing Company

3. Address of Operator  
P.O. Box 10340, Midland, TX 79702-7340

4. Well Location

Unit Letter H : 1980 feet from the North line and 760 feet from the East line

Section 16 Township 26S Range 29E NMPM Eddy County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
2930'

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)

Pit Location: UL      Sect      Twp      Rng      Pit type      Depth to Groundwater      Distance from nearest fresh water well     

Distance from nearest surface water      Below-grade Tank Location UL      Sect      Twp      Rng      ;  
     feet from the      line and      feet from the      line

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☒ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See Attached.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Cathy Wright TITLE Sr Eng Tech DATE 12/6/04  
Type or print name Cathy Wright E-mail address: wrightc@pogoproducing.com Telephone No. 432-685-8100

(This space for State use)

APPROVED BY [Signature] TITLE      DATE 12-18-04  
Conditions of approval, if any:

Pogo Producing Company  
DiMaggio #11  
H/16/26S/29E  
Eddy County, NM  
30-015-33557

Spud & Set Surface Csg - MIRU Capstar #9. Spud well @ 20:00 hrs 08/27/04. Drld 17-1/2" hole to 565'. TD reached @ 16:00 hrs 08/28/04. Ran 13 jts 13-3/8" 48# H-40 STC csg. Cmt'd w/ 460 sks Lite @ 12.4 ppg followed by 200 sks Cl "C" + 2% CaCl2 @ 14.8 ppg. Circ 135 sks to surface. Plug down @ 00:00 hrs 08/29/04. WOC 18 hrs. Make cut-off. Install WH. NU BOP's & test ok.

Intermediate Csg - Drld 11" hole to 2845'. TD reached @ 03:30 hrs 09/05/04. Ran 65 jts 8-5/8" 32# J-55 STC csg. Cmt'd w/ 950 sks Lite @ 12.4 ppg followed by 200 sks Cl "C" + 2% CaCl2 @ 14.8 ppg. Plug down @ 17:00 hrs 09/05/04. Circ 120 sks to surface. WOC 18 hrs. Make cut-off. Install WH. NU BOP's & test ok.

TD & Prod Csg - Drld 7-7/8" hole to 6405'. KOP @ 4400'. TD reached @ 06:00 hrs 09/24/04. Ran 146 jts 5-1/2" 17# J-55 BTC & N-80 LT&C csg. Cmt'd w/ 800 sks Cl "C" + additives @ 14.9 ppg. Ran CBL 10/14/04. TOC @ 2860'.