Submit 3 Copies To Appropriate District State of New Mexico Form C-103 Office May 27, 2004 Energy, Minerals and Natural Resources District I WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 District II 30-015-23512 OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease District III 1220 South St. Francis Dr. STATE 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH Glass Kincaid OS PROPOSALS.) 8. Well Number 1. Type of Well: Oil Well Gas Well RECEIVED 2. Name of Operator 9. OGRID Number JAN 27 2005 Yates Petroleum Corporation 025575 3. Address of Operator OCD-AHTESIA 10. Pool name or Wildcat 105 S. 4<sup>th</sup> Street, Artesia, NM 88210 Penasco Draw-SA-Yeso Assoc. 4. Well Location Unit Letter 330 feet from the North line and 330 feet from the West line 7 Section Township 19S Range **NMPM** Eddv County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3644'GR Pit or Below-grade Tank Application or Closure Pit type Steel Depth to Groundwater NA Distance from nearest fresh water well NA Distance from nearest surface water NA Pit Liner Thickness: Below-Grade Tank: Volume bbls; Construction Material 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON **REMEDIAL WORK** ALTERING CASING □ TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDON □ PULL OR ALTER CASING MULTIPLE COMPL П CASING/CEMENT JOB П OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Yates Petroleum Corporation plans to plug and abandon this well as follows: 1. Rig up all H2S safety equipment. TOH with 2-3/8" tubing. No casing recovery attempt will be made. 2. Set 4-1/2" CIBP at 2246' and cap with 35' cement. 3. Spot an 11 sx Class "C" with 2% CaCl2 plug from 853' to 1003', across the intermediate casing shoe. WOC 3 hrs and tag plug. Reset if necessary. 4. Spot an 11 sx Class "C" with 2% CaCl2 plug from 250' to 400', across the surface casing shoe. WOC 3 hrs and tag plug. Reset if ' necessary. 5. Spot an 11 sx Class "C" with 2% CaCl2 plug from 0' to 150'. WOC 24 hrs and tag plug. 6. Remove all surface equipment and weld dry hole marker per regulations. NOTE: Yates Petroleum Corporation will use steel pits and no earth pits I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan .

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan .

SIGNATURE

TITLE Regulatory Compliance Supervisor

DATE January 26, 2005

Type or print name

Tina Huerta

E-mail address: tinah@ypcnm.com

Telephone No. 505-748-1471

For State Use Only

APPROVED BY:

Conditions of Approval (if any):



