

Submit 3 Copies To Appropriate District Office
District I
 1623 N. French Dr., Hobbs, NM 88240
District II
 1301 W. Grand Ave., Artesia, NM 88210
District III
 1000 Rio Brazos Rd., Aztec, NM 87410
District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103

May 27, 2004

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO.

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

OG-6027

7. Lease Name or Unit Agreement Name

New Mexico CW State Com

8. Well Number

1

9. OGRID Number

155615

10. Pool name or Wildcat

Burton Flat; Morrow (Pro Gas)

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

Nadel and Gussman Permian LLC

3. Address of Operator

601 N. Marienfeld Suite 508, Midland Texas, 79701

4. Well Location

Unit Letter _____ feet from the East line and 1580 feet from the South line
 Section 16 Township 21S Range 27E NMPM Eddy County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3277 GI.

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐PLUG AND ABANDON ☒TEMPORARILY ABANDON ☐CHANGE PLANS ☐PULL OR ALTER CASING ☐MULTIPLE COMPL ☐OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐P AND A ☐CASING/CEMENT JOB ☐OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Circ hole w/10 ppg salt gel mud

2. Cap cdp @ 8390 w/ 35' cml

3. Free point and pull 7" csg

4. Spot a 100' plug 50' in and out across csg stub and tag

5. Spot a 100' plug across intermediate shoe from 2850 to 2950 - TAG

6. Spot @100' plug from 2800 to 2900' across the base of the salt. - TAG

7. Spot a 100' plug across the surf shoe from 550 to 650' - TAG

8. Spot a 60" surf plug 60'

9. Erect PA marker.

If earthen pits are used in association with this work a pit permit is required prior to construction.

No pits will be dug a steel workover pit will be utilized.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCID guidelines ☐, a general permit ☐ or an (attached) alternative Of D approved plan ☐.

SIGNATURE Kem McCready TITLE Operational Manager DATE 1/23/06

Type or print name K. E. McCready

E-mail address: kemm@naguss.com

Telephone No. 432-682-4429

For State Use Only

APPROVED BY: Phil Hawkins TITLE Field Insp. DATE 1/4/06

Conditions of Approval (if any):

Notify OCD 24 hrs. prior to any work done.

NADEL AND GUSSMAN PERMIAN

New Mexico CW State Com #1
 1580' FSL, 660' FEL Sec 16, 21S, 27E, Eddy County, NM
 API # 30 - 015 - 22923-00

Elev: 3277, KB: NA'

