

Submit 3 Copies To Appropriate District
Office
District I

1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 87003
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103

June 19, 2008

HOBBS OGD
CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

MAY 26 2011

WELL API NO.

30-015-21777

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

Nash Unit

8. Well Number

004 SWD

9. OGRID Number

005380

10. Pool name or Wildcat

SWD;DELAWARE

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☐ Other SWD

2. Name of Operator

XTO Energy, Inc.

3. Address of Operator

200 N. Loraine, Ste. 800 Midland, TX 79701

4. Well Location

Unit Letter A : 990 feet from the North line and 330 feet from the West line

Section 13 Township 23S Range 29E NMPM County Eddy

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: Re-set packer ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. MIRU FU. ND WH. NU BOP. Release packer. POOH w/99 jts 2 7/8" IPC tbg. and packer.

2. RIH w/5-1/2" x 2-3/8" packer.

3. Set packer at 3152'. ND BOP. NU WH.

4. Press TCA to 350 psig for 30 min on chart recorder. RWIT.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Sherry Pack TITLE Regulatory Analyst DATE 5/25/2011

Type or print name Sherry Pack E-mail address: sherry_pack@xtoenergy.com PHONE 432.620.6709

For State Use Only


APPROVED BY Reynold (Nue) TITLE Compliance Officer DATE 7/21/11

Conditions of Approval (if any):

XTO ENERGY


Well: Nash Unit #4 SWD
Area: Carlsbad
Location: Section 13, T23S, R29E
County: Eddy
Elevation: 3002 GL 3014 KB

WI: 87.674140%
NRI:
Spud: 5/9/76
State: New Mexico



PREPARED BY: Richard Lauderdale

DATE: 4/24/08



RECEIVED
MAY 24 1971
MAIL

✓ 5/20/11

XTO ENERGY
unit LTR 4 SEC 13-7235-R29C
950 FNL 4 330 FNL
EOD 1 county, WA
API # 30-015-21732
Foster Energy Supply
Use Air/a
Jesse Beery 5/20/11
HALL/AM/24