

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-35121

Release Notification and Corrective Action

NMLB 1122240834

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company BOPCO, L.P.	260737	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 432-556-8730
Facility Name: Remuda Basin 25 State #1		Facility Type E&P
Surface Owner State of N.M.	Mineral Owner State	Lease No E5894

LOCATION OF RELEASE

Unit Letter I	Section 25	Township 23S	Range 29E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude N 32.288041 Longitude W 103.936333

NATURE OF RELEASE

Type of Release: Produced water and condensate	Volume of Release: 95 bbls of produced water and less than 1 bbl condensate.	Volume Recovered: None
Source of Release: 300 bbl produced water tank	Date and Hour of Occurrence 6/4/11, between 5 pm and 11 pm	Date and Hour of Discovery 6/5/11 9:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Tony Savoie	Date and Hour 6/5/11 7:30 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

JUN 16 2011

Describe Cause of Problem and Remedial Action Taken.* The 300 bbl water tank was struck by lightning the evening of 6/4/11, the pumper discovered it the next morning, all of the water had soaked into the ground inside the earthen containment. There was no evidence of fire anywhere at the facility. The well was shut in the morning of 6/5/11.

Describe Area Affected and Cleanup Action Taken.* Approximately 2100 sq. ft. inside the containment area and approximately 300 sq. ft. outside the containment area on the caliche well pad. Samples were collected a 2 ft. intervals to a depth of 12 ft. below ground surface on 6/8/11 and analyzed for TPH and Chlorides. It appears the vertical extent did not exceed 3 ft. below ground surface. A copy of the analytical results are attached. We plan on excavating the affected soil inside the containment area on 6/20/11. The soil remediation will follow the NMOCD recommended guidelines for the remediation of leaks and spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Tony Savoie	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by District Supervisor Mike Bratcher	
Title: Waste Mgmt. & Remediation Specialist	Approval Date: AUG 10 2011	Expiration Date:
E-mail Address: TASavoie@BassPet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/17/11	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 9/10/2011	

* Attach Additional Sheets If Necessary

2RP-821