Submit 1 Copy To Appropriate District State of New Mex	xico Forr	n C-10
Office District I Energy, Minerals and Natur		er 13, 200
1625 N French Dr , Hobbs, NM 88240	WELL API NO.	
District II OIL CONCEDIA TION	DIVISION 30-015-21189	
1301 W. Grand Ave, Artesia, NM 88210 District III 1220 South St. France	1.5 Indicate Type of Lease	
1000 Pro Prozos P.d. Aztec NIM 87410	STATE FEE V	<u> </u>
District IV Santa Fe, NM 87.	6. State Oil & Gas Lease No.	
1220 S St Francis Dr, Santa Fe, NM 87505		
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreemen	t Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU		
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FO PROPOSALS)	8. Well Number	
1. Type of Well: Oil Well Gas Well Other P&A	2	
2. Name of Operator	9. OGRID Number	
Yates Petroleum Corporation	025575	
3. Address of Operator	10. Pool name or Wildcat	
105 South Fourth Street, Artesia, NM 88210	Eagle Creek; San Andres	
4. Well Location		1.
Unit Letter L : 2310 feet from the South	line and330 feet from theWest	_ line
Section 13 Township 17S Ran		
11. Elevation (Show whether DR,		
3465'0	ÚK L	新草丸
10 01 1 4	CNI (CNI)	
12. Check Appropriate Box to Indicate Na	ature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK ALTERING CA:	SING F
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS P AND A	U110 E
PULL OR ALTER CASING MULTIPLE COMPL	CASING/CEMENT JOB	
DOWNHOLE COMMINGLE	ONOINO/OEMENT 30B	
BOWNITOLE COMMINIOLE		
OTHER:		
	OTHER:	
13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion.	ertinent details, and give pertinent dates, including esti	
 Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion. 	ertinent details, and give pertinent dates, including esti	
 Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion. MIRU. Unseated pump. NU BOP. 	ertinent details, and give pertinent dates, including esti . For Multiple Completions: Attach wellbore diagram	of
 Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion. MIRU. Unseated pump. NU BOP. S/2/11 – Set a 4-1/2" CIBP at 1310'. Spotted 130 sx Class "C" cement for the starting of the	ertinent details, and give pertinent dates, including esti . For Multiple Completions: Attach wellbore diagram from 1310' up to surface. Topped off well with cement	of
 13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion. 13. MIRU. Unseated pump. NU BOP. 14. Set a 4-1/2" CIBP at 1310'. Spotted 130 sx Class "C" cement for starting out cellar and cut off wellhead. Installed dry hole marker. 	ertinent details, and give pertinent dates, including esti . For Multiple Completions: Attach wellbore diagram from 1310' up to surface. Topped off well with cement	of
 13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion. 13. SEE RULE 19.15.7.14 NMAC proposed completion or recompletion. 14. MIRU. Unseated pump. NU BOP. 15. MIRU. Unseated pump. NU BOP. 16. MIRU. Set a 4-1/2" CIBP at 1310'. Spotted 130 sx Class "C" cement for significant systems. 16. MIRU. Unseated pump. NU BOP. 17. MIRU. Unseated pump. NU BOP. 18. MIRU. Unseated pump. NU BOP. 18. MIRU. Unseated pump. NU BOP. 19. MIR	ertinent details, and give pertinent dates, including esti . For Multiple Completions: Attach wellbore diagram from 1310' up to surface. Topped off well with cement	of
 13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion. 1/1/11 – MIRU. Unseated pump. NU BOP. 1/2/11 – Set a 4-1/2" CIBP at 1310'. Spotted 130 sx Class "C" cement for 1/9/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. 	ertinent details, and give pertinent dates, including esti . For Multiple Completions: Attach wellbore diagram from 1310' up to surface. Topped off well with cement	of
 13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion. 1/1/11 – MIRU. Unseated pump. NU BOP. 1/2/11 – Set a 4-1/2" CIBP at 1310'. Spotted 130 sx Class "C" cement for 1/9/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. 	ertinent details, and give pertinent dates, including esti . For Multiple Completions: Attach wellbore diagram from 1310' up to surface. Topped off well with cement	of
 13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion. 1/1/11 – MIRU. Unseated pump. NU BOP. 1/2/11 – Set a 4-1/2" CIBP at 1310'. Spotted 130 sx Class "C" cement for 1/9/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. 	ertinent details, and give pertinent dates, including esti . For Multiple Completions: Attach wellbore diagram from 1310' up to surface. Topped off well with cement Filled cellar and cut off anchors. Cleaned location.	. of VELL I
 13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion. /1/11 – MIRU. Unseated pump. NU BOP. /2/11 – Set a 4-1/2" CIBP at 1310'. Spotted 130 sx Class "C" cement ft/9/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. 	ertinent details, and give pertinent dates, including esti . For Multiple Completions: Attach wellbore diagram from 1310' up to surface. Topped off well with cement	. of VELL IS
 13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion. 1/1/11 – MIRU. Unseated pump. NU BOP. 1/2/11 – Set a 4-1/2" CIBP at 1310'. Spotted 130 sx Class "C" cement for 1/9/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. 	ertinent details, and give pertinent dates, including esti . For Multiple Completions: Attach wellbore diagram from 1310' up to surface. Topped off well with cement Filled cellar and cut off anchors. Cleaned location. RECEIVEL	. of VELL IS
 13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion. 1/1/11 – MIRU. Unseated pump. NU BOP. 1/2/11 – Set a 4-1/2" CIBP at 1310'. Spotted 130 sx Class "C" cement for 1/9/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. 	ertinent details, and give pertinent dates, including esti . For Multiple Completions: Attach wellbore diagram from 1310' up to surface. Topped off well with cement Filled cellar and cut off anchors. Cleaned location.	. of VELL IS
 13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion. /1/11 – MIRU. Unseated pump. NU BOP. /2/11 – Set a 4-1/2" CIBP at 1310'. Spotted 130 sx Class "C" cement ft/9/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. 	ertinent details, and give pertinent dates, including esti . For Multiple Completions: Attach wellbore diagram from 1310' up to surface. Topped off well with cement Filled cellar and cut off anchors. Cleaned location. We RECEIVE AUG 11 2011	of EVELL IS
 13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion. 1/1/11 – MIRU. Unseated pump. NU BOP. 1/2/11 – Set a 4-1/2" CIBP at 1310'. Spotted 130 sx Class "C" cement for 1/9/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. 	ertinent details, and give pertinent dates, including esti . For Multiple Completions: Attach wellbore diagram from 1310' up to surface. Topped off well with cement Filled cellar and cut off anchors. Cleaned location. RECEIVEL	of EVELL IS
 13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion. 13. MIRU. Unseated pump. NU BOP. 14. Set a 4-1/2" CIBP at 1310'. Spotted 130 sx Class "C" cement for starting out cellar and cut off wellhead. Installed dry hole marker. 	ertinent details, and give pertinent dates, including esti . For Multiple Completions: Attach wellbore diagram from 1310' up to surface. Topped off well with cement Filled cellar and cut off anchors. Cleaned location. We RECEIVE AUG 11 2011	of EVELL IS
 13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion. 13. Big 17.11 - MIRU. Unseated pump. NU BOP. 14.12 CIBP at 1310'. Spotted 130 sx Class "C" cement ft 13/9/11 - Dug out cellar and cut off wellhead. Installed dry hole marker. 14. Dug GED AND ABANDONED. 	rom 1310' up to surface. Topped off well with cement Filled cellar and cut off anchors. Cleaned location. RECEIVEL AUG 11 2011 NMOCD ARTES	of EVELL IS
 13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion. 13. MIRU. Unseated pump. NU BOP. 14. MIRU. Unseated pump. NU BOP. 15. MIRU. Set a 4-1/2" CIBP at 1310'. Spotted 130 sx Class "C" cement for significant starting of the starting of the	retinent details, and give pertinent dates, including esti . For Multiple Completions: Attach wellbore diagram from 1310' up to surface. Topped off well with cement Filled cellar and cut off anchors. Cleaned location. RECEIVE AUG 11 2011 NMOCD ARTES te:	of EVELL IS
 13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion. 13. MIRU. Unseated pump. NU BOP. 14. Set a 4-1/2" CIBP at 1310'. Spotted 130 sx Class "C" cement for significant stalled dry hole marker. 15. PLUGGED AND ABANDONED. 	rom 1310' up to surface. Topped off well with cement Filled cellar and cut off anchors. Cleaned location. RECEIVEL AUG 11 2011 NMOCD ARTES	of EVELL IS
13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion. 8/1/11 – MIRU. Unseated pump. NU BOP. 8/2/11 – Set a 4-1/2" CIBP at 1310'. Spotted 130 sx Class "C" cement ft	rom 1310' up to surface. Topped off well with cement Filled cellar and cut off anchors. Cleaned location. Well and the surface of the surface	of EVELL IS
13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion. 3/1/11 – MIRU. Unseated pump. NU BOP. 3/2/11 – Set a 4-1/2" CIBP at 1310'. Spotted 130 sx Class "C" cement ft//3/9/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. PLUGGED AND ABANDONED. Spud Date: Rig Release Date.	rom 1310' up to surface. Topped off well with cement Filled cellar and cut off anchors. Cleaned location. Well and the surface of the surface	of EVELL IS
13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion. 3/1/11 – MIRU. Unseated pump. NU BOP. 3/2/11 – Set a 4-1/2" CIBP at 1310'. Spotted 130 sx Class "C" cement ft/9/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. PLUGGED AND ABANDONED. Spud Date: Rig Release Date hereby certify that the information above is true and complete to the be	rom 1310' up to surface. Topped off well with cement Filled cellar and cut off anchors. Cleaned location. RECEIVEL AUG 11 2011 NMOCD ARTES st of my knowledge and belief.	D SIA
13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion. 15/1/11 – MIRU. Unseated pump. NU BOP. 15/2/11 – Set a 4-1/2" CIBP at 1310'. Spotted 130 sx Class "C" cement ft/9/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. 15/2/II – Set a 4-1/2" CIBP at 1310'. Rig Release Date of the beautiful description of the proposed complete to the beautiful description.	rom 1310' up to surface. Topped off well with cement Filled cellar and cut off anchors. Cleaned location. Well and the surface of the surface	D SIA
13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion. 8/1/11 – MIRU. Unseated pump. NU BOP. 8/2/11 – Set a 4-1/2" CIBP at 1310'. Spotted 130 sx Class "C" cement from the system of the system of the system. See a 4-1/2" CIBP at 1310'. Spotted 130 sx Class "C" cement from the system of the system of the system of the system. See a 4-1/2" CIBP at 1310'. Spotted 130 sx Class "C" cement from the system of the system. See a 4-1/2" CIBP at 1310'. Spotted 130 sx Class "C" cement from the system of	RECEIVEL AUG 11 2011 NMOCD ARTES st of my knowledge and belief. Bertinent dates, including estite.	VELL IS
13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion. 3/1/11 – MIRU. Unseated pump. NU BOP. 3/2/11 – Set a 4-1/2" CIBP at 1310'. Spotted 130 sx Class "C" cement ff 3/9/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. PLUGGED AND ABANDONED. Spud Date: Rig Release Date hereby certify that the information above is true and complete to the besides of the proposed for print name Tina Huerta E-mail address: ting the proposed for print name Tina Huerta E-mail address: ting the proposed for print name Tina Huerta E-mail address: ting the proposed for print name Tina Huerta E-mail address: ting the proposed for print name Tina Huerta E-mail address: ting the proposed for print name Tina Huerta E-mail address: ting the proposed for print name Tina Huerta E-mail address: ting the proposed for print name Tina Huerta E-mail address: ting the proposed for print name Tina Huerta E-mail address: ting the proposed for	RECEIVE AUG 11 2011 NMOCD ARTES Tet: Attach wellbore diagram Attach wellbore diagram RECEIVE AUG 11 2011 NMOCD ARTES Tet: August 10, Thomas and autory compliance Supervisor Thomas and autory and bure only. Thomas 575-748-4	VELL IS
13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion. 3/1/11 – MIRU. Unseated pump. NU BOP. 3/2/11 – Set a 4-1/2" CIBP at 1310'. Spotted 130 sx Class "C" cement ft. 3/9/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. PLUGGED AND ABANDONED. Rig Release Date hereby certify that the information above is true and complete to the besides of the proposed for the proposed	RECEIVEL AUG 11 2011 NMOCD ARTES te: August 10, August 10, August 10, August 10, August 20, August 10, August 20, A	VELL IS
13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion. 3/1/11 – MIRU. Unseated pump. NU BOP. 3/2/11 – Set a 4-1/2" CIBP at 1310'. Spotted 130 sx Class "C" cement ff s/9/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. PLUGGED AND ABANDONED. Rig Release Date hereby certify that the information above is true and complete to the best of the second o	RECEIVEL AUG 11 2011 NMOCD ARTES st of my knowledge and belief. Bertinent dates, including estite.	VELL IS