OCD-ARTESIA

Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-013
Expires: July 31, 201

5 Lease Serial No. NM 81953

SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreement, Name and/or No SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well 8. Well Name and No. Oil Well Other Gas Well Pure Gold 4 Federal 1 2 Name of Operator Devon Energy Production Company, L.P. 9. API Well No 30-015-26509 3b Phone No. (include area code) 3a Address 10. Field and Pool or Exploratory Area 20 N Broadway, Oklahoma City, OK 73102-8260 Delaware 405-235-3611 Location of Well (Footage, Sec., T.R. M., or Survey Description) FNL & 1980 FWL SEC 9 T23S R31E 11. Country or Parish, State Eddy County, NM 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Deepen Acidize Production (Start/Resume) Water Shut-Off Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Other Add Pay New Construction Casing Repair Recomplete ✓ Subsequent Report **Brushy Canyon** Plug and Abandon Change Plans Temporarily Abandon Convert to Injection Plug Back Water Disposal Final Abandonment Notice 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection) 6/20/11 - 7/8/11 1) MIRU. POOH w/ rods. ND WH. NU BOP. Rise pkr. CHC. 2) RIH & tag plug. Tag TOC on CIBP @ 13,403'. Set EOT @ 12,145'. Set cmt plug w/ 800 sx of Class H, Yld 1.18 cf/sx. Disp w/ 41 bbls wtr. Test 1100 psi. 3) RIH & tag plug @ 7843'. RIH w/ perf guns @ 4 spf: 4 total shots @ 4230'. RDMO WL. 4) RIH w/ cmt ret to 4199'. Pump 36 bbls thru & set @ 4199'. Pump 150 sx C, Yld 1.37 cf/sx. Displ w/ 23 bbls. 5) Tag cmt @ 4195'. DO Cmt. RIH to 5035'. MIRU JW WL and run CBL. TOC @ 3280'. 6) Set CIBP @ 5000'. Perf 4199-4220'. RDMO WL. RIH w/ pkr & set @ 4107'. 7) RU & RIH w/ swab & made 5 swab runs. Acidize w/ 500 g Xylene, 3500 g 7.5% HCL w/ 50 BS @ 5 bpm. RDMO. 8) RIH w/ swab. RD swab & unseat pkr. RIH w/ tbg. RECEIVED

9) RIH w/ pump. NU WH. TOP.

Accepted for record - NMOCD

DS 8-16-11

AUG NMOCD ARTESIA

Submit 3160-4 Completion	Recompletion	Report])
 I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Judy A. Barnett 	Title Regulatory Specialist	:	
Signature Jacky Co Sauce	Date 07/19/2011	ACCEPTED FOR RECOU	5 Û
THIS SPACE FOR FEDERAL OR STATE OFFICE USE			
Approved by	Title	Date JUL 2 3 2011	_
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Jans	
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for fictitious or fraudulent statements or representations as to any matter within its ju	or any person knowingly and willfully to mrisdiction.	make to any department or as new of the United States Africa CARLSBAD FIELD OFFICE	lse,
(Instructions on page 2)			