OCD-ARTESIA

Form 3160- 5 (August, 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BURGALLOE LAND MANAGEMENT

FORM APPROVED
OMB No 1004- 0137

BUREAU OF LAND MANAGEMENT Expires July 31, 2010 5 Lease Senal No. SUNDRY NOTICES AND REPORTS ON WELLS SHL. NM104684, BHL: NM67106 Do not use this form for proposals to drill or to re-enter an 6 If Indian, Allottee, or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. If Unit or CA Agreement Name and/or No SUBMIT IN TRIPLICATE - Other Instructions on page 2. Type of Well X Oil Well Gas Well Well Name and No Other Seabiscuit Federal Com #2H Name of Operator API Well No COG Operating LLC 3a Address Phone No (include area code) 30-015-37607 2208 W. Main Street 575-748-6946 Artesia, NM 88210 10 Field and Pool, or Exploratory Area Location of Well (Footage, Sec., T., R., M., or Survey Description) Cotton Draw; Bone Spring Lat. 11 County or Parish, State SHL: 330' FSL & 2260' FWL, Unit N (SESW) Sec 12-T24S-R31E Long. BHL: 363' FNL & 2226' FWL, Unit C (NENW) Sec 12-T24S-R31E Eddy NM 12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Acıdize Deepen Production (Start/Resume) Water Shut-off Altering Casing Fracture Treat Reclamation Well Integrity Casing Repair New Construction Recomplete Subsequent Report Other Completion Operations Change Plans Plug and abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug back Water Disposal 13 Describe Proposed or Completed Operation (clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths or pertinent markers and sands Attach the Bond under which the work will performed or provide the Bond No. on file with the BLM/ BIA Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection) 7/5/11 to 7/7/11 MIRU WSU. Tag & drill out 1st DVT @ 4500'. Test csg to 3000#. Test ok. Tag & drill out 2nd DVT @ 8492'. Circulate clean. Test csg to 3000#. Test ok. 7/8/11 to 7/19/11 Perforate Bone Spring 9100-13400'. Acdz w/38766 gal 15% acid. Frac w/4009557# sand & 3233212 gal fluid. 7/25/11 MIRU CTU & drill out all frac plugs. ACCEPTED FOR RECORD 7/26/11 Start flowing back & testing. RECEIVED AUG 1 5 2011 Accepted for record - NMOCD AUG 18 2011 BUREAU OF LAND MANAGEMENT NMOCD ARTESIA GARLSDAD FIELD OFFICE 14 I hereby certify that the foregoing is true and correct Name (Printed/ Typed) Stormi Davis Regulatory Analyst 8/2/11 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Date Conditions of approval, if any are attached Approval of this notice does not warrant or

which would entitle the applicant to conduct operations thereon

Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

certify that the applicant holds legal or equitable title to those rights in the subject lease Office