

**Poker Lake Unit 335H
30-015-39252
BOPCO, L.P.
December 19, 2011
Conditions of Approval**

- 1. BOP schematic is incomplete – valves and valve sizes are required. This will not be approved if submitted on a future APD.**
- 2. Submit sundry with manifold schematic showing routing to closed loop system. Also, include routing to mud/gas separator and routing out of mud/gas separator to flare and tanks. Schematic has wording “to mud/gas separator and/or pits”, but schematic is not complete enough to determine what will actually be onsite. This could result in a shutdown of operations if the BLM inspector cannot determine what operator is doing.**
- 3. Variance approved to use flex line with Serial #5212 from BOP to choke manifold. Check condition of 3” flexible line from BOP to choke manifold, replace if exterior is damaged or if line fails test. Line to be as straight as possible with no hard bends and is to be anchored according to Manufacturer’s requirements. Anchor requirements to be onsite for review. If the BLM inspector questions the straightness of the hose, a BLM engineer will be contacted and will review in the field or via picture supplied by inspector to determine if changes are required (operator shall expect delays if this occurs).**

WWI 121911