

Submit 1 Copy To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
October 13, 2009

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		WELL API NO. <b>30-015-27861</b>
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator <b>OXY USA WTP LP</b>		6. State Oil & Gas Lease No. <b>E-10169</b>
3. Address of Operator <b>P.O. Box 50250 Midland, TX 79710</b>		7. Lease Name or Unit Agreement Name <b>Stinking Draw</b>
4. Well Location Unit Letter <b>4</b> : <b>990</b> feet from the <b>north</b> line and <b>990</b> feet from the <b>west</b> line Section <b>36</b> Township <b>20N</b> Range <b>23E</b> NMPM County <b>Eddy</b>		8. Well Number <b>3</b>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) <b>3682' GR</b>		9. OGRID Number <b>192463</b>
		10. Pool name or Wildcat <b>Deeper Draw, S. Up. Perm (Assoc)</b>

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: **Casing Integrity** ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☒

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Stinking Draw #3 - 30-015-27861

TD-8000' PBTD-7912' Perfs-7436-7756'

OXY USA WTP LP respectfully requests to temporarily abandon this well. It is currently being evaluated for possible future recompletion with the coil tubing-acid simulation. The pilot project is to begin in 12/11 and depending on the success of this project, this well would be a future candidate.

1. POOH w/ prod equipment, RIH & set CIBP @ +/-7385'
2. Notify BLM/NMOCD of casing integrity test 24hrs in advance.
3. RU pump truck, circulate well with treated water, pressure test casing to 500# for 30 min.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *David Stewart* TITLE Regulatory Advisor DATE 11/22/11

Type or print name David Stewart E-mail address: david\_stewart@oxy.com PHONE: 432-685-5717

For State Use Only


APPROVED BY: *J. C. Shepard* TITLE Geologist DATE NOV 23 2011

Conditions of Approval (if any):

dm

OXY USA WTP LP  
Stinking Draw #3  
API No. 30-015-27861

14-3/4" hole @ 1228'  
9-5/8" csg. @ 1228'  
w/ 1400sx-TOC-Surf



CIBP @ +/- 7385'

8-3/4" hole @ 8000'  
7" csg @ 8000'  
DVT @ 6287'  
w/ 1095sx-TOC-Surf-Circ

Perfs @ 7436-7756'

PB-7912'

TD-8000'