Form 3160-5 (April 2004)	UNITED STATES DEPARTMENT OF THE INTERIOR	CD-ARTESIA		FORM APPROVED OM B No. 1004-0137
RECEIVED BURBAU OF LAND MANAGEMENT			Bxpires: March 31, 2007 5. Lease Serial No.	
SUNDRY NOTICES AND REPORTS ON WELLS				NM 45236
MAY 0 1,2 112 use the abandoned we NMOCD ARTESIA	nis form for proposals to drill or a ell. Use Form 3160 - 3 (APD) for su	to re-enter an uch proposals.	6. If Indian	, Allottee or Tribe Name
SUBMIT IN TRIPLICATE- Other instructions on reverse side.			7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well ☐ Gas Well ☐ Other				
			8. Well Nan	
2. Name of Operator OXY USA In	9. API W			
3a Address P.O. Box 50250 Midland, TX	o. (include area code)		- 39831	
P.O. Box 50250 Midland, TX 79710 432-685-5717 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			10. Field and Pool, or Exploratory Area Tugle Wells Bone Spring	
SL-360FSL STOFEL SESE(A) Sec. 33 Ta3S R3(E			11. County of	or Parish, State
PBH-330 FBL 550 FE	EC NENE(A) " "	(/	Eddy	NM
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA				
TYPE OF SUBMISSION	SION TYPE OF ACTION			
	Acidize Deepen	Production (Sta	art/Resume)	Water Shut-Off
Notice of Intent	Alter Casing Fracture Tr	, []	-•	Well Integrity Other Soul Set
Subsequent Report	Casing Repair Change Plans New Const	, L1	oandon	CSC & CUIT
Final Abandonment Notice	Convert to Injection Plug Back	Water Disposal		
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Pinal Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Spud 17-1/2" hole 4/7/12, drill to 633'. RIH & set 13-3/8" 48# H-40 STC csg @ 633', cmt w/ 360sx (112bbl) PPC w/ additives, followed by 300sx (72bbl) PPC w/ additives, circ 228sx (85bbl) cmt to surf. WOC. Test BOP's @ 250# low 5000# high. WOC per BLM requirements. 4/10/12, RIH & tag cmt @ 574', circ hole, pressure test csg to 1200# for 30min, tested good.				
4/11/12, drill 12-1/4" hole to 4316' 4/13/12. RIH & set 9-5/8" 40# J55 LTC csg @ 4306', cmt w/ 1195sx (398bbl) Light PPC w/ additives, followed by 300sx (71bbl) PPC w/ additives, circ 448sx (150bbl) cmt to surf. WOC. Test BOP's to 250# low, 5000#. WOC per BLM Potash requirements. 4/16/12 RIH & tag cmt @ 4189', circ hole, pressure test csg to 2750# for 30 min, tested good.				
14. I hereby certify that the fore Name (Printed/Typed)	going is true and correct			
David Stewart		Title Regulatory Advisor	1000	חדבת במת מבכמתת
Signature Ou S	Lil	Date 4/17(1	AUUL	
THIS SPÂCE FOR FEDERAL OR STATE OFFICE USE				
certify that the applicant holds legal which would entitle the applicant to		Office Office	BURA C	APR 2. 8 2012 Date AU OF LAND MANAGEMENT ARI SRAD FIELD OFFICE
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to-make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.				