Office	State of New Mexico	Form C-103
District 1	Energy, Minerals and Natural Resources	June 19, 2008
1625 N French Dr, Hobbs, NM 88240 District II		WELL API NO. 30-015-40078
1301 W Grand Ave , Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd , Aztec, NM 87410	1220 South St. Francis Dr.	STATE X FEE
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S St Francis Dr , Santa Fe, NM 87505		X0-0647-0408
	S AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS DIFFERENT RESERVOIR. USE "APPLICATION PROPOSALS")	TO DRILL OR TO DEEPEN OR PLUG BACK TO A ON FOR PERMIT" (FORM C-101) FOR SUCH	Washington 33 State
	Well ☐ Other:	8. Well Number ₀₅₄
Name of Operator Apache Corporation		9. OGRID Number 873
3. Address of Operator		10. Pool name or Wildcat
303 Veterans Airpark Lane, Suite 3000	Midland, TX 79705	Artesia; Glorieta-Yeso (O) (96830)
4. Well Location		
Unit Letter : 2310		990 feet from the East line
Section 33	Township 17S Range 28E	NMPM County Eddy
	. Elevation (Show whether DR, RKB, RT, GR,	etc.)
36	75' GR	
12. Check Appl	ropriate Box to Indicate Nature of Noti	ce, Report or Other Data
NOTICE OF INTE	NITION TO:	LIDOTOLIENT DEDODT OF.
NOTICE OF INTE PERFORM REMEDIAL WORK ☐ PI	NTION TO: S LUG AND ABANDON ☐ REMEDIAL W	UBSEQUENT REPORT OF: /ORK ☐ ALTERING CASING ☐
	-	DRILLING OPNS. P AND A
PULL OR ALTER CASING M	ULTIPLE COMPL	_
DOWNHOLE COMMINGLE		
OTHER.	OTHER: Com	pletion
13. Describe proposed or completed	l operations. (Clearly state all pertinent details	s, and give pertinent dates, including estimated date
13. Describe proposed or completed of starting any proposed work).	l operations. (Clearly state all pertinent details	
13. Describe proposed or completed	l operations. (Clearly state all pertinent details	s, and give pertinent dates, including estimated date
13. Describe proposed or completed of starting any proposed work).	operations. (Clearly state all pertinent details SEE RULE 1103. For Multiple Completions:	s, and give pertinent dates, including estimated date
 Describe proposed or completed of starting any proposed work). or recompletion. Apache completed this well as follows: 	operations. (Clearly state all pertinent details SEE RULE 1103. For Multiple Completions:	s, and give pertinent dates, including estimated date
 13. Describe proposed or completed of starting any proposed work). or recompletion. Apache completed this well as follows 5/31/12 MIRUSU. 6/01/12 Tag up on DV tool & DO @ 2 	d operations. (Clearly state all pertinent details SEE RULE 1103. For Multiple Completions: s: 2990'. Log TOC @ 70'. Perf Glorieta/Yeso @ 3	s, and give pertinent dates, including estimated date. Attach wellbore diagram of proposed completion 3618', 38', 53', 62', 79', 3701', 08', 19', 25', 38',
13. Describe proposed or completed of starting any proposed work). or recompletion. Apache completed this well as follows 5/31/12 MIRUSU. 6/01/12 Tag up on DV tool & DO @ 2 60', 75', 97', 3803', 20', 40', 60', 60', 75', 97', 3803', 20', 40', 60', 60', 75', 97', 3803', 20', 40', 60', 60', 75', 97', 3803', 20', 40', 60', 75', 97', 3803', 20', 40', 60', 60', 75', 97', 3803', 20', 40', 60', 75', 97', 3803', 20', 40', 60', 75', 97', 3803', 20', 40', 60', 75', 97', 3803', 20', 40', 60', 60', 75', 97', 3803', 20', 40', 60', 60', 75', 97', 3803', 20', 40', 60', 60', 75', 97', 3803', 20', 40', 60', 60', 75', 97', 3803', 20', 40', 60', 60', 75', 97', 3803', 20', 40', 60', 60', 75', 97', 3803', 20', 40', 60', 60', 75', 97', 98', 98', 98', 98', 98', 98', 98', 98	d operations. (Clearly state all pertinent details SEE RULE 1103. For Multiple Completions: s: 2990'. Log TOC @ 70'. Perf Glorieta/Yeso @ 36', 85', 3905', 39', 53', 64', 83', 93', 4009', 22', 4	s, and give pertinent dates, including estimated date: Attach wellbore diagram of proposed completion 3618', 38', 53', 62', 79', 3701', 08', 19', 25', 38', 43', 54', 65' w/ 1 SPF, 29 holes
13. Describe proposed or completed of starting any proposed work). or recompletion. Apache completed this well as follows 5/31/12 MIRUSU. 6/01/12 Tag up on DV tool & DO @ 2 60', 75', 97', 3803', 20', 40', 66/04/12 Spot 420 gals 15% Titrate ac	d operations. (Clearly state all pertinent details SEE RULE 1103. For Multiple Completions: s: 2990'. Log TOC @ 70'. Perf Glorieta/Yeso @ 36', 85', 3905', 39', 53', 64', 83', 93', 4009', 22', 40d. Acidize w/ 3293 gals 15% HCL NEFE acid	s, and give pertinent dates, including estimated date: Attach wellbore diagram of proposed completion 3618', 38', 53', 62', 79', 3701', 08', 19', 25', 38', 43', 54', 65' w/ 1 SPF, 29 holes
13. Describe proposed or completed of starting any proposed work). or recompletion. Apache completed this well as follows 5/31/12 MIRUSU. 6/01/12 Tag up on DV tool & DO @ 2 60', 75', 97', 3803', 20', 40', 6 6/04/12 Spot 420 gals 15% Titrate ac 6/05/12 LD tbg. ND BOP & NU frac 6/19/12 Frac 159,230 gals 20# & 180	d operations. (Clearly state all pertinent details SEE RULE 1103. For Multiple Completions: s: 2990'. Log TOC @ 70'. Perf Glorieta/Yeso @ 36', 85', 3905', 39', 53', 64', 83', 93', 4009', 22', 40d. Acidize w/ 3293 gals 15% HCL NEFE acid	s, and give pertinent dates, including estimated date: Attach wellbore diagram of proposed completion 3618', 38', 53', 62', 79', 3701', 08', 19', 25', 38', 43', 54', 65' w/ 1 SPF, 29 holes
13. Describe proposed or completed of starting any proposed work). or recompletion. Apache completed this well as follows 5/31/12 MIRUSU. 6/01/12 Tag up on DV tool & DO @ 2 60', 75', 97', 3803', 20', 40', 6 6/04/12 Spot 420 gals 15% Titrate ac 6/05/12 LD tbg. ND BOP & NU frac 6/19/12 Frac 159,230 gals 20# & 180 6/20/12 Rack pipe.	d operations. (Clearly state all pertinent details SEE RULE 1103. For Multiple Completions: SEE RULE 1103. For Multiple	s, and give pertinent dates, including estimated date: Attach wellbore diagram of proposed completion 3618', 38', 53', 62', 79', 3701', 08', 19', 25', 38', 43', 54', 65' w/ 1 SPF, 29 holes
13. Describe proposed or completed of starting any proposed work). or recompletion. Apache completed this well as follows 5/31/12 MIRUSU. 6/01/12 Tag up on DV tool & DO @ 2 60', 75', 97', 3803', 20', 40', 6 6/04/12 Spot 420 gals 15% Titrate ac 6/05/12 LD tbg. ND BOP & NU frac 6/19/12 Frac 159,230 gals 20# & 180	d operations. (Clearly state all pertinent details SEE RULE 1103. For Multiple Completions: SEE RULE 1103. For Multiple	s, and give pertinent dates, including estimated date. Attach wellbore diagram of proposed completion 3618', 38', 53', 62', 79', 3701', 08', 19', 25', 38', 43', 54', 65' w/ 1 SPF, 29 holes
13. Describe proposed or completed of starting any proposed work). or recompletion. Apache completed this well as follows 5/31/12 MIRUSU. 6/01/12 Tag up on DV tool & DO @ 2 60', 75', 97', 3803', 20', 40', 6 6/04/12 Spot 420 gals 15% Titrate ac 6/05/12 LD tbg. ND BOP & NU fract 6/19/12 Frac 159,230 gals 20# & 180 6/20/12 Rack pipe. 6/21/12 RIH w/ tbg & bailer. CO to P 6/22/12 RIH w/ prod equip SN @ 40 7/02/12 Set 640 pumping unit.	d operations. (Clearly state all pertinent details SEE RULE 1103. For Multiple Completions: SEE RULE 1103. For Multiple	s, and give pertinent dates, including estimated date: Attach wellbore diagram of proposed completion 3618', 38', 53', 62', 79', 3701', 08', 19', 25', 38', 43', 54', 65' w/ 1 SPF, 29 holes
13. Describe proposed or completed of starting any proposed work). or recompletion. Apache completed this well as follows 5/31/12 MIRUSU. 6/01/12 Tag up on DV tool & DO @ 2 60', 75', 97', 3803', 20', 40', 6 6/04/12 Spot 420 gals 15% Titrate ac 6/05/12 LD tbg. ND BOP & NU fract 6/19/12 Frac 159,230 gals 20# & 180 6/20/12 Rack pipe. 6/21/12 RIH w/ tbg & bailer. CO to P 6/22/12 RIH w/ prod equip SN @ 40	d operations. (Clearly state all pertinent details SEE RULE 1103. For Multiple Completions: SEE RULE 1103. For Multiple	s, and give pertinent dates, including estimated date. Attach wellbore diagram of proposed completion 3618', 38', 53', 62', 79', 3701', 08', 19', 25', 38', 43', 54', 65' w/ 1 SPF, 29 holes
13. Describe proposed or completed of starting any proposed work). or recompletion. Apache completed this well as follows 5/31/12 MIRUSU. 6/01/12 Tag up on DV tool & DO @ 2 60', 75', 97', 3803', 20', 40', 6 6/04/12 Spot 420 gals 15% Titrate ac 6/05/12 LD tbg. ND BOP & NU fract 6/19/12 Frac 159,230 gals 20# & 180 6/20/12 Rack pipe. 6/21/12 RIH w/ tbg & bailer. CO to P 6/22/12 RIH w/ prod equip SN @ 40 7/02/12 Set 640 pumping unit.	d operations. (Clearly state all pertinent details SEE RULE 1103. For Multiple Completions: SEE RULE 1103. For Multiple	RECEIVED AUG 0 8 2012
13. Describe proposed or completed of starting any proposed work). or recompletion. Apache completed this well as follows 5/31/12 MIRUSU. 6/01/12 Tag up on DV tool & DO @ 2 60', 75', 97', 3803', 20', 40', 6 6/04/12 Spot 420 gals 15% Titrate ac 6/05/12 LD tbg. ND BOP & NU frac 6/19/12 Frac 159,230 gals 20# & 180 6/20/12 Rack pipe. 6/21/12 RIH w/ tbg & bailer. CO to P 6/22/12 RIH w/ prod equip SN @ 40 7/02/12 Set 640 pumping unit. 7/05/12 Start prod to Washington Ba	d operations. (Clearly state all pertinent details SEE RULE 1103. For Multiple Completions: SEE RULE 1103. For Multiple	RECEIVED AUG 0 8 2012
13. Describe proposed or completed of starting any proposed work). or recompletion. Apache completed this well as follows 5/31/12 MIRUSU. 6/01/12 Tag up on DV tool & DO @ 2 60', 75', 97', 3803', 20', 40', 6 6/04/12 Spot 420 gals 15% Titrate ac 6/05/12 LD tbg. ND BOP & NU fract 6/19/12 Frac 159,230 gals 20# & 180 6/20/12 Rack pipe. 6/21/12 RIH w/ tbg & bailer. CO to P 6/22/12 RIH w/ prod equip SN @ 40 7/02/12 Set 640 pumping unit. 7/05/12 Start prod to Washington Ba	d operations. (Clearly state all pertinent details SEE RULE 1103. For Multiple Completions: SEE RULE 1103. For Multiple	RECEIVED AUG 0 8 2012 NMOCD ARTESIA
13. Describe proposed or completed of starting any proposed work). or recompletion. Apache completed this well as follows 5/31/12 MIRUSU. 6/01/12 Tag up on DV tool & DO @ 2 60', 75', 97', 3803', 20', 40', 6 6/04/12 Spot 420 gals 15% Titrate ac 6/05/12 LD tbg. ND BOP & NU fract 6/19/12 Frac 159,230 gals 20# & 180 6/20/12 Rack pipe. 6/21/12 RIH w/ tbg & bailer. CO to P 6/22/12 RIH w/ prod equip SN @ 40 7/02/12 Set 640 pumping unit. 7/05/12 Start prod to Washington Ba	d operations. (Clearly state all pertinent details SEE RULE 1103. For Multiple Completions: SEE RULE 1103. For Multiple	RECEIVED AUG 0 8 2012 NMOCD ARTESIA
13. Describe proposed or completed of starting any proposed work). or recompletion. Apache completed this well as follows 5/31/12 MIRUSU. 6/01/12 Tag up on DV tool & DO @ 2 60', 75', 97', 3803', 20', 40', 6 6/04/12 Spot 420 gals 15% Titrate ac 6/05/12 LD tbg. ND BOP & NU frac 6/19/12 Frac 159,230 gals 20# & 180 6/20/12 Rack pipe. 6/21/12 RIH w/ tbg & bailer. CO to P 6/22/12 RIH w/ prod equip SN @ 40 7/02/12 Set 640 pumping unit. 7/05/12 Start prod to Washington Ba Spud Date: 05/21/2012	d operations. (Clearly state all pertinent details SEE RULE 1103. For Multiple Completions: SEE RULE 1103. For Multiple Complete Action SEE RULE 1103. For Multiple Complete	RECEIVED AUG 0 8 2012 NMOCD ARTESIA
13. Describe proposed or completed of starting any proposed work). or recompletion. Apache completed this well as follows 5/31/12 MIRUSU. 6/01/12 Tag up on DV tool & DO @ 2 60', 75', 97', 3803', 20', 40', 6 6/04/12 Spot 420 gals 15% Titrate ac 6/05/12 LD tbg. ND BOP & NU fract 6/19/12 Frac 159,230 gals 20# & 180 6/20/12 Rack pipe. 6/21/12 RIH w/ tbg & bailer. CO to P 6/22/12 RIH w/ prod equip SN @ 40 7/02/12 Set 640 pumping unit. 7/05/12 Start prod to Washington Ba	d operations. (Clearly state all pertinent details SEE RULE 1103. For Multiple Completions: SEE RULE 1103. For Multiple	RECEIVED AUG 0 8 2012 NMOCD ARTESIA
13. Describe proposed or completed of starting any proposed work). or recompletion. Apache completed this well as follows 5/31/12 MIRUSU. 6/01/12 Tag up on DV tool & DO @ 2 60', 75', 97', 3803', 20', 40', 6 6/04/12 Spot 420 gals 15% Titrate ac 6/05/12 LD tbg. ND BOP & NU fract 6/19/12 Frac 159,230 gals 20# & 180 6/20/12 Rack pipe. 6/21/12 RIH w/ tbg & bailer. CO to P 6/22/12 RIH w/ prod equip SN @ 40 7/02/12 Set 640 pumping unit. 7/05/12 Start prod to Washington Ba Spud Date: 05/21/2012 Thereby certify that the information above SIGNATURE	d operations. (Clearly state all pertinent details SEE RULE 1103. For Multiple Completions: SEE RULE 1103. For Multiple Complete Action SEE RULE 1103. For Multiple Complete	RECEIVED AUG 0 8 2012 NMOCD ARTESIA DATE 08/06/2012
13. Describe proposed or completed of starting any proposed work). or recompletion. Apache completed this well as follows 5/31/12 MIRUSU. 6/01/12 Tag up on DV tool & DO @ 2 60', 75', 97', 3803', 20', 40', 6 6/04/12 Spot 420 gals 15% Titrate ac 6/05/12 LD tbg. ND BOP & NU fract 6/19/12 Frac 159,230 gals 20# & 180 6/20/12 Rack pipe. 6/21/12 RIH w/ tbg & bailer. CO to P 6/22/12 RIH w/ prod equip SN @ 40 7/02/12 Set 640 pumping unit. 7/05/12 Start prod to Washington Ba Spud Date: 05/21/2012	d operations. (Clearly state all pertinent details SEE RULE 1103. For Multiple Completions: SEE RULE 1103. For Multiple	RECEIVED AUG 0 8 2012 NMOCD ARTESIA DATE 08/06/2012
13. Describe proposed or completed of starting any proposed work). or recompletion. Apache completed this well as follows 5/31/12 MIRUSU. 6/01/12 Tag up on DV tool & DO @ 2 60', 75', 97', 3803', 20', 40', 6 6/04/12 Spot 420 gals 15% Titrate ac 6/05/12 LD tbg. ND BOP & NU fract 6/19/12 Frac 159,230 gals 20# & 180 6/20/12 Rack pipe. 6/21/12 RIH w/ tbg & bailer. CO to P 6/22/12 RIH w/ prod equip SN @ 40 7/02/12 Set 640 pumping unit. 7/05/12 Start prod to Washington Ba Spud Date: 05/21/2012 Thereby certify that the information above SIGNATURE	d operations. (Clearly state all pertinent details SEE RULE 1103. For Multiple Completions: SEE RULE 1103. For Multiple	RECEIVED AUG 0 8 2012 NMOCD ARTESIA DATE 08/06/2012