




# United States Department of the Interior

BUREAU OF LAND MANAGEMENT  
Carlsbad Field Office  
620 E. Greene St.  
Carlsbad, NM 88220-6292



IN REPLY REFER TO:  
NMLC-068677  
3162.4 (P0220)



August 23, 2012

30-015-36407

Not Drilled

Cimarex Energy Co. of Colorado  
600 N. Marienfeld St., Ste. 600  
Midland, TX 79701

Gentlemen:

Your Applications for Permit to Drill (APDs) the referenced wells have expired because drilling has not commenced within two years as per Onshore Order #1.

NMLC-068677 Glycerin 10 Federal Com 3, 2020'S. & 330'E., sec.10, T. 16 S., R. 29 E.

APD EXT. Approved on September 2, 2010, APD expired on June 16, 2012

If a well has not been spud, but site construction activities have occurred please contact Jim Amos at (575) 234-5909 for surface reclamation instructions. If drilling operations have commenced on a well send all necessary reports (spud, casing/cementing, etc., 1 original and 3 copies) to the BLM, so we may correct our records.

Sincerely,

For Don Peterson  
Assistant Field Manager  
Lands & Minerals

bcc:  
P0221, I&E CFO  
NMOCD Artesia