Office	State of New Mexico	Form C-103
<u>- 10111111</u>	rgy, Minerals and Natural Resources	June 19, 2008
1625 N French Dr , Hobbs, NM 88240 District II		WELL API NO. 30-015-01592
1301 W Grand Ave , Artesia, NM 88210 OI	L CONSERVATION DIVISION	5. Indicate Type of Lease
District III	1220 South St. Francis Dr.	STATE X FEE
1000 Rio Brazos Rd , Aztec, NM 87410 District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S St Francis Dr , Santa Fe, NM	,	E0-0135-0005
87505 SUNDRY NOTICES AND	DEDODTE ON WELLC	
(DO NOT USE THIS FORM FOR PROPOSALS TO DI		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR USE "APPLICATION FO	R PERMIT" (FORM C-101) FOR SUCH	Empire Abo Unit "D"
PROPOSALS.) 1. Type of Well: ☑ Oil Well ☐ Gas Well	□ Other:	8. Well Number _{034A}
2. Name of Operator	- Other.	9. OGRID Number
Apache Corporation		873
3. Address of Operator		10. Pool name or Wildcat
303 Veterans Airpark Lane, Suite 3000 Midlar	nd, TX 79705	Empire; Abo (22040)
4. Well Location		
Unit Letter_N : 330	feet from the South line and 23	110 feet from the West line
Section 27	Township 17S Range 28E	NMPM County Eddy
	vation (Show whether DR, RKB, RT, GR, etc.	
3676' G		
12. Check Appropri	ate Box to Indicate Nature of Notice	. Report or Other Data
** *		•
NOTICE OF INTENTION		BSEQUENT REPORT OF:
	AND ABANDON 🔲 REMEDIAL WO	
		RILLING OPNS. P AND A
	PLE COMPL CASING/CEME	NT JOB
DOWNHOLE COMMINGLE		
OTHER	□ OTHER	
UIBER		
OTHER. 13. Describe proposed or completed oper		nd give pertinent dates, including estimated date
13. Describe proposed or completed oper	ations. (Clearly state all pertinent details, a	nd give pertinent dates, including estimated date
13. Describe proposed or completed oper	ations. (Clearly state all pertinent details, a	nd give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
13. Describe proposed or completed oper of starting any proposed work). SEE	ations. (Clearly state all pertinent details, a	
13. Describe proposed or completed oper of starting any proposed work). SEE	ations. (Clearly state all pertinent details, a	
13. Describe proposed or completed oper of starting any proposed work). SEE	ations. (Clearly state all pertinent details, a	
13. Describe proposed or completed oper of starting any proposed work). SEE	ations. (Clearly state all pertinent details, a	
 Describe proposed or completed oper of starting any proposed work). SEE or recompletion. 	ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: A	Attach wellbore diagram of proposed completion
 Describe proposed or completed oper of starting any proposed work). SEE or recompletion. 	ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: A	Attach wellbore diagram of proposed completion acked fluid. We are re-evaluating increased
Describe proposed or completed oper of starting any proposed work). SEE or recompletion. Apache would like to TA this well by setting.	ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: A	Attach wellbore diagram of proposed completion acked fluid. We are re-evaluating increased
Describe proposed or completed oper of starting any proposed work). SEE or recompletion. Apache would like to TA this well by setting injection and pressure maintenance.	ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: A	Attach wellbore diagram of proposed completion acked fluid. We are re-evaluating increased
13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion. Apache would like to TA this well by setting injection and pressure maintenance. TA status may be gran	ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: A a CIBP above top perfs and fill hole with particle after a	Attach wellbore diagram of proposed completion acked fluid. We are re-evaluating increased
13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion. Apache would like to TA this well by setting injection and pressure maintenance. TA status may be grar successful MIT test is	ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: A a CIBP above top perfs and fill hole with partied after a performed.	Attach wellbore diagram of proposed completion acked fluid. We are re-evaluating increased
13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion. Apache would like to TA this well by setting injection and pressure maintenance. TA status may be grar successful MIT test is Contact the OCD to so	ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: A a CIBP above top perfs and fill hole with partied after a performed. hedule the test	Attach wellbore diagram of proposed completion acked fluid. We are re-evaluating increased
13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion. Apache would like to TA this well by setting injection and pressure maintenance. TA status may be grar successful MIT test is	ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: A a CIBP above top perfs and fill hole with partied after a performed. hedule the test	Attach wellbore diagram of proposed completion acked fluid. We are re-evaluating increased PRECEIVED SEP 2 4 2012
13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion. Apache would like to TA this well by setting injection and pressure maintenance. TA status may be grar successful MIT test is Contact the OCD to so so it may be witnessed.	ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: A a CIBP above top perfs and fill hole with partied after a performed. hedule the test d.	Attach wellbore diagram of proposed completion acked fluid. We are re-evaluating increased
13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion. Apache would like to TA this well by setting injection and pressure maintenance. TA status may be grar successful MIT test is Contact the OCD to so so it may be witnessed.	ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: A a CIBP above top perfs and fill hole with partied after a performed. hedule the test d.	Attach wellbore diagram of proposed completion acked fluid. We are re-evaluating increased PRECEIVED SEP 2 4 2012
13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion. Apache would like to TA this well by setting injection and pressure maintenance. TA status may be grar successful MIT test is Contact the OCD to so so it may be witnessed.	ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: A a CIBP above top perfs and fill hole with partied after a performed. hedule the test d.	Attach wellbore diagram of proposed completion acked fluid. We are re-evaluating increased PRECEIVED SEP 2 4 2012
13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion. Apache would like to TA this well by setting injection and pressure maintenance. TA status may be grar successful MIT test is Contact the OCD to so so it may be witnessed. Spud Date: 01/26/1960	ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: A a CIBP above top perfs and fill hole with particle after a performed. hedule the test d. Rig Release Date: 04/30/1960	Attach wellbore diagram of proposed completion acked fluid. We are re-evaluating increased PALIZ RECEIVED SEP 2 4 2012 INIVIOCD ARTESIA
13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion. Apache would like to TA this well by setting injection and pressure maintenance. TA status may be grar successful MIT test is Contact the OCD to so so it may be witnessed.	ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: A a CIBP above top perfs and fill hole with particle after a performed. hedule the test d. Rig Release Date: 04/30/1960	Attach wellbore diagram of proposed completion acked fluid. We are re-evaluating increased PALIZ RECEIVED SEP 2 4 2012 INIVIOCD ARTESIA
13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion. Apache would like to TA this well by setting injection and pressure maintenance. TA status may be grar successful MIT test is Contact the OCD to so so it may be witnessed. Spud Date: 01/26/1960	ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: A RULE 1103. For Multiple Completions: A repeated after a performed. Hedule the test d. Rig Release Date: 04/30/1960	Attach wellbore diagram of proposed completion acked fluid. We are re-evaluating increased PALIZ RECEIVED SEP 2 4 2012 INIVIOCD ARTESIA
13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion. Apache would like to TA this well by setting injection and pressure maintenance. TA status may be grar successful MIT test is Contact the OCD to so so it may be witnessed. Spud Date: 01/26/1960	ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: A a CIBP above top perfs and fill hole with particle after a performed. hedule the test d. Rig Release Date: 04/30/1960	Attach wellbore diagram of proposed completion acked fluid. We are re-evaluating increased PALIZ RECEIVED SEP 2 4 2012 INIVIOCD ARTESIA
13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion. Apache would like to TA this well by setting injection and pressure maintenance. TA status may be grar successful MIT test is Contact the OCD to so so it may be witnessed so it may be witnessed. Spud Date: 01/26/1960 I hereby certify that the information above is the SIGNATURE	ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: A RULE 1103. For Multiple Completions: A repertinent details, a RULE 1103. For Multiple Completions: A repertinent details, a Rule 1103. For Multiple Completions: A repertinent details, a Rule 1103. For Multiple Completions: A repertinent details, a Rule 1103. For Multiple Completions: A rule 1103. For Multiple Completion	Attach wellbore diagram of proposed completion acked fluid. We are re-evaluating increased PRECEIVED SEP 2 4 2012 ININI OCD ARTESIA ge and belief. DATE 09/19/2012
13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion. Apache would like to TA this well by setting injection and pressure maintenance. TA status may be grar successful MIT test is Contact the OCD to so so it may be witnessed so it may be witnessed. Spud Date: 01/26/1960 I hereby certify that the information above is the SIGNATURE Type or print name Fatima Vasquez	ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: A RULE 1103. For Multiple Completions: A repeated after a performed. Hedule the test d. Rig Release Date: 04/30/1960	Attach wellbore diagram of proposed completion acked fluid. We are re-evaluating increased PRECEIVED SEP 2 4 2012 ININI OCD ARTESIA ge and belief. DATE 09/19/2012
13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion. Apache would like to TA this well by setting injection and pressure maintenance. TA status may be grar successful MIT test is Contact the OCD to so so it may be witnessed so it may be witnessed. Spud Date: 01/26/1960 I hereby certify that the information above is the SIGNATURE Type or print name Fatima Vasquez For State Use Only	ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: A RULE 1103. Flow Rule 1103. Flow Rule 1103. Flow Rule 1103. Flow Rule 1103. Rig Release Date: 04/30/1960. Fue and complete to the best of my knowled TITLE Regulatory Tech E-mail address: Fatima Vasquez@a	Attach wellbore diagram of proposed completion acked fluid. We are re-evaluating increased PHIZ RECEIVED SEP 2 4 2012 INIMIDED ARTESIA ge and belief. DATE 09/19/2012 Apachecorp.com PHONE: (432) 818-1015
13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion. Apache would like to TA this well by setting injection and pressure maintenance. TA status may be grar successful MIT test is Contact the OCD to so so it may be witnessed so it may be witnessed. Spud Date: 01/26/1960 I hereby certify that the information above is the SIGNATURE Type or print name Fatima Vasquez For State Use Only	ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: A RULE 1103. For Multiple Completions: A repertinent details, a RULE 1103. For Multiple Completions: A repertinent details, a Rule 1103. For Multiple Completions: A repertinent details, a Rule 1103. For Multiple Completions: A repertinent details, a Rule 1103. For Multiple Completions: A rule 1103. For Multiple Completion	Attach wellbore diagram of proposed completion acked fluid. We are re-evaluating increased PHIZ RECEIVED SEP 2 4 2012 INIMIDED ARTESIA ge and belief. DATE 09/19/2012 Apachecorp.com PHONE: (432) 818-1015