

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-005-60520
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. K-2114
7. Lease Name or Unit Agreement Name LER 16
8. Well Number 9
9. OGRID Number 185217
10. Pool name or Wildcat Chisum SA, East

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Fred F. Pool, III

3. Address of Operator
P.O. Box 132, Roswell, NM 88202

4. Well Location
Unit Letter K : 2200 feet from the South line and 1650 feet from the West line
Section 16 Township 11S Range 28E NMPM Chaves County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3676 GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type earth Depth to Groundwater 200+ Distance from nearest fresh water well 1 Mi+ Distance from nearest surface water 1 Mi+

Pit Liner Thickness: 12 mil Below-Grade Tank: Volume bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach well bore diagrams of proposed completion or recompletion.

We propose to P & A this well as follows;

NOTE: There is already CIBP set 1990' (100' above top perf.).

- 1) Load hole w/mud.
- 2) Cut off casing @ TOC (approx.) 1200'. Recover casing.
- 3) Spot cement plug across stub of casing, 50' in and 50' out (50 sx), tag.
- 4) Spot 25 sx cement plug across top of Queen @ 952'.
- 5) Spot cement plug across shoe of 13 3/8" surface pipe @ 315' (50' in, 50' out) 65 sx. TAG
- 6) 10 sx at surface with dry hole marker.

If this work requires an earthen pit, a permit must be approved prior to construction of the pit(s).

Notify OCD 24 hrs. prior to any work date

I declare the above to be true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank application is in accordance with NMOCDC guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE

Fred F. Pool, III

TITLE Operator

DATE 4/29/05

Type or print name Fred F. Pool, III

E-mail address: spool@dfn.com

Telephone No. 623-4667

For State Use Only

APPROVED BY:

Phil Anderson

TITLE

Field Inspector

DATE 5/3/05