
Office		New Me		Form C-103
District I	Energy, Minerals	s and Natu	ıral Resources	March 4, 2004
1625 N. French Dr., Hobbs, NM 88240				WELL API NO.
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSER	VATION	DIVISION	30-015-25044
District III	1220 Sout			5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410		e, NM 8'		STATE FEE
District IV	Saina r	e, mili	7303	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505				
	ES AND REPORTS C	N WELLS	S	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSA)	LS TO DRILL OR TO DEF	EPEN OR PL	UG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICA"	TION FOR PERMIT" (FOR	RM C-101) F	OR SUCH	Atoka San Andres
PROPOSALS.) 1. Type of Well:		RE	CEIVED	8. Well Number
Oil Well Gas Well C)ther			159
		MA	AY 1 9 2005	
2. Name of Operator	* D	dot	大AFTE QIA	9. OGRID Number
Devon Energy Production Co.	LP		in the second	6137
3. Address of Operator	10			10. Pool name or Wildcat
PO Box 250, Artesia, NM 8821				Atoka San Andres
4. Well Location				
Unit Letter C: 125 feet fro	om the North line and	d 1665 fee	et from the West1	line
	1: 100 P	265 37		7.11
				ounty Eddy
	11. Elevation (Show w	vhether DR	R, RKB, RT, GR, etc.) was a supplied to
Pit or Below-grade Tank Application (For pi	t on below grade tonk ale		. C 144 must be attach	A Section
Pit Location: ULSect_ Twp	Rng_ Pit type_	Depth t	to Groundwater_	Distance from nearest fresh water well
Distance from nearest surface water	Below-grade Tank Locat	tion UL	SectTwp	Rng;
feet from the _line and _feet fr	om the _line			
		ndicate N		Report or Other Data
NOTICE OF INTI	ÊNTION TO:			SEQUENT REPORT OF:
NOTICE OF INTI	ENTION TO: PLUG AND ABANDOI CHANGE PLANS	N 🗆	SUE REMEDIAL WOR COMMENCE DR	SEQUENT REPORT OF: K
NOTICE OF INTI	ENTION TO: PLUG AND ABANDOI CHANGE PLANS MULTIPLE	N 🗆	SUE REMEDIAL WOR COMMENCE DR CASING TEST A	SEQUENT REPORT OF: K
NOTICE OF INTI	ENTION TO: PLUG AND ABANDOI CHANGE PLANS	N 🗆	SUE REMEDIAL WOR COMMENCE DR	SEQUENT REPORT OF: K
NOTICE OF INTI	ENTION TO: PLUG AND ABANDOI CHANGE PLANS MULTIPLE	N 🗆	SUE REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB	SEQUENT REPORT OF: K
NOTICE OF INTIPERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	ENTION TO: PLUG AND ABANDOR CHANGE PLANS MULTIPLE COMPLETION	N	SUE REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: Chart	SEQUENT REPORT OF: KK
NOTICE OF INTI PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. Test and Chart for TA. Contacted Mike	ENTION TO: PLUG AND ABANDOR CHANGE PLANS MULTIPLE COMPLETION red operations. (Clear)). SEE RULE 1103.	N	SUE REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: Chart pertinent details, an ole Completions: A	SEQUENT REPORT OF: K
NOTICE OF INTI PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. Test and Chart for TA. Contacted Mike	ENTION TO: PLUG AND ABANDOR CHANGE PLANS MULTIPLE COMPLETION red operations. (Clear c). SEE RULE 1103.	N	SUE REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: Chart pertinent details, an ole Completions: A	SEQUENT REPORT OF: RK ALTERING CASING ALTERIN
NOTICE OF INTI PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. Test and Chart for TA. Contacted Mike	ENTION TO: PLUG AND ABANDOR CHANGE PLANS MULTIPLE COMPLETION red operations. (Clear c). SEE RULE 1103.	N	SUE REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: Chart pertinent details, an ole Completions: A	SEQUENT REPORT OF: RK ALTERING CASING ALTERIN
NOTICE OF INTI PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. Test and Chart for TA. Contacted Mike	ENTION TO: PLUG AND ABANDOR CHANGE PLANS MULTIPLE COMPLETION red operations. (Clear c). SEE RULE 1103.	N	SUE REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: Chart pertinent details, an ole Completions: A	SEQUENT REPORT OF: RK ALTERING CASING ALTERIN
NOTICE OF INTI PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. Test and Chart for TA. Contacted Mike	ENTION TO: PLUG AND ABANDOR CHANGE PLANS MULTIPLE COMPLETION red operations. (Clear c). SEE RULE 1103.	N	SUE REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: Chart pertinent details, an ole Completions: A	SEQUENT REPORT OF: RK ALTERING CASING ALTERIN
NOTICE OF INTIPERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. Test and Chart for TA. Contacted Mike and the starting and t	ENTION TO: PLUG AND ABANDOR CHANGE PLANS MULTIPLE COMPLETION Ted operations. (Clear E). SEE RULE 1103. The Bratcher. Was told the second of	ly state all For Multiphat if no one	SUE REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: Chart pertinent details, an ole Completions: A me showed up, continue pest of my knowleds	ALTERING CASING ILLING OPNS. PLUG AND ABANDONMENT ND ABANDONMENT and test d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion AUSS - 476 nue with test. Chart and report is attached.
NOTICE OF INTIPERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. Test and Chart for TA. Contacted Mike and the starting and t	ENTION TO: PLUG AND ABANDOR CHANGE PLANS MULTIPLE COMPLETION Ted operations. (Clear E). SEE RULE 1103. Bratcher. Was told the complete of th	ly state all For Multip hat if no on CSG ete to the b guidelines [SUE REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: Chart pertinent details, an ole Completions: A me showed up, continue the completion of the co	ALTERING CASING ALTERING CASIN
NOTICE OF INTIPERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. Test and Chart for TA. Contacted Mike or recompletion. Test and Chart for TA. Contacted Mike or recompletion. I hereby certify that the information aborande tank has been/will be constructed or closs SIGNATURE Type or print name Jennifer Van Cure.	ENTION TO: PLUG AND ABANDOR CHANGE PLANS MULTIPLE COMPLETION Ted operations. (Clear E). SEE RULE 1103. Bratcher. Was told the Seed according to NMOCE OWN CLUMPA	ly state all For Multiphat if no on ete to the boundelines [SUE REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: Chart pertinent details, an ole Completions: A me showed up, conting the sh	ALTERING CASING ALTERING CASIN
NOTICE OF INTIPERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. Test and Chart for TA. Contacted Mike Control of the Control o	ENTION TO: PLUG AND ABANDOR CHANGE PLANS MULTIPLE COMPLETION Ted operations. (Clear E). SEE RULE 1103. Bratcher. Was told the Seed according to NMOCE OWN CLUMPA	ly state all For Multiphat if no on ete to the boundelines [SUE REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: Chart pertinent details, an ole Completions: A me showed up, conting the sh	ALTERING CASING ALTERING CASING CASING ALTERING CASING CASING CASING CASING CASING CASING ALTERING CASING CASING CASING CASING CASING CASING CASING CA
NOTICE OF INTIPERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. Test and Chart for TA. Contacted Mike Company Abandana Starting any proposed work or recompletion. Test and Chart for TA. Contacted Mike Company Abandana Starting any proposed work or recompletion. Test and Chart for TA. Contacted Mike Company Abandana Starting any proposed or complete of starting any proposed or complete or complet	ENTION TO: PLUG AND ABANDOR CHANGE PLANS MULTIPLE COMPLETION Ted operations. (Clear E). SEE RULE 1103. Bratcher. Was told the Seed according to NMOCE OWN CLUMPA	ly state all For Multiphat if no on ete to the boundelines [SUE REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: Chart pertinent details, an ole Completions: A me showed up, conting the sh	ALTERING CASING ALTERING CASING CASING ALTERING CASING CASING CASING CASING CASING CASING ALTERING CASING CASING CASING CASING CASING CASING CASING CA
NOTICE OF INTIPERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. Test and Chart for TA. Contacted Mike or recompletion. Test and Chart for TA. Contacted Mike or recompletion. I hereby certify that the information aborande tank has been/will be constructed or closs SIGNATURE Type or print name Jennifer Van Cure.	ENTION TO: PLUG AND ABANDOR CHANGE PLANS MULTIPLE COMPLETION Ted operations. (Clear E). SEE RULE 1103. The Bratcher. Was told the seed according to NMOCE The Seed according to NMOCE The E-mail address: John E-mail address: John Moce Seed according to NMOCE Seed accord	ly state all For Multiphat if no on ete to the boundelines [SUE REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: Chart pertinent details, an ole Completions: A me showed up, conting the sh	ALTERING CASING ALTERING CAS



Page 1 of 1 **DAILY ABANDONMENT REPORT** DATE: 4/29/2005 **ASAU 159** PERMIAN BASIN DISTRICT: TIGHT GROUP: UNRESTRICTED REPORT NO: 3 SPUD DATE: 1/18/1985 LOCATION: 14-18-S 26-E 6
PROJECT: PB NEW MEXICO PROD SUP: FORMATION: KB ELEV: LITHOLOGY: DEPTH: FOOTAGE: ATOKA WI: FIELD: DSS: COUNTY: EDDY API: 300-15-25044 RIG NM / NO: 1 STATE: NM AFE #: 63510NA PBTD: RIG PH #: PROP. #: 63510-532 AFE DRLG COST: 0 AFE COMP COST: AFE TOTAL COST: 0 AUTH TVD: (ft) 2,350 DAILY COMP COST: 0 DAILY TOTAL COST: 0 CUM TOTAL COST: DAILY DRLG COST:

AUTH TVD AUTH TMD					DAILY DRLG CO		2,350 11,300	DAILY COM			AILY TOTAL (UM TOTAL C		2,350 11,300
lo Casing							Length		-	es up to 04/29/0		Bot (ft)	Den (ft)
	Job T			Equip	. Repaired		-		F	Remarks			
		NDON			A -4114 1				1	000	TO CLIMANA		<u>-</u>
		Hrs 5.00	Prob?		Activity L V TO LOCATION.			S OF	Code	T	TS SUMMAF		costs
06:00 11	:00	5.00		PACKER FLI AND NU WE SWEDGE, A RIGGED DO AND PRESS FOR 30 MIN. YESTERDAN WE WERE G	V TO LOCATION. UID. POOH AND I LL FLANG. LEFT 2" 1000# VALVE WN PULLING UN URED UP CSG T IT HELD LOSE 5 ((MIKE BRATCHE GOING TO TEST.) HEAD AND DUE	LAY DOWN FLANG, A AND A BU IT. RIGGEI O 500 PSI G PSI IN 30 ER) AND TO HE SAID IF	N 2 7/8" TBG 2 7/8' TO 2" LL PLUG OI D UP KILL T AND CHAR MIN. CALLE OLD HIM TH	S. ND BOP N TOP. RUCK TED IT ED OCD HE TIME HOWED	Code 377-102 377-501 377-711	MILL TRUCK A PULLING UNIT SUPERVISOR	Γ		1,000.00 1,200.00 150.00
											M	ECEIV AY 19 2	005
										Total Daily Cos	st:		2,3

Total Daily Cost:

FOREMAN: MATHEWS, J / CHANEY, J Cumulative Cost to Date:

11,300

Page 1 of 1 **DAILY ABANDONMENT REPORT** DATE: 4/28/2005 **ASAU 159** DISTRICT: PERMIAN BASIN TIGHT GROUP: UNRESTRICTED REPORT NO: SPUD DATE: 1/18/1985 LOCATION: 14-18-S 26-E 6 PROD SUP: FORMATION: PROJECT: PB NEW MEXICO KB ELEV: LITHOLOGY: FIELD: ATOKA WI: DEPTH: DSS: FOOTAGE: COUNTY: EDDY RIG NM / NO: API: 300-15-25044 STATE: NM AFE #: 63510NA RIG PH #: PBTD: 0 AFE TOTAL COST: 0 AFE COMP COST: 63510-532 AFE DRLG COST: PROP. #: 0 5,250 DAILY COMP COST: 8,950 CUM COMP COST: AUTH TVD: (ft) DAILY DRLG COST: 0 DAILY TOTAL COST: 5.250 AUTH TMD: (ft) 0 CUM TOTAL COST: CUM DRLG COST: 8,950

	MD: (CUM DRLG COST:	8,950	CUM COMP			M TOTAL C		8,950
Vo Cas	ing Dat	:a				Length	Top Depth	Open Zone	es up to 04/28/05	Top (ft)	Bot (ft)	Den (ft)
	Job '	Туре		Equ	ip. Repaired			F	Remarks			
TE	MP AB		ED					· · · · · · · · ·				
rom	То	Hrs	Prob?		Activity Last 24	4 Hours			COST	S SUMMA	RY	
	15:00	9.00	NO		EW TO LOCATION. RIH W		2 7/8" TBG	Code	Descrip			Costs
, S	13.50	9.00	NO	AND BIT A BIT AND S 1574' AND CSG TO 5 PACKER.	ND SCRAPPER TO 1609', ND SCRAPPER TO 1609', SCRAPPER DOWN. PICK I SET PACKER. NU PUMP OO PSI, IT HELD GOOD. PI PICKED UP A CIBP AND F HANGING.	POOH WITH T JP PACKER AN TRUCK AND TI OOH WITH TBO	BG. LAY ID RIH TO ESTED GAND	377-102 377-104 377-501 377-711	KILL TRUCK PACKER, CIBP, PULLING UNIT SUPERVISOR			500.0 2,800.0 1,800.0 150.0
		ć			,							
									Total Daily Cost:			5,2

FOREMAN: MATHEWS, J / CHANEY, J Cumulative Cost to Date:

8,950

Page 1 of 1 **DAILY ABANDONMENT REPORT ASAU 159** DATE: 4/27/2005 DISTRICT: PERMIAN BASIN TIGHT GROUP: UNRESTRICTED REPORT NO: SPUD DATE: 1/18/1985 LOCATION: 14-18-S 26-E 6 PROJECT: PB NEW MEXICO KB ELEV: LITHOLOGY: FIELD: ATOKA WI: DEPTH: DSS: FOOTAGE: COUNTY: RIG NM / NO: 300-15-25044 EDDY API: STATE: NM AFE #: 63510NA PBTD: RIG PH #: 0 AFE TOTAL COST: 63510-532 AFE COMP COST: PROP. #: AFE DRLG COST: 0 AUTH TVD: (ft) DAILY DRLG COST: DAILY COMP COST: 3,700 0 DAILY TOTAL COST: 3.700 CUM DRLG COST: AUTH TMD: (ft) 3,700 CUM COMP COST: 0 CUM TOTAL COST: 3,700

Length

No Casing Data

Top Depth Open Zones up to 04/27/05 Top (ft) Bot (ft)

Total Daily Cost:

FOREMAN: MATHEWS, J / CHANEY, J Cumulative Cost to Date:

3,700

3,700

Den (ft)

						Length Top Depth	-	s up to 04/2//05 Top (It)	Bot (it) Deli (it		
	Job T			Equ	ip. Repaired		F	Remarks			
	TEMP ABANDONED										
			Prob?	· · · · · · · · · · · · · · · · · · ·	Activity Last 2		COSTS SUMMARY				
0:00 1	7:00	7.00	NO		BLEW WELL DOWN TO		Code	Description	Costs		
						BOLTS WERE RUSTED	377-103	ВОР	700.0		
] .			VORKED WITH CHEATER IU BOP AND GOT READY	377-103	FLOW BACK TAND	1,000.0		
				TO RUN E	IT AND SCRAPPER. SD	ON	377-103 377-501	PUMP	250.		
							377-501	PULLING UNIT SUPERVISOR	1,600. 150.		
							0,,,,,,	COI LIVICOIX	100.		
								;			
		1									
	İ										
]				
							[
	Ì										
									1		
		ļ							1		
	1				Ì		L		L		