District I		ew Mexico ad Natural Resources	Form C-10 May 27, 20	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVA	ATION DIVISION	30-005-62578	
District III	1220 South S	St. Francis Dr.	5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410		NM 87505	STATE STATE STATE	
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa i C,	14141 07303	6. State Oil & Gas Lease No.	
87505			LG-4351	
SUNDRY NOT	ICES AND REPORTS ON	WEIIS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPO			Eden Valley AID State	,
DIFFERENT RESERVOIR. USE "APPLI				
PROPOSALS.)			8. Well Number	
1. Type of Well: Oil Well	Gas Well Other	RECEIVED	1	
2. Name of Operator		JUL 0 8 2005	9. OGRID Number	
Yates Petroleum Corporat	ion		025575	
3. Address of Operator	37.6.0004.0	OCD-AHTSDIA	10. Pool name or Wildcat	
105 S. 4 th Street, Artesia,	NM 88210		Pecos Slope Abo	
4. Well Location				
Unit Letter B:	660 feet from the	North line and	1980 feet from the East lin	e
Section 34	Township 7S	Range 24E	NMPM Chaves County	
Section 34		ther DR, RKB, RT, GR, etc.,		
	11. Dicvation (Show when	3781'GR		
Pit or Below-grade Tank Application	or Closure	3701 GR		
Pit type Depth to Groundwat		t frack system well Die	A	ľ
				-]
Pit Liner Thickness: mil	Below-Grade Tank: Volum	ne bbls; Co	nstruction Material	
	Appropriate Box to Indi		•	
NOTICE OF IN	NTENTION TO:	SUB	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON		K 🔲 ALTERING CASING []
TEMPORARILY ABANDON 🛛			LLING OPNS. ☐ PLUG AND ABANDON []
PULL OR ALTER CASING	MULTIPLE COMPL	☐ CASING/CEMEN	T JOB 🔲	
		_		
OTHER:		OTHER:		
				
13. Describe proposed or com	pleted operations. (Clearly s	tate all pertinent details, and	d give pertinent dates, including estimated	late
13. Describe proposed or compostarting any proposed w	pleted operations. (Clearly s ork). SEE RULE 1103. For	tate all pertinent details, and	d give pertinent dates, including estimated of tach wellbore diagram of proposed comple	date
13. Describe proposed or com	pleted operations. (Clearly s ork). SEE RULE 1103. For	tate all pertinent details, and	d give pertinent dates, including estimated of tach wellbore diagram of proposed comple	date tion
13. Describe proposed or composed wor recompletion.	rork). SEE RULE 1103. For	tate all pertinent details, and Multiple Completions: At	d give pertinent dates, including estimated of tach wellbore diagram of proposed comple	date tion
13. Describe proposed or composed or starting any proposed wor recompletion. Yates Petroleum Corporation plans	to plug and abandon this we	tate all pertinent details, and Multiple Completions: At	d give pertinent dates, including estimated of tach wellbore diagram of proposed comple	date tion
13. Describe proposed or composed or starting any proposed wor recompletion. Yates Petroleum Corporation plans 1. MIRU all safety equipment neces	to plug and abandon this we essary.	tate all pertinent details, and Multiple Completions: At	d give pertinent dates, including estimated of tach wellbore diagram of proposed comple	date tion
13. Describe proposed or composed or starting any proposed wor recompletion. Yates Petroleum Corporation plans 1. MIRU all safety equipment nece 2. Set a 4-1/2" CIBP at 3317' with	to plug and abandon this we essary.	tate all pertinent details, and Multiple Completions: At ll as follows:	d give pertinent dates, including estimated of tach wellbore diagram of proposed comple	late tion
13. Describe proposed or composed or starting any proposed wor recompletion. Yates Petroleum Corporation plans 1. MIRU all safety equipment nece 2. Set a 4-1/2" CIBP at 3317' with	to plug and abandon this we essary.	tate all pertinent details, and Multiple Completions: At ll as follows:	d give pertinent dates, including estimated of tach wellbore diagram of proposed comple	date
 Describe proposed or composed of starting any proposed wor recompletion. Yates Petroleum Corporation plans MIRU all safety equipment nece Set a 4-1/2" CIBP at 3317' with Circulate hole with 9.5# mud. PUH with tubing to 1415' and p 	to plug and abandon this we essary. 35' cement on top. Cond. Plug from 18 ump 25 sx for a 100' cement	tate all pertinent details, and Multiple Completions: At as follows: At a completion At a complet	d give pertinent dates, including estimated of tach wellbore diagram of proposed comple	date tion
of starting any proposed or composed was or recompletion. Yates Petroleum Corporation plans MIRU all safety equipment nece Set a 4-1/2" CIBP at 3317' with Circulate hole with 9.5# mud. PUH with tubing to 1415' and pum Total Composed or composed or composed or composed or recompletion.	to plug and abandon this we essary. 35' cement on top. Cond. Plug from 18 ump 25 sx for a 100' cement up 15 sx for a 60' surface plu	tate all pertinent details, and Multiple Completions: At as follows: At a completion At a complet	d give pertinent dates, including estimated of tach wellbore diagram of proposed comple	date
 Describe proposed or composed of starting any proposed wor recompletion. Yates Petroleum Corporation plans MIRU all safety equipment nece Set a 4-1/2" CIBP at 3317' with Circulate hole with 9.5# mud. PUH with tubing to 1415' and p 	to plug and abandon this we essary. 35' cement on top. Cond. Plug from 18 ump 25 sx for a 100' cement up 15 sx for a 60' surface plu	tate all pertinent details, and Multiple Completions: At as follows: At a completion At a complet	d give pertinent dates, including estimated of tach wellbore diagram of proposed comple	date
13. Describe proposed or composed or starting any proposed wor recompletion. Yates Petroleum Corporation plans 1. MIRU all safety equipment nece 2. Set a 4-1/2" CIBP at 3317' with 3. Circulate hole with 9.5# mud. 4. PUH with tubing to 1415' and p 5. PUH with tubing to 60' and pum 6. Cut off wellhead and install man	to plug and abandon this we essary. 35' cement on top. 25. sx for a 100' cement up 15 sx for a 60' surface pluker.	tate all pertinent details, and Multiple Completions: At all as follows: Magical	d give pertinent dates, including estimated of tach wellbore diagram of proposed comple	date tion
of starting any proposed or composed was or recompletion. Yates Petroleum Corporation plans MIRU all safety equipment nece Set a 4-1/2" CIBP at 3317' with Circulate hole with 9.5# mud. PUH with tubing to 1415' and pum Total Composed or composed or composed or composed or recompletion.	to plug and abandon this we essary. 35' cement on top. 25. sx for a 100' cement up 15 sx for a 60' surface pluker.	tate all pertinent details, and Multiple Completions: At all as follows: Magical	d give pertinent dates, including estimated of tach wellbore diagram of proposed comple	late
13. Describe proposed or composed or starting any proposed wor recompletion. Yates Petroleum Corporation plans 1. MIRU all safety equipment nece 2. Set a 4-1/2" CIBP at 3317' with 3. Circulate hole with 9.5# mud. 4. PUH with tubing to 1415' and p 5. PUH with tubing to 60' and pum 6. Cut off wellhead and install man	to plug and abandon this we essary. 35' cement on top. 25. sx for a 100' cement up 15 sx for a 60' surface pluker.	tate all pertinent details, and Multiple Completions: At all as follows: Magical	d give pertinent dates, including estimated of tach wellbore diagram of proposed comple	date
13. Describe proposed or composed or starting any proposed wor recompletion. Yates Petroleum Corporation plans 1. MIRU all safety equipment nece 2. Set a 4-1/2" CIBP at 3317' with 3. Circulate hole with 9.5# mud. 4. PUH with tubing to 1415' and p 5. PUH with tubing to 60' and pum 6. Cut off wellhead and install man	to plug and abandon this we essary. 35' cement on top. 25. sx for a 100' cement up 15 sx for a 60' surface pluker.	tate all pertinent details, and Multiple Completions: At all as follows: Magical	d give pertinent dates, including estimated of tach wellbore diagram of proposed comple	date
13. Describe proposed or composed or starting any proposed wor recompletion. Yates Petroleum Corporation plans 1. MIRU all safety equipment nece 2. Set a 4-1/2" CIBP at 3317' with 3. Circulate hole with 9.5# mud. 4. PUH with tubing to 1415' and p 5. PUH with tubing to 60' and pum 6. Cut off wellhead and install man	to plug and abandon this we essary. 35' cement on top. 25. sx for a 100' cement up 15 sx for a 60' surface pluker.	tate all pertinent details, and Multiple Completions: At all as follows: Magical	d give pertinent dates, including estimated of tach wellbore diagram of proposed comple	date date tion
13. Describe proposed or composed or starting any proposed wor recompletion. Yates Petroleum Corporation plans 1. MIRU all safety equipment nece 2. Set a 4-1/2" CIBP at 3317' with 3. Circulate hole with 9.5# mud. 4. PUH with tubing to 1415' and p 5. PUH with tubing to 60' and pum 6. Cut off wellhead and install man	to plug and abandon this we essary. 35' cement on top. 25. sx for a 100' cement up 15 sx for a 60' surface pluker.	tate all pertinent details, and Multiple Completions: At all as follows: Magical	d give pertinent dates, including estimated of tach wellbore diagram of proposed comple	late
13. Describe proposed or composed or starting any proposed wor recompletion. Yates Petroleum Corporation plans 1. MIRU all safety equipment nece 2. Set a 4-1/2" CIBP at 3317' with 3. Circulate hole with 9.5# mud. 4. PUH with tubing to 1415' and p 5. PUH with tubing to 60' and pum 6. Cut off wellhead and install man	to plug and abandon this we essary. 35' cement on top. 25. sx for a 100' cement up 15 sx for a 60' surface pluker.	tate all pertinent details, and Multiple Completions: At all as follows: Magical	d give pertinent dates, including estimated of tach wellbore diagram of proposed comple	date tion
of starting any proposed we or recompletion. Yates Petroleum Corporation plans 1. MIRU all safety equipment nece 2. Set a 4-1/2" CIBP at 3317' with 3. Circulate hole with 9.5# mud. 4. PUH with tubing to 1415' and pum 5. PUH with tubing to 60' and pum 6. Cut off wellhead and install man	to plug and abandon this we essary. 35' cement on top. 25. sx for a 100' cement on 15 sx for a 60' surface pluker. 35' command the steel pits and no	tate all pertinent details, and Multiple Completions: At as follows: At a follows:	tach wellbore diagram of proposed comple	tion
of starting any proposed we or recompletion. Yates Petroleum Corporation plans 1. MIRU all safety equipment nece 2. Set a 4-1/2" CIBP at 3317' with 3. Circulate hole with 9.5# mud. 4. PUH with tubing to 1415' and pum 5. PUH with tubing to 60' and pum 6. Cut off wellhead and install man NOTE: Yates Petroleum Corporation I hereby certify that the information	to plug and abandon this we essary. 35' cement on top. 25. sx for a 100' cement on 15 sx for a 60' surface pluker. 35' command the steel pits and no above is true and complete	tate all pertinent details, and Multiple Completions: At Multiple Completions: At ll as follows: Add	e and belief. I further certify that any pit or belief	nutrion
of starting any proposed we or recompletion. Yates Petroleum Corporation plans 1. MIRU all safety equipment nece 2. Set a 4-1/2" CIBP at 3317' with 3. Circulate hole with 9.5# mud. 4. PUH with tubing to 1415' and pum 5. PUH with tubing to 60' and pum 6. Cut off wellhead and install man NOTE: Yates Petroleum Corporation I hereby certify that the information	to plug and abandon this we essary. 35' cement on top. 25. sx for a 100' cement on 15 sx for a 60' surface pluker. 35' command the steel pits and no above is true and complete	tate all pertinent details, and Multiple Completions: At Multiple Completions: At ll as follows: Add	tach wellbore diagram of proposed comple	nutrion
of starting any proposed or composed was a starting any proposed with a starting and part of the starting and proposed was a starting any proposed was a starting and a starting any proposed was a starting any proposed was a starting and a starting and a starting any proposed was a starting and a starting any proposed was a starting and a	to plug and abandon this we essary. 35' cement on top. 25.5x for a 100' cement on 15 sx for a 60' surface pluker. 35' common top. 25.5x for a 60' surface pluker. 36' surface pluker. 36' surface pluker. 36' surface pluker.	tate all pertinent details, and Multiple Completions: At Multiple Completions: At ll as follows: Add - 1 - 1415 Plug. Tag plug. Ig. Tag plug. Plug. Tag	e and belief. I further certify that any pit or belor an (attached) alternative OCD-approved plan	ow-
of starting any proposed we or recompletion. Yates Petroleum Corporation plans 1. MIRU all safety equipment nece 2. Set a 4-1/2" CIBP at 3317' with 3. Circulate hole with 9.5# mud. 4. PUH with tubing to 1415' and pum 5. PUH with tubing to 60' and pum 6. Cut off wellhead and install man NOTE: Yates Petroleum Corporation I hereby certify that the information	to plug and abandon this we essary. 35' cement on top. 25.5x for a 100' cement on 15 sx for a 60' surface pluker. 35' common top. 25.5x for a 60' surface pluker. 36' surface pluker. 36' surface pluker. 36' surface pluker.	tate all pertinent details, and Multiple Completions: At Multiple Completions: At ll as follows: Add	e and belief. I further certify that any pit or bek or an (attached) alternative OCD-approved plan	ow-
13. Describe proposed or compost of starting any proposed wor recompletion. Yates Petroleum Corporation plans 1. MIRU all safety equipment nece 2. Set a 4-1/2" CIBP at 3317' with 3. Circulate hole with 9.5# mud. 4. PUH with tubing to 1415' and pum 6. Cut off wellhead and install man 6. Cut off wellhead and install man NOTE: Yates Petroleum Corporation I hereby certify that the information grade tank has been/will be constructed of SIGNATURE	to plug and abandon this we essary. 35' cement on top. 25. xx for a 100' cement on 15 sx for a 60' surface pluker. To will use steel pits and no above is true and complete r dosed according to NMOCD gu	tate all pertinent details, and Multiple Completions: At Multiple Completions: At ll as follows: Add	e and belief. I further certify that any pit or belor an (attached) alternative OCD-approved plan [nce Supervisor DATE July 7, 2005	pw-
of starting any proposed or composed was a starting any proposed with a starting and part of the starting and proposed was a starting any proposed was a starting and a starting any proposed was a starting any proposed was a starting and a starting and a starting any proposed was a starting and a starting any proposed was a starting and a	to plug and abandon this we essary. 35' cement on top. 25. x for a 100' cement on 15 sx for a 60' surface pluker. In above is true and complete redosed according to NMOCD gu	tate all pertinent details, and Multiple Completions: At Multiple Completions: At ll as follows: Add	e and belief. I further certify that any pit or belor an (attached) alternative OCD-approved plan [nce Supervisor DATE July 7, 2005	pw-
13. Describe proposed or composed of starting any proposed wor recompletion. Yates Petroleum Corporation plans 1. MIRU all safety equipment nece 2. Set a 4-1/2" CIBP at 3317' with 3. Circulate hole with 9.5# mud. 4. PUH with tubing to 1415' and p 5. PUH with tubing to 60' and pum 6. Cut off wellhead and install man note: Yates Petroleum Corporation NOTE: Yates Petroleum Corporation I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name Tina Hue	to plug and abandon this we essary. 35' cement on top. 25. xx for a 100' cement on 15 sx for a 60' surface pluker. To will use steel pits and no above is true and complete r dosed according to NMOCD gu	tate all pertinent details, and Multiple Completions: At Multiple Completions: At ll as follows: Daa'- - 1415 Plug. Tag plug. g. Tag plug. earth pits to the best of my knowledge idelines , a general permit TLE Regulatory Complia ddress:tinah@ypcnm.com	e and belief. I further certify that any pit or belor an (attached) alternative OCD-approved plan [nce Supervisor DATE July 7, 2005 Telephone No505-748-1471	pw-
13. Describe proposed or compost of starting any proposed wor recompletion. Yates Petroleum Corporation plans 1. MIRU all safety equipment nece 2. Set a 4-1/2" CIBP at 3317' with 3. Circulate hole with 9.5# mud. 4. PUH with tubing to 1415' and pum 6. Cut off wellhead and install man 6. Cut off wellhead and install man NOTE: Yates Petroleum Corporation I hereby certify that the information grade tank has been/will be constructed of SIGNATURE	to plug and abandon this we essary. 35' cement on top. 25' sx for a 100' cement on 15 sx for a 60' surface pluker. Ton will use steel pits and no above is true and complete redosed according to NMOCD gu	tate all pertinent details, and Multiple Completions: At Multiple Completions: At ll as follows: Add	e and belief. I further certify that any pit or belor an (attached) alternative OCD-approved plan [nce Supervisor DATE July 7, 2005 Telephone No505-748-1471	pw-

WELL NAME: Eden Valley AID State #1

FIELD: Pecos Slope Abo

LOCATION: 660' FNL & 1980 'FEL Sec 34-7S-24E

Chaves County

GL: 3780.6 **ZERO**: **KB**: 3788.6

SPUD DATE: 3/6/88

COMPLETION DATE:

4/5/88

COMMENTS: API # 30-005-62578

CASING PROGRAM

9 5/8 36# J-55	<u>1365'</u>
4 ½" 10.5# J -55	3800'
2 3/8" J-55	3327'

14 3/4 " Hole

9 5/8" @ 1365' w/1100 sx cmt (Circ)

7 7/8" Hole

2 3/8" tbg @ 3327' SN set @ 3327' Guiberson Tension Pkr @ 3327'

PBTD 3756'

<u>Abo</u>

Perfs: 3367-72' w/10 .42" holes-2 spf

Acidize: 1000 g 7 1/2%

Frac: 25000# 20/40 Sd

4 1/2 " @ 3800' w/1075 sx (Circ)

Not to Scale 2/17/03 Cam

TD 3800'

WELL NAME: Eden Valley AID State #1 FIELD: Pecos Slope Abo

660' FNL & 1980 'FEL Sec 34-7S-24E LOCATION: **Chaves County**

GL: 3780.6 **ZERO**: **KB**: 3788.6

SPUD DATE: 3/6/88 COMPLETION DATE: 4/5/88

API # 30-005-62578 COMMENTS:

14 3/4 " Hole

Pkr @ 3327'

PBTD 3756'

CASING PROGRAM

9 5/8 36# J-55	1365'
4 ½" 10.5# J-55	3800'
2 3/8" J-55	3327′

60' surface Plug 100' Plug from 1415' - 1315' (TAG PLUG) 9 5/8" @ 1365' w/1100 sx cmt (Circ)

<u>Tops</u>

Glorieta 1122' Yeso 1160' 3298' <u>Abo</u>

7 7/8" Hole 2 3/8" tbg @ 3327' SN set @ 3327' Guiberson Tension

CIBP @ 3317' w/ 35' cement on top

<u>Abo</u>

Perfs: 3367-72' w/10 .42" holes-2 spf Acidize: 1000 g 7 ½%

Frac: 25000# 20/40 Sd

4 1/2 " @ 3800' w/1075 sx (Circ)

Not to Scale 2/17/03 Cam

TD 3800'