V. T: Form 3160-5 (November 1994) N.M. Oil Cons. DIV-Dist. 2

UNITED STATES 1301 W. Grand August DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT 5. Le

FORM APPROVED OMB No. 1004-0135 Expires July 31, 1996

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS

NM-15295

Type of Well Gas Well Other S. Well Name and No. C. K. 7 Federal No. 1	Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name	
Secribe Proposed or Completed Operations Subsequent Report Casing Repair New Construction Pingal Abandonment Notice Casing Repair New Construction Pingal Abandon Pingal Abando	SUBMIT IN TR	RIPLICATE - Other Instru	ctions on reverse	side	7. If Unit or	CA/Agreement, Name and/or No.	
2. Name of Operator Gruy Petroleum Management Co. 3a. Address P.O. Box 140907 Irving, TX 75014-0907 4. Location of Well (Footage, Sec, T., R., M., or Survey Description) SHL 2495' FNL & 1415' FEL Sec 7G 24S-26E BHL 1275' FNL & 906' FEL Sec 7A 24S-26E BHL 1275' FNL & 906' FEL Sec 7A 24S-26E TYPE OF SUBMISSION 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION Notice of Intent Acidize Acidize Binal Abandonment Notice Casing Repair New Construction Recomplete Other Site Security Change Plans Plug and Abandon Temporarily Abandon Diagram 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereous fit the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zone Attach the Bond under which the work will be performed or provide the Bond No. on file with BMBIA. Required subsequent reports shall be filed within 30 day following completion of the involved operations. If the operation results in a multiple completion or recompleted, and the operation have been completed, and the operator in special reports shall be filed on the determined that the site is ready for final inspection.) Attached, please find a site security diagram for the CK 7 Federal No. 1.	1. Type of Well		<u> </u>	<u> </u>	NA NA		
Gruy Petroleum Management Co. 3a. Address P.O. Box 140907 Irving, TX 75014-0907 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) SHL 2495' FNL & 1415' FEL Sec 7G 24S-26E BHL 1275' FNL & 906' FEL Sec 7A 24S-26E BHL 1275' FNL & 906' FEL Sec 7A 24S-26E ULU-ATTIESIA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent	Oil Well 🖾 Gas Well	Other			8. Well Nam	ne and No.	
33. Address P.O. Box 140907 Irving, TX 75014-0907 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) SHL 2495 FNL & 1415 FEL Sec 7G 24S-26E BHL 1275 FNL & 906 FEL Sec 7A 24S-26E BHL 1275 FNL & 906 FEL Sec 7A 24S-26E BHL 1275 FNL & 906 FEL Sec 7B 24S-26E BHL 1275 FNL & 906 FEL Sec 7B 24S-26E TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Acidize Production (Start/Resume) Subsequent Report Casing Repair New Construction Recomplete Change Plans Plug and Abandon Temporarily Abandon Diagram Carlsbad; Morrow, South 11. County or Parish, State Eddy, NM TYPE OF ACTION Water Shut-Off Well Integrity Change Plans Plug and Abandon Temporarily Abandon Diagram Attach the Bond under which the work will be performed or provide the Bond No. on file with BLMBIA. Required subsequent reports shall be filed ont testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Attached, please find a site security diagram for the CK 7 Federal No. 1.	2. Name of Operator				CK7	Federal No. 1	
P.O. Box 140907 Irving, TX 75014-0907 972.401.3111 RECEIVED 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) SHL 2495' FNL & 1415' FEL Sec 7G 24S-26E BHL 1275' FNL & 906' FEL Sec 7A 24S-26E BHL 1275' FNL & 906' FEL Sec 7A 24S-26E TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent	Gruy Petroleum Manager	nent Co.			9. API Well	l No.	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) SHL 2495' FNL & 1415' FEL Sec 7G 24S-26E BHL 1275' FNL & 906' FEL Sec 7A 24S-26E BHL 1275' FNL & 906' FEL Sec 7A 24S-26E BHL 1275' FNL & 906' FEL Sec 7A 24S-26E CCU-AFT FES! Eddy, NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Acidize Deepen Production (Star/Resume) Alter Casing Fracture Treat Reclamation Well Integrity Subsequent Report Casing Repair New Construction Final Abandonment Notice Change Plans Plug and Abandon Temporarily Abandon Diagram 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereo If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zone Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BlA. Required subsequent reports shall be filed owithin 30 day following completion of the involved operations. If the operation results in a multiple completion or recompleted. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator had betermined that the site is ready for final inspection.) Attached, please find a site security diagram for the CK 7 Federal No. 1.	3a. Address						
SHL 2495 FNL & 1415 FEL Sec 7G 24S-26E BHL 1275 FNL & 906 FEL Sec 7A 24S-26E BHL 1275 FNL & 906 FEL Sec 7A 24S-26E CUU-AFT FESTA Eddy, NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen Production (Start/Resume) Alter Casing Fracture Treat Reclamation Well Integrity Casing Repair New Construction Recomplete Other-Site Security Change Plans Plug and Abandon Temporarily Abandon Diagram Diagram Diagram Diagram Diagram Diagram 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereo If the proposal is to deepen directionally or recomplete borizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zone Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed one testing has been completed. Final Abandonment Notices shall be filed one testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator hadetermined that the site is ready for final inspection.) Attached, please find a site security diagram for the CK 7 Federal No. 1.	P.O. Box 140907 Irving,	TX 75014-0907	972.401.3111	RECEIVED	10. Field and	Pool, or Exploratory Area	
BHL 1275' FNL & 906' FEL Sec 7A 24S-26E CUU-ACTIESIA Eddy, NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen Production (Start/Resume) Acidize Reclamation Well Integrity Alter Casing Fracture Treat Reclamation Recomplete Other Site Security Change Plans Plug and Abandon Temporarily Abandon Diagram Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereo If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zone Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BlA. Required subsequent reports shall be filed on following completion in a new interval, a form 3160-4 shall be filed on testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator had determined that the site is ready for final inspection.) Attached, please find a site security diagram for the CK 7 Federal No. 1.	4. Location of Well (Footage, Sec	c., T., R., M., or Survey Description)		0.0.000		<u> </u>	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen Reclamation Water Shut-Off Well Integrity Casing Repair New Construction Recomplete Other-Site Security Convert to Injection Plug Back Water Disposal Convert to Injection It the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zone Attach the Bond under which the work will be performed or provide the Bond No. on file with BLMBIA. Required subsequent reports shall be filed within 30 day following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed on testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator had determined that the site is ready for final inspection.) Attached, please find a site security diagram for the CK 7 Federal No. 1.	SHL 2495' FNL & 1415'	FEL Sec 7G 24S-26E		AUG 0 9 2005	11. County o	or Parish, State	
TYPE OF SUBMISSION Notice of Intent	BHL 1275' FNL & 906' I	QUU-ARTESIA		4	Eddy, NM		
Notice of Intent Acidize Deepen Production (Start/Resume) Water Shut-Off Well Integrity Subsequent Report Casing Repair New Construction Recomplete Other Site Security Diagram Change Plans Plug and Abandon Plug Back Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereo If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zone Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 day following completion of the involved operations. If the operation results in a multiple completion or recompleted. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator had determined that the site is ready for final inspection.) Attached, please find a site security diagram for the CK 7 Federal No. 1.	12. CHECK AI	PPROPRIATE BOX(ES) TO	INDICATE NATUI	RE OF NOTICE, R	EPORT, OR	OTHER DATA	
Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Other Site Security Diagram Change Plans Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereo If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zone Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 day following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed one testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator had determined that the site is ready for final inspection.) Attached, please find a site security diagram for the CK 7 Federal No. 1.	TYPE OF SUBMISSION	·	TY	PE OF ACTION			
Subsequent Report Casing Repair New Construction Recomplete Other Site Security Diagram Convert to Injection Plug and Abandon Plug Back Water Disposal Convert and true vertical depths of all pertinent markers and zone Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed on testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator had determined that the site is ready for final inspection.) Attached, please find a site security diagram for the CK 7 Federal No. 1.	Notice of Intent	☐ Acidize	Deepen Deepen	Production (Star	1/Resume)	☐ Water Shut-Off	
Final Abandonment Notice Change Plans Plug and Abandon Plug Back Water Disposal Convert to Injection Plug Back Water	~	Alter Casing	Fracture Treat	Reclamation		· ·	
Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereo If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zone Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BlA. Required subsequent reports shall be filed within 30 day following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed on testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator had determined that the site is ready for final inspection.) Attached, please find a site security diagram for the CK 7 Federal No. 1.	Subsequent Report	Casing Repair	New Construction	Recomplete		Other Site Security	
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereo If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zone Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 day following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed one testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator had determined that the site is ready for final inspection.) Attached, please find a site security diagram for the CK 7 Federal No. 1.	Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily Al	oandon	Diagram	
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all perturent markers and 20 day Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BlA. Required subsequent reports shall be filed within 30 day following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed one testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator had determined that the site is ready for final inspection.) Attached, please find a site security diagram for the CK 7 Federal No. 1.		Convert to Injection	Plug Back	Water Disposal			
ACCEPTED FOR RECORD	If the proposal is to deepen din Attach the Bond under which t following completion of the in- testing has been completed. F determined that the site is ready	ectionally or recomplete horizontally the work will be performed or provovolved operations. If the operation inal Abandonment Notices shall be for final inspection.)	y, give subsurface locatio ide the Bond No, on file results in a multiple comp filed only after all requi	ns and measured and tr with BLM/BIA. Requireletion or recompletion	ue vertical deptired subsequent in a new intervamation, have t	hs of all pertinent markers and zones to reports shall be filed within 30 days all, a Form 3160-4 shall be filed once been completed, and the operator has	
					ACCEP	TED FOR RECORD	

AUG - 8 2005 LES BABYAK PETROLEUM ENGINEER

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	Title		
Natalie Krueger	Regulatory Technician		
Signature at a lie Kruger	Date August 3, 2005		
THIS SPACE FOR FEDERA	L OR STATE OFFICE US	SE	
Approved by	Title	Date	
Conditions of approval, if any, are attached. Approval of this notice does not warm certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.	nt or lease Office ACC	epted for record NMOCD	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



