
Form 316G-5 (March 2012)	NE HAVE & MELE, A.T.	RIGERVATION DIVIS			TODA ( ADDA OF TO	
	NM OIL CO UNITED STATES PARTMENT OF THE INT	E EIEST STREET	RECE	VED	FORM APPROVED OMB No. 1004-0137	
BUF	REAU OF LAND MANAGE	EBSHANNIM 88210	DEC <b>21</b>	52 Ucase Seria	Expires: October 31, 2014 No.	
SUNDRY	NOTICES AND REPORT	S ON WELLS		NM 27634	ottee or Tribe Name	
Do not use this abandoned well.	NOTICES AND REPORT form for proposals to d Use Form 3160-3 (APD)	rill or to re-ente ) for such prope	MOCD A psals.	TESIAJ		
SUBMIT IN TRIPLICATE – Other instructions on page 2.				7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well Image: Gas Well   Image: Oil Well Image: Gas Well   Image: Other				8. Well Name and No. Hanagan Federal #5		
2. Name of Operator Pecos River Operating, Inc.				9. API Well No. 30-005-62996		
3a. Address     3b. Phone No. (include area code)       PO Box 1433     575 622 1001			10. Field and Pool or Exploratory Area Pecos Slope, Abo			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 660 FSL, 1980 FWL, Section 14, T175, R26E				11. County or Parish, State Chaves		
	CK THE APPROPRIATE BOX(E	S) TO INDICATE NA	TURE OF NOTIO	L CE, REPORT OF	R OTHER DATA	
TYPE OF SUBMISSION	1.	· · · · · · · · · · · · · · · · · · ·	TYPE OF ACT			
Notice of Intent	Acidize	Deepen		uction (Start/Resu	ime) 🔲 Water Shut-Off	
[Y] Nonce of Intent	Alter Casing	Fracture Treat	Recl:	mation	Well Integrity	
Subsequent Report	Casing Repair	New Construction		mplete	Other	
Final Abandonment Notice	Change Plans	Plug and Abandon Plug Back		porarily Abandon er Disposal		
•		C. 11				00', 970
We will then run tubing and load th 2000' 1. 35 sx @ 2100' - 2969-to-2100' t				10 <sup>2</sup> -Witnes	BUREAU BUREAU	
2000' 1. 35 sx @ 2100' - 2009-to-2100' t 2. 250 sx @ 970' - Surface	to cover top of Glorietta & 204	9-TageOrA	bove 200			
1. 35 sx @ 2100' - 2000' to 2. 250 sx @ 970' - Surface After plugging the well to the surface APPROVED FOR <u>3</u>	to cover top of Glorietta® 204 ce, a dry hole marker will be ins	9-TageOrA	bove 200		ROSWELL OF ICE	RECENED
1. 35 sx @ 2100' - 2000' 2. 250 sx @ 970' - Surface After plugging the well to the surface	to cover top of Glorietta& 204 ce, a dry hole marker will be ins	9-TageOrA	bove 200			
1. 35 sx @ 2100' - 2000' 2. 250 sx @ 970' - Surface After plugging the well to the surface APPROVED FOR <u>3</u>	to cover top of Glorietta & 204 ce, a dry hole marker will be ins MONTH PERIOD 0 2013	9-Tage Or A	bove 200		ROSWELL OF ICE	
1. 35 sx @ 2100' - 2000' to 2. 250 sx @ 970' - Surface After plugging the well to the surface APPROVED FOR <u>3</u> <u>MAR 1</u> 14. Thereby certify that the foregoing is	to cover top of Glorietta & 204 ce, a dry hole marker will be ins MONTH PERIOD 0 2013	9-Tage Or A	bove 200		ROSWELL OF ICE	
1. 35 sx @ 2100' - 2000' to 2. 250 sx @ 970' - Surface After plugging the well to the surface APPROVED FOR <u>3</u> <u>MAR 1</u> 14. Thereby certify that the foregoing is	to cover top of Glorietta & 204 ce, a dry hole marker will be ins MONTH PERIOD 0 2013	9-Tage Or A talled and the location	bove 200		ROSWELL OF ICE	
1. 35 sx @ 2100' - 2000' to 2. 250 sx @ 970' - Surface After plugging the well to the surface APPROVED FOR <u>3</u> ENDING <u>MAR 1</u> 14. Thereby certify that the foregoing is Phelps White	to cover top of Glorietta & 204 ce, a dry hole marker will be ins MONTH PERIOD 0 2013	P-TageOrA talled and the location ped) Title Pre Date 11/	bove 200 on cleared and le esident /28/2012	veled.	ROSWELL OF ICE	
1. 35 sx @ 2100' - 2000' to 2. 250 sx @ 970' - Surface After plugging the well to the surface APPROVED FOR <u>3</u> ENDING <u>MAR 1</u> 14. I hereby certify that the foregoing is Phelps White Signature Approved by /S/ DAVI	to cover top of Glorietta@204 ce, a dry hole marker will be ins 	P-TageOrA talled and the location ped) Title Pre Date 11/ <b>R FEDERAL OF</b>	bove 200 on cleared and le esident 28/2012 R STATE OF	FICE USE	ROV 93 PH 2: 42	
1. 35 sx @ 2100' - 2000' to 2. 250 sx @ 970' - Surface After plugging the well to the surface APPROVED FOR 3 ENDING MAR 1 14. I hereby certify that the foregoing is Phelps White Signature Approved by /S/DAVI Conditions of approval, if any, are attach that the applicant holds legal or equitable	to cover top of Glorietta@204 ce, a dry hole marker will be ins 	P-TageOrA talled and the location ped) Title Pre Date 11/ <b>R FEDERAL OF</b>	bove 200 on cleared and le esident 28/2012 R STATE OF PETROLEUM	FICE USE	POSWELL OF LUND 2: 42	
1. 35 sx @ 2100' - 2000' to 2. 250 sx @ 970' - Surface After plugging the well to the surface APPROVED FOR 3 ENDING MAR 1 14. I hereby certify that the foregoing is Phelps White Signature Approved by /S/ DAVI Conditions of approval, if any, are attach that the applicant holds legal or equitable entitle the applicant to conduct operation	to cover top of Glorietta@204 ce, a dry hole marker will be ins 	P-TageOrA talled and the location ped) Title Pre Date 11/ <b>R FEDERAL OF</b> warrant or certify use which would Offi	bove 200 on cleared and leased esident 28/2012 R STATE OF PETROLEUM	FICE USE	ELL OF LAND PH 2: 47	
1. 35 sx @ 2100' - 2000' to 2. 250 sx @ 970' - Surface After plugging the well to the surface APPROVED FOR 3 ENDING MAR 1 14. I hereby certify that the foregoing is Phelps White Signature Signature Approved by /S/DAVI Conditions of approval, if any, are attach that the applicant to conduct operation Title 18 U.S.C. Section 1001 and Title 4 fictitious or fraudulent statements or rep	to cover top of Glorietta@204 ce, a dry hole marker will be ins 	Ped) Title Pre Date 11/ R FEDERAL OF warrant or certify use which would Offi me for any person knowi	bove 200 on cleared and leased esident 28/2012 R STATE OF PETROLEUN ce ngly and willfully	FICE USE	DEC 10 2	
1. 35 sx @ 2100' - 2000' to 2. 250 sx @ 970' - Surface After plugging the well to the surface APPROVED FOR 3 ENDING MAR 1 14. I hereby certify that the foregoing is Phelps White Signature Approved by /S/ DAVI Conditions of approval, if any, are attach that the applicant holds legal or equitable entitle the applicant to conduct operation Title 18 U.S.C. Section 1001 and Title 4	to cover top of Glorietta@204 ce, a dry hole marker will be ins 	Ped) Title Pre Date 11/ <b>R FEDERAL OF</b> warrant or certify use which would Offi ne for any person knowi	bove 200 on cleared and leased esident 28/2012 R STATE OF PETROLEUN ce	FICE USE	DEC 10 2	

# Proposed Plan

Pecos River Operating, Inc.



# Pecos River Operating Hanagan Fed. #5 API 30-005-62996

## WELL/BORE DIAGRAM

Hanagan Fed #5



# .8 5/8" 24# J-55 @ 912'. Cement Circulated

#### Top of Cement Est 3700'

Perforations: 4244 to 4733

# 4 1/2 11.5# J-55 @ 4800

# San Andres 865

#### Glorietta 2049

#### Abo 4214

### BUREAU OF LAND MANAGEMENT Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 (575) 627-0272

# Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon. If you are unable to plug the well by the 90<sup>th</sup> day provide the BLM Roswell Field Office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when the BLM Roswell Field Office can expect the well to be plugged: Failure to do so will result in enforcement action.

2. <u>Notification:</u> Contact the BLM Roswell Field Office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, during office hours call (575) 910-6024 or after office hours call (575) 627-0205. Engineer on call during office hours phone (575) 627-0275 or phone (after hours) call (575) 626-5749.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9090 feet; a 3M system for a well not deeper than 13636 feet; and a 5M system for a well not deeper than 22727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at a rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement:</u> Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 50 feet of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C" for up to 7500 feet of depth, mixed at 14.8 lbs./gal with 6.3 gallons of fresh water per sack or class "H" for deeper than 7500 feet plugs, mixed at 16.4 lbs./gal with 4.3 gallons of fresh water per sack.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10 feet in length, 4 feet above the ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to the BLM Roswell Field Office. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged.</u>

Following the submittal and approval of the Subsequent Report of Abandonment, a Notice of Intent for Final Abandonment with the proposed surface restoration procedure must be submitted for approval.