Form 3160-5 (March 2012)

## UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD Artesia

FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014

5. Lease Serial No. NM000503

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE – Other instructions on page 2.				7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well  Oil Well  Gas Well  Other				8. Well Name and No. Cotton Draw Unit 162H		
Name of Operator     Devon Energy Production Company, L.P.				9. API Well No. 30-015-39730		
3a. Address 333 W. Sheridan Avenue Oklahoma City, Oklahoma 73102	3b. Phone No. (include area code) 405-228-4248		10. Field and Pool or Exploratory Area Cotton Draw; Delaware South			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 330 FSL & 860 FWL, Unit M, Sec 11, T25S-R31E				11. County or Parish, State Eddy, NM		
12. CHE	CK THE APPROPRIATE E	SOX(ES) TO INDICATE NATUR	RE OF NOT	ICE, REPORT OR OTH	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	=	roduction (Start/Resume) Water Shut-Off Well Integrity		
Subsequent Report	Casing Repair Change Plans	New Construction Plug and Abandon	=	Recomplete Other Spud Report  Temporarily Abandon		
Final Abandonment Notice	Convert to Injection	Plug Back	☐ Wa	Water Disposal		
the proposal is to deepen direction Attach the Bond under which the following completion of the invol testing has been completed. Final determined that the site is ready for	hally or recomplete horizont work will be performed or p wed operations. If the opera Abandonment Notices must or final inspection.)	ally, give subsurface locations an provide the Bond No. on file with ation results in a multiple complet to be filed only after all requireme	d measured BLM/BIA. ion or reconnts, includin	and true vertical depths Required subsequent re apletion in a new interval g reclamation, have bee	·	
	Is FW. Circ 329 sx to sui 3/8" casing to 1210 psi fo ole @ 4335'. RIH w/99 jts	rf. WOC. Test BOPE, CK Mai or 30 minutes. Test Good. s 9-5/8" 40# J-55 LTC csg & se	nifold , 250 et @ 4335'.	psi, L 3500 psi H, An Lead w/ 1203 sx Cl (	nular 1500 psi. All tests 10 mins.  C, yld 2.05 sf/sx. Tail w/300 sx Cl C,	

All tested good. Pressure Test 8-3/4" casing to 1500 psi for 30 minutes. Test Good. 11/23/12 - 11/26/12: TD 8-3/4" vertical hole @ 7585'. TIH w/curve assembly. KOP @ 7585'. TD Curve. TOH to run E-logs. TIH w/lateral assembly. 12/02/12 - 12/04/2012: TD' 8-3/4" production hole @ 12612'. RIH w/170 jts 5-1/2" 17# HCP110 BTC & 120 jts 5-1/2" HCP 110 LTC csg, set @ 12594'; CHC. 1st lead w/400 sx Cl H, Yld 2.3 cf/sx, 2nd Lead w/350 sx Cl H, Yld 2.01 cf/sx. Tail w/1,475 sx Cl "H" cmt, Yld 1.28 cf/sx; disp w/ 291 bbls FW; did not circulate cmt. RD Cementer. Release Rig @ 1800 hrs. \*note: CBL ran on 12/12/12. Found TOC @ 4866'.

Accepted for record

RECEIVED

MAY **2 1** 2013

NMOCD ARTESIA

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed

Patti Riechers

Title Regulatory Specialist

Date 05/02/2013

ACCEPTED FOR RECORD

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

CARLSBAD FIELD OFFICE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)