

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised July 18, 2013

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-41240
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator DEVON ENERGY PRODUCTION COMPANY, LP.		6. State Oil & Gas Lease No.
3. Address of Operator 333 WEST SHERIDAN AVENUE, OKC, OK 73102		7. Lease Name or Unit Agreement Name Lone Ranger 33 State
4. Well Location Unit Letter 1 : 1895 feet from the SOUTH line and 50 feet from the EAST line Section 33 Township 28S Range 27E NMPM EDDY, County		8. Well Number 2H
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3111' (23S)		9. OGRID Number 6137
		10. Pool name or Wildcat FOREHAND RANCH; BONE SPRING

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: Drilling Operations: Spud First 3' ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

07/26/13

MIRU. Butches Rat Hole Services. Set 10' x 30' pipe with a lid. Cemented 30" Csg 3' from the top and back filled it with dirt to the top. Drill time 1 hour.

RECEIVED

AUG 22 2013

NMOCD ARTESIA

Spud Date:

7/26/13

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Erin Workman

TITLE

Regulatory Compliance Associate

DATE

08/14/13

Type or print name

Erin L. Workman

E-mail address:

Erin.workman@dmn.com

PHONE:

(405) 552-7970

For State Use Only

APPROVED BY:

SPDade

TITLE

Dist. Rep. Supervisor

DATE

8/22/2013

Conditions of Approval (if any):



AUGUST 1, 2013

DEVON
SETH IRELAND
seth.ireland.dvn.com

ON JULY 26, 2013, WE SET 10' X 30" PIPE WITH A LID ON THE LONE RANGER 33 STATE 2H. WE CEMENTED THE 30" CASING 3' FROM THE TOP AND BACK FILLED IT WITH DIRT TO THE TOP. DRILL TIME WAS 1 HOUR.

PLEASE LET ME KNOW IF YOU HAVE ANY QUESTIONS.

REGARDS,

LEE SELLERS
DRILLING SERVICES COORDINATOR