<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720 District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 District III

State of New Mexico

Form C-101 Revised July 18, 2013

Energy Minerals and Natural Resources

Oil Conservation Division

1000 Rio 1 Phone: (50 District I 1220 S. Se Phone: (5

Brazos Road, Aztec, NM 87410	1000 C	
505) 334-6178 Fax: (505) 334-6170	1220 South St. Francis Dr.	NOV A C COLO
<u>IV</u> 50. Francis Dr., Santa Fe, NM 87505 505) 476-3460 Fax: (505) 476-3462	Santa Fe, NM 87505	NOV 08 2013
(303) 410-3402 Fax. (303) 410-3402		NMOCD ARTESIA
PLICATION FOR PERMIT TO DRILL,	RE-ENTER, DEEPEN, PLUG	BACK, OR ADD A ZONE
1. Operator Name and Address		2 OGRID Number
ser-Francis Oil Company		012361

APPLIC	CATION	I FOR J	PERMIT T	O DRII	L, RE-EN	TER, DF	EPEN, I	PLUGBACK	C, OR AD	D A ZONE
		1.	1. Operator Name a	and Address	-				² OGRID Numl 012361	ber
			Company 11sa, OK	74121-	1468			1	3 API Number -015-2641	r_
	rty Code				3. Property Na	ame		30-	015-2641 %	L 5 Vell No. 1
<u> </u>		2991	Malaga l		7. Surface Loc			L		
UL - Lot	Section	Township	Range	Lot ldn			/S Line	Feet From	E/W Line	County
_C	1	24S	28E	÷ ÷	660		rth	1980	West	Eddy
				* Pro	posed Bottom	Hole Loc	ation			
UL - Lot	Section	Township	Range	Lot Idn	Feet from	n N	/S Line	Feet From	E/W Line	County
- Jahr					9. Pool Inform	nation				
Culebra Culogra	Bluff	South	n (Bone Sp	rings)	Pool Name				<u> </u>	Pool Code 15011
			•	Addi	itional Well In	oformation				
11. Worl	<u>к Туре</u>	T	12. Well Type	T	13. Cable/Ro			Lease Type	15. Gr	ound Level Elevation
16. Mu	P	-	G 17. Proposed Depth		R 18. Formatio	ion	. 19	P Contractor	_	2956 20. Spud Date
1	No		12100	Z1	nd Bone Sp	orings Unk. 8/25			8/25/90	
Depth to Grou	nd water	n/a	Dista	nce from nea	arest fresh water w	well Distance to nearest surface water n/a				
XWe will be	using a clo		system in lieu o	f lined pits	;					
_	-	•	·	_	l Casing and (Cement Pr	ogram			
Туре	Hole S	Size	Casing Size	1	g Weight/ft	T	g Depth	Sacks of C	ement	Estimated TOC
Surface	17 1	./2 1	13 3/8		48	6	15	775	5	Surf
Interm.	12 1	. /, 4	9 5/8	36	& 40	25	50	1150)	Surf
Prod.	8 3	1/4	7		26	106	71	1400	J	4610
					t Program: A					
Liner:	+½" , 15	.1# se	et from 10)328 '- 1	2098'. C	mt'd w/	285 sxs	s. TOC @ 1	10328'.	
			22.	Proposed	Blowout Pre	vention Pr	ogram			
	Туре		'	Working Pres	ssure	Test Pressure			М	lanufacturer
·						<u>1 </u>				,
12 _ , ,	- 41-			• • • • • • • • • • • • • • • • • • • •						
best of my kno			on given above is t	rue and com	plete to the	İ	OIL C	CONSERVAT	ION DIVIS	SION
I further cert 19.15.14.9 (B' Signature:	• / —	1	ed with 19.15.14.9	9 (A) NMA(C ☐ and/or	Approved B	y://	hound	1	
Printed name:	Charl	Attas	Van Valker	ohuro	7	Title:	<u> </u>	JI 19.	lonie	
			ry Complia		$\overline{}$	Approved D	nte: 11/01	121/2	piration Date:	11/0/2015
• • • • • • • • • • • • • • • • • • •	T KPU									

E-mail Address: Charlotv@kfoc.net Phone: 918-491-4314 Date: 11/7/13 Conditions of Approval Attached District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone: (575) 748-1283 Fax: (575) 748-9720
District III
1000 Rio Brazos Road, Aztec, NM 87410
Phone: (505) 334-6178 Fax: (505) 334-6170
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505
Phone: (505) 476-3460 Fax: (505) 476-3462

State of New Mexico
Energy, Minerals & Natural Resources Department
OIL CONSERVATION DIVISION OCT 3 0 2
1220 South St. Francis Dr.

NMOCD ARTESIA

Form C-102
Revised August 1, 2011
OCT 3 0 20/3 Submit one copy to appropriate
District Office

AMENDED REPORT

WELL LOCATION AND ACREAGE DEDICATION PLAT

Santa Fe, NM 87505

¹ API Number	² Pool Code	³ Pool I	lame		
015-26415	15011	Culebra Bluff South (Bo	ne Springs)		
⁴ Property Code		⁶ Well Number			
22991	Mala	1 ' 1			
⁷ OGRID No.		8 Operator Name	⁹ Elevation		
012361	Kaiser-Francis Oil Company 2956				

Surface Location UL or lot no. Section Township Range Lot Idn Feet from the North/South line East/West line Feet from the County 660 North 1980 24S 28E C 1 Eddy West

¹¹ Bottom Hole Location If Different From Surface

_										
I	UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County
-				1						N
Ī	¹² Dedicated Acres	13 Joint o	r Infili 14 (Consolidation	Code 15 Or	der No.				
-	40	N	Į.	_		_		•		

No allowable will be assigned to this completion until all interests have been consolidated or a non-standard unit has been approved by the division.

16	A	•		"OPERATOR CERTIFICATION
•	2	,		I hereby certify that the information contained herein is true and complete
1980'	8	•		to the best of my knowledge and belief, and that this organization either
1900				owns a working interest or unleased mineral interest in the land including
	•			the proposed bottom hole location or has a right to drill this well at this
				location pursuant to a contract with an owner of such a mineral or working
				interest, or to a voluntary pooling agreement or a compulsory pooling opter heretofore-entered by the division.
				Siprature Charlotte Van Valkenburg Printed Name
			:	Charlotv@kfoc.net E-mail Address
				"SURVEYOR CERTIFICATION I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys
İ	,	·		made by me or under my supervision, and that the same is true and correct to the best of my belief.
				Date of Survey
·		. * .		Signature and Seal of Professional Surveyor:
				Certificate Number

Kaiser-Francis Oil Company 2nd Bone Springs Recompletion Procedure Malaga #1 Federal Com #1

Section 1, T24S, R28E Eddy County, New Mexico API # 30-015-26415

WELL DATA

Elevation:

GL Elev. = 2956'

KB Elev. = 2975

Surface Casing:

13-3/8" 48# @ 615', cemented w/ 775 sx, circ.

Intermediate Csg:

9 5/8" 36# & 40# K-55 @ 2,550', cemented w/ 1150 sx, circ.

Intermediate Csg:

7" 26# S-95 & N-80 @ 10,671', cemented w/ 1400 sx. TOC

= 4610' (temp srvy)

Liner:

4 ½" 15.1# C-75 FL-4S f/ 10,328' - 12,098', cmt'd w/ 285 sx.

CBL shows patchy cement f/ 11,430-TOL.

TD:

12,100'

PBTD:

11,986'

Proposed Perfs:

2nd Bone Springs: 8756-64, 8779-90, 8802-12

Current perfs:

11,827'-37' Atoka A-3, 11,896' -905' Atoka Bank Lime

		п ропо.	1			,	,				
		·	•		Con		•		Burst	Coll.	Jt Str.
OD	Weight	Grade	Depth	Conn	OD	ID	Drift	Capacity	(80%)	(80%)	(80%)
			0-								
7"	26#	S-95	10,671'	LT&C	-	6.276	6.151	0.038262	6880	4696	
4 1/2"	15.1#	C-75	10328- 12098	LT&C	-	3.826	3.701	0.01422	7864	8312	
2 3/8"	4.7#	J-55	10330- 11,750	8RD	3.063	1.995	1.901	0.003866	6160	6480	57384
2 7/8"	6.5#	N/L-80	0-10,328'	Nu-Lok	????	2.441	2.347	0.005788	8456	8456	115968
3 1/2"	10.2#	P-110		CS	3.916	2.922	2.797	0.008294	10672	9061	249600
3 1/2"	9.3#	P-110		CS	3.916	2.992	2.867	0.008696	10672	9061	228000

^{**}Exact data for Nu-Lok tubing connections unknown-should be close to 8RD.

Annulus	Capacity
2 7/8" X 7"	0.030232
3 1/2" X 7"	0.026362
2 3/8" X 4	
. 1/2"	0.00874
2 3/8" X 7"	0.032782

WELL DATA (cont'd):

Tubing String

160 jts 2 7/8" N-80 Nu-Lok 166 jts 2 7/8" N-80 Nu-Lok CB 3' X 2 7/8" pup joint Lindsey Seal Assembly 44 jts 2 3/8" J-55 EOT @ 11,750' 1 1/4" CT inside 2 7/8" RECEIVED

0CT 3 0 2013

NMOCD ARTESIA

PROCEDURE

1) MIRU 1 ¼" CT unit. Kill w ell w/ lease brine. ND CT wellhead. Weld on to 1 ¼" CT string and POOH. RDMO CTU.

Note: CT Grade in unknown

Note: Current FTP is 540#.

- 2) MIRU WOR and pump truck. Set pipe racks and cat walk. Note and report tubing and all annuli pressures on first report.
- 3) Kill well, as necessary, w/ lease brine. ND wellhead. NU BOP w/ 2 7/8" pipe rams. RU tubing scanners. Sting out of Lindsey seal assembly and TOOH w/ 2 7/8" Nu-Lok tubing scanning and standing back. LD joints w/ less than 70% remaining wall thickness. LD seal assembly and 2 3/8" tailpipe.
- 4) Round trip bit and scraper for 7", 26# casing to top of 4 ½" liner at 10,328'. Flush casing w/ 40 bbls lease brine.
- 5) MIRU ELU and pack-off. RIH w/ GR/JB for 4 ½", 15.1# casing. Carefully work tool through liner top and into liner to just above perfs at 11,800'. POOH. RIH w/ 4 ½" 10K CIBP. Carefully work plug through liner top and into liner and set plug in above Atoka perfs at ~11,790'. POOH w/ setting tool. RIH w/ bailer and dump 35' cement on top of plug.

Note: take note of fluid level going in with plug.

Note: all depths correlated to SLB CN-LD log run #2 (10-1-90)

6) Load casing. RIH w/ CBL/VDL. Log cement f/ 10,170' to ~6000' w/ 1500# imposed on the well. Correlate CBL to SLB CN-LDL run #1 (9-15-90). Contact Ardmore/Tulsa if cement bond is at all questionable in the proposed perforation area.

Note: Send copies of log to: <u>BillyW@KFOC.net</u>, <u>VinceD@KFCO.net</u> and <u>Da</u>vidZ@KFOC.net.

- 7) TIH w/ SN on O/E 2 7/8" tubing to 10,721'. MIRU cementers. Pump 45sx Class H cement plug f/ 10,721-10,278'. P/U out of cement and reverse string clean. WOC and tag plug to verify TOC is at 10,278' or higher.
- 8) Circulate hole w/ clean 2% KCl. Test plug and casing to 1500#. Swab FL down to ~7000'. TOOH w/ tubing –laying down.
- 9) MIRU ELU and lubricator. RIH and set 7", 10K CIBP above TOC at 10,270'. W/ the FL at 7000', RIH w/ 4" slick gun carrying 3325-321T or equivalent charges (0.41" EHD X 43.58" PEN). Perforate 2nd Bone Springs as follows:

8756-64	2 SPF	120° phasing	17 holes
8779-90	2 SPF	120° phasing	23 holes
8802-12	2 SPF	120° phasing	21 holes

Note: all depths correlated to SLB CN-LDL log run #2 (2-17-90)

POOH w/ spent guns. Monitor for any pressure changes at the surface.

- 10) Take delivery of 3 ½", 10.3#, P-110, CS hydrill frac string. Strap and tally pipe. Change rams in BOP to accommodate 3 ½" tubing. RU tubing testers. P/U and TIH w/ the following BHA (B to T) on 3 ½" tubing to ~8720' testing to 10,000#:
 - A. WLREG
 - B. "XN" nipple (frac-hardened)
 - C. 3 joints of tailpipe
 - D. 10K treating packer
 - E On/Off tool w/ "X" Profile (frac-hardened)
 - F. Remaining 3 ½" tubing to surface.

Note: optimal make-up torque for 3 ½", 10.3# CS P-110 is 3375 ft/lbs (Max:3800 ft*lbs, Min: 3000 ft*lbs). Calibrate tongs before use.

Note: Make and break connections using low tong speed to prevent gaulding.

Note: Dope pins only with proper pipe dope and use a stabbing guide to make up. Ensure thread protectors are collected, accounted-for and reinstalled whenever pipe is picked up or laid down.

- 11) Set packer. Land hanger w/ string in compression (dependent on tubemove). ND BOP. NU 3 1/16' X 10M tree. Load annulus w/ 2% KCl. Test 3 ½" X 7" annulus to 1500#.
- 12)Break 2nd Bone Springs perfs down w/ 15 bbls 2% KCl. Report initial, 5 min, 10 min and 15 min SIPs. RDMO pump truck. RDMO WOR.

Note: impose 1500# on annulus and monitor throughout job.

- 13)R/U 10M tree-saver. Set steam-cleaned frac tanks and fill w/ 2% KCl (from powder, not substitute) water. RU FBE.
- 14)RU stimulation company. Pump fracture-stimulation on 2nd Bone Springs perfs as per attached schedule. Report initial, 5 min, 10 min and 15 min SIPs. RDMO tree saver and stimulation provider.

Note: impose 1500# on annulus and monitor throughout job.


Note: max treating pressure will be limited to 9500#. Set pop-offs to release at 10K. Test same.

Note: install pop-off on 3 1/2" X 5 1/2" annulus. Test same.

- 15)Flow back well, monitor for gas and oil production. When well dies, MIRU WOR. Release pkr, run tailpipe down through perfs to verify everything is clear and POOH. LD workstring.
- 16) Take delivery of 2 7/8" N-80 production tubing. RIH w/ BP, MA, perf sub SN and TAC on 2 7/8" tubing. Place the SN @ ~8835 and TAC @ ~8650'. Make some swab runs to verify fluid is clean.
- 17)Run rods and pump (design forthcoming). Seat pump. Load and test tubing to 300#. Set unit and evaluate pump action. RDMO WOR.
- 18) Put well on production.

	Kaiser-Francis	Malaga 1 Federal Com #1
Location:	660' FNL, 1680' FWL, Section 1,	API - 30-015-26415
	T24S, R28E	Field: Malaga
County:	Eddy	Spud Date: 8/25/90
State:	New Mexico	Completed: 10/24/90
Elevation:	GL - 2956' KB - 2975'	Diagram: Updated - 6/2013
	Je 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Work History:
88888888888888888888888888888888888888	100'	8/25/90 - Spud well. Tursur - Corripteutin - Periratoka Barik - Trayor - Wira - Street 60 deg phasing using a 3-3/8" csg gun, 37 .34" holes. Az w 2000 gal MOD 101, 47 ball sealers & 50 gal Musol A w/ 1000 SCF/bbl N2 in flush, AIR 2.6 BPM, ISIP 6470#, ATP 6950#. Flw 48 hrs, 1199 MCFD, FTP 665#, 5 day SITP 3220#. Acid Frac w/ 3000 gal GW, 4000 gal 20% HCI, 3501 gal GW, 7260 gal 20% HCI & 7000 gal GW, all w/ 20% CO2, AIR 9.5 BPM, ATP 7300, ISIP 5680, 15 min 4520. Jetted well in w/ CT and N2. Flw 24 hrs, 770 MCFD, FTP 600. Perf Atoka A-3 zone 11827-37' w/ 4 SPF, 41 holes. Tast hoth zones @ 3300 mcfnd.@ 15/55# FTP. 2/01 - Clean out w/ 1-1/4" CT. CT stuck at 10,700", worked free and clean out to bottom perf. Az w/ 200 gals 15% NeFe, flush w/ KCI & N2. Well KO flwg 200 - 300 mcfpd. 8/04 - Swab, made 2 runs, rec'd 2 BW, RDMO 7/06 - Swab, MIRU, comp running, RDMO 11/09 - 20 hr SITP 414#. RIH w/ 1-5/8" gauge ring tag TD @ 11,997*. RIH with psi gauges made stops 2,4,6,8,10, 10,500*, & 11,866* - BHP 645#. 1/10 - RIH w/1-1/4" coil tbg, circ 4 BW w/ N2 & set @ 11,800*. Start soap injection.

Malaga 1 Com 1
Coard Loop System Plagram



State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez
Governor


David Martin Cabinet Secretary - Designate

Brett F. Woods, Ph.D. Deputy Cabinet Secretary

October 31, 2013

Kaiser-Francis Oil Co. P.O. Box 21468 Tulsa, OK 74121-1468 Jami Bailey Division Director Oil Conservation Division





NON-DENIAL OF APD(S) DESPITE NON-COMPLIANCE WITH INACTIVE WELL REQUIREMENTS

Re:

Kaiser-Francis Oil Company, OGRID No. 12361

Malaga 1 Com #1, C-1-T24S-R28E, 660' FNL & 1980' FWL, Eddy County, New Mexico

Dear Operator:

You have requested a permit to drill, deepen or plug back the well/s identified above. Unfortunately, according to the attached inactive well list, your company is out of compliance with 19.15.5.9(A) NMAC [Part 5.9(A)] due to having too many wells in violation of 19.15.25.8 NMAC [Part 25.8] (inactive well rule) that are not subject to an inactive well agreed compliance order ("ACOI"). See Part 5.9(A)(4) NMAC. As an operator of 50 wells, your company may have no more than 2 wells in violation of Part 25.8. Your company has 4 wells in violation.

The Director of the Oil Conservation Division ("OCD") or her designee <u>may deny a permit to drill, deepen or plug back</u> if the applicant is not in compliance with Part 5.9(A). See 19.15.14.10(A) NMAC.

An Operator is not in compliance with Part 5.9(A) if the Operator:

- does not meet the financial assurance requirements of 19.15.8 NMAC;
- is subject to a division or commission order finding the operator to be in violation of an order requiring corrective action;

I To check an operator's compliance with the inactive well rule, go to the OCD's website at www.emnrd.state.nrn.us/ocd. On the left-hand side of the main window, click on "OCD Online"; select "£-Permitting"; click on "Compliance"; click on "Inactive Well List." Leave the search terms as "Exclude Wells Under ACOI," "Exclude Wells in Approved TA Period,:' and "15" months from last production or injection. Enter the operator's name or OGRID and select "Get Report." The report will list wells operated by that operator that are presumed to be out of compliance with the division's inactive well rule, and that will be considered in determining if the operator is out of compliance with Part 5.9(A).

- has a penalty assessment that has been unpaid for more than 70 days since the issuance of the order assessing the penalty; or
- has more than the allowed number of wells out of compliance with 19.15.25.8
 NMAC (inactive well rule).

As the Director's designee I have decided **not to deny** your APD application on the basis of 5.9. However, my decision not to deny your APD on the basis of Part 5.9 does not constitute approval of your APD by the OCD District Office, which may impose specific requirements.

Please note, however, that the OCD cannot assign an allowable to a well or issue authorization to transport oil or natural gas from a well if the operator is out of compliance with Part 5.9. See 19.15.16.19(A) NMAC. Therefore, if your company is not in compliance with Part 5.9(A) at the time it requests an allowable and authorization to transport, its request will be denied.

To come into compliance with Part 5.9(A) as to inactive wells you must reduce the number of wells on your inactive well list or otherwise demonstrate that you have no more than the tolerated number of wells out of compliance with the inactive well rule. A well will be removed from the inactive well list when you take one of the following actions:

- 1. plug the wellbore and file an approved C-103 reporting the plugging;
- 2. place the well on approved temporary abandonment status;
- 3. return the well to production or other beneficial use and file a C-115 reporting production or use; or
- 4. enter into an ACOI with the OCD covering the well.

An ACOI sets a schedule for returning the operator's inactive wells to compliance and imposes sanctions if the schedule is not met. If you would like to discuss entering into an ACOI for your non-compliant inactive wells, please contact OCD Compliance & Enforcement Manager, Daniel Sanchez at (505) 476-3493 or daniel.sanchez@state.nm.us.² Attached is an information sheet explaining Part 5.9.

This non-denial of your APD(s) for the above identified well(s) despite non-compliance with inactive well requirements automatically expires six months from today's date unless an APD for the above well(s) is approved within that time by the OCD District Office.

Respectfully yours,

Daniel Sanchez

OCD Enforcement & Compliance Manager

Variable

² Please note that Agreed Compliance Orders are offered at the discretion of the OCD, and that not all Operators are eligible to enter into such agreements.

6733 South Yale Avenue, 74136 (918) 494-0000

November 7, 2013

State of New Mexico
Oil Conservation Division
811 S. First
Artesia, NM 88210

Re: Permit to Recomplete (Form C-101)

Malaga 1 Com 1

API 30-015-26415

Dear Sirs:

Please find attached form C-101 for the subject well. This was previously filed and denied due to the inactive well rule. I have also attached a letter from Mr. Daniel Sanchez stating his decision <u>not</u> to deny our application. We realize the well will not be assigned an allowable or issued authority to transport oil or natural gas until we are back in compliance. However, this recompletion is necessary to prevent loss of lease and Kaiser-Francis would therefore appreciate expedited approval.

Thank you for your cooperation in this matter. Should anything further be necessary, please feel free to contact me at 918-491-4314 or by email at Charlotv@kfoc.net.

Sincerely,

C. Tan Jalkenburg

Charlotte Van Valkenburg

Mgr., Regulatory Compliance

Attachments