orm 3160- 5	UNITED	STATES	OCD Artesia	FORM APPROVED OMB No. 1004- 0137					
ugust, 2007)	DEPARTMENT O								
	BUREAU OF LANI	D MANAGEMENT		Expires: July 2	31, 2010				
SL	INDRY NOTICES ANI	D REPORTS ON WE	5. Lease Serial No. NMNM100858						
Do	not use this form for prop	use this form for proposals to drill or to re-enter an ned well. Use Form 3160-3 (APD) for such proposals.			6. If Indian, Allottee, or Tribe Name				
aban SUBMIT IN	7. If Unit or CA. Agreement Name and/or No.								
Type of Well	NM 1308	31							
Gas Well			8. Well Name and No.						
Name of Operator				Blue Thunder 5					
OG Operating LLC		3b. Phone No. (inclu	de area code)		0874				
2208 W. Main Street		575-7	48-6940	30-015-3					
Artesia, NM 88210		Lat.		10. Field and Pool, or Exploratory Area Hack Berry; Bone Spring, Nort					
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		,		11. County or Parish, State					
SHL: 660' FNL & 200' FE	EL, Sec 5-T19S-R31E	Long.		Eddy County	NM				
CHECK APPROPRIATE BO	X(S) TO INDICATE NATU	URE OF NOTICE, REPO	RT, OR OTHER D	ATA					
TYPE OF SUBMISSION		T	YPE OF ACTION						
Notice of Intent	Acidize	Deepen	Production (St	art/Resume) Water	Shut-off				
	Altering Casing	Fracture Treat	Reclamation	Well Is	ntegrity				
Subsequent Report	Casing Repair	New Construction	Recomplete	Other					
			· ·						
	Chanye Plans	Plug and abandon	Temporarily Al	bandon					
Final Abandonment Notice	Change Plans	Plug and abandon	Temporarily Al		<u></u>				
	Convert to Injection Operation (clearly state all per	Plug back	Water Disposa ated starting date of	any proposed work and appro					
3. Describe Proposed or Completed If the proposal is to deepen dire Attach the Bond under which the following completion of the involv testing has been completed. Final determined that the site is ready for final	Convert to Injection Operation (clearly state all per ectionally or recomplete horizon work will performed or provid ed operations. If the operation Abandonment Notice shall be al inspection.)	Plug back rtinent details including estim tally, give subsurface locatio le the Bond No. on file with results in a multiple comple	Water Disposa ated starting date of ins and measured and in the BLM/ BIA. Req ition or recompletion in	1 any proposed work and appro true vertical depths or pertin uired subsequent reports shall n a new interval, a Form 316	ent markers and be filed within 30 50-4 shall be filed , and the operato				
3. Describe Proposed or Completed If the proposal is to deepen dire Attach the Bond under which the following completion of the involv testing has been completed. Final	Convert to Injection Operation (clearly state all per ectionally or recomplete horizon work will performed or provid ed operations. If the operation Abandonment Notice shall be al inspection.)	Plug back rtinent details including estim tally, give subsurface locatio le the Bond No. on file with results in a multiple comple	Water Disposa ated starting date of ins and measured and in the BLM/ BIA. Req ition or recompletion in	any proposed work and appro true vertical depths or pertin uired subsequent reports shall in a new interval, a Form 316 mantion, have been completed	ent markers and be filed within 30 60-4 shall be filed , and the operato				
 Describe Proposed or Completed If the proposal is to deepen dir Attach the Bond under which the following completion of the involv testing has been completed. Final determined that the site is ready for final Method for Water Disposa Name of formation proof 	Convert to Injection Operation (clearly state all per ectionally or recomplete horizon work will performed or provid ed operations. If the operation Abandonment Notice shall be al inspection.)	Plug back rtinent details including estim ntally, give subsurface locatio te the Bond No. on file with results in a multiple comple e filed only after all require Bone Spring	Water Disposa ated starting date of ins and measured and in the BLM/ BIA. Req ition or recompletion in	any proposed work and appro true vertical depths or pertin uired subsequent reports shall in a new interval, a Form 316 mantion, have been completed	ent markers and be filed within 30 50-4 shall be filed , and the operato				
 Describe Proposed or Completed If the proposal is to deepen dire Attach the Bond under which the following completion of the involv testing has been completed. Final determined that the site is ready for final Method for Water Disposa Name of formation proof Amount of water product 	Convert to Injection Operation (clearly state all per ectionally or recomplete horizon work will performed or provid ed operations. If the operation Abandonment Notice shall be al inspection.)	Plug back rtinent details including estim ntally, give subsurface locatio le the Bond No. on file with results in a multiple comple e filed only after all require Some Spring 517 BWPD	Water Disposa ated starting date of ins and measured and in the BLM/ BIA. Req ition or recompletion in	any proposed work and appro true vertical depths or pertin uired subsequent reports shall in a new interval, a Form 316 mantion, have been completed	ent markers and be filed within 30 50-4 shall be filed , and the operato				
 Describe Proposed or Completed If the proposal is to deepen dire Attach the Bond under which the following completion of the involv testing has been completed. Final determined that the site is ready for final Method for Water Disposa Name of formation proof Amount of water product How water is stored on 	Convert to Injection Operation (clearly state all per ectionally or recomplete horizon work will performed or provid ed operations. If the operation Abandonment Notice shall be al inspection.)	Plug back rtinent details including estim ntally, give subsurface locatio le the Bond No. on file with results in a multiple comple e filed only after all require Gone Spring 517 BWPD rglass tanks	Water Disposa ated starting date of ins and measured and in the BLM/ BIA. Req ition or recompletion in	any proposed work and appro true vertical depths or pertin uired subsequent reports shall in a new interval, a Form 316 mantion, have been completed	ent markers and be filed within 30 50-4 shall be filed , and the operato				
 Bescribe Proposed or Completed If the proposal is to deepen dire Attach the Bond under which the following completion of the involv testing has been completed. Final determined that the site is ready for final Method for Water Disposa Name of formation proof 2) Amount of water product How water is stored on How water is moved to 	Convert to Injection Operation (clearly state all per ectionally or recomplete horizon work will performed or provid ed operations. If the operation Abandonment Notice shall be al inspection.)	Plug back rtinent details including estim ntally, give subsurface locatio le the Bond No. on file with results in a multiple comple e filed only after all require Gone Spring 517 BWPD rglass tanks	Water Disposa ated starting date of ins and measured and in the BLM/ BIA. Req ition or recompletion in	any proposed work and appro true vertical depths or pertin uired subsequent reports shall in a new interval, a Form 316 mantion, have been completed	ent markers and be filed within 30 60-4 shall be filed , and the operato				
 Bescribe Proposed or Completed If the proposal is to deepen dire Attach the Bond under which the following completion of the involv testing has been completed. Final determined that the site is ready for final Method for Water Disposa Name of formation proof Amount of water product How water is stored on 	Convert to Injection Operation (clearly state all per ectionally or recomplete horizon work will performed or provid ed operations. If the operation Abandonment Notice shall be al inspection.)	Plug back rtinent details including estim ntally, give subsurface locatio le the Bond No. on file with results in a multiple comple e filed only after all require Gone Spring 517 BWPD rglass tanks	Water Disposa ated starting date of ins and measured and in the BLM/ BIA. Req ition or recompletion in	any proposed work and appro true vertical depths or pertin uired subsequent reports shall in a new interval, a Form 316 mantion, have been completed	ent markers and be filed within 30 60-4 shall be filed , and the operato				
 3. Describe Proposed or Completed If the proposal is to deepen dird Attach the Bond under which the following completion of the involv testing has been completed. Final determined that the site is ready for final Method for Water Disposa 1) Name of formation produ- 2) Amount of water produ- 3) How water is stored on 4) How water is moved to 5) Disposal Facility: a) Facility owner name 	Convert to Injection Operation (clearly state all per ectionally or recomplete horizon work will performed or provid ed operations. If the operation Abandonment Notice shall be al inspection.)	Plug back rtinent details including estim ntally, give subsurface locatio te the Bond No. on file with results in a multiple comple e filed only after all require Bone Spring 517 BWPD rglass tanks ed	Water Disposa ated starting date of ins and measured and in the BLM/ BIA. Req tion or recompletion in ements, including recla	any proposed work and appro true vertical depths or pertin uired subsequent reports shall n a new interval, a Form 316 mantion, have been completed.	ent markers and be filed within 30 50-4 shall be filed , and the operato				
 3. Describe Proposed or Completed If the proposal is to deepen dire Attach the Bond under which the following completion of the involv testing has been completed. Final determined that the site is ready for final Method for Water Disposa 1) Name of formation produces 2) Amount of water produces 3) How water is stored on 4) How water is moved to 5) Disposal Facility: a) Facility owner name b) Name of facility or w c) Type of facility or w 	Convert to Injection Operation (clearly state all per ectionally or recomplete horizon work will performed or provid ed operations. If the operation Abandonment Notice shall be al inspection.)	Plug back rtinent details including estim ntally, give subsurface locatio le the Bond No. on file with results in a multiple comple e filed only after all require Some Spring 517 BWPD rglass tanks ed State HU Order #SWI	Water Disposa ated starting date of ins and measured and in the BLM/ BIA. Req tion or recompletion in ements, including recla	any proposed work and appro- true vertical depths or pertin- uired subsequent reports shall in a new interval, a Form 316 mantion, have been completed Scented Kertect NMOCD APR 2 1 20 NMOCD ARTE	ent markers and be filed within 30 30-4 shall be filed , and the operate d ED 14 SA				
 3. Describe Proposed or Completed 3. Describe Proposal is to deepen dired 4. Attach the Bond under which the following completion of the involve testing has been completed. Final determined that the site is ready for final determined that the site is dete	Convert to Injection Operation (clearly state all per ectionally or recomplete horizon work will performed or provid ed operations. If the operation Abandonment Notice shall be al inspection.)	Plug back rtinent details including estim ntally, give subsurface locatio le the Bond No. on file with results in a multiple comple e filed only after all require Some Spring 517 BWPD rglass tanks ed State HU Order #SWI	Water Disposa ated starting date of ns and measured and n the BLM/ BIA. Req tion or recompletion in ements, including recla	any proposed work and appro- true vertical depths or pertin- uired subsequent reports shall in a new interval, a Form 316 mantion, have been completed STATION RECEIV APR 2 1 20 NMOCD ARTE	ent markers and be filed within 30 50-4 shall be filed , and the operate d EDT 14 SIA FOR				
 3. Describe Proposed or Completed If the proposal is to deepen dire Attach the Bond under which the following completion of the involv testing has been completed. Final determined that the site is ready for final Method for Water Disposa 1) Name of formation produces 2) Amount of water produces 3) How water is stored on 4) How water is moved to 5) Disposal Facility: a) Facility owner name b) Name of facility or w c) Type of facility or w 	Convert to Injection Operation (clearly state all per ectionally or recomplete horizon work will performed or provid ed operations. If the operation Abandonment Notice shall be al inspection.) I ducing water on lease: B ced in barrels per day: 5 lease: 2 - 500 BBL fiber disposal facility: Trucket : COG Operating LLC vell name and number: S ell: WDW Section, Township & Ra SUBJE	Plug back rtinent details including estim ntally, give subsurface locatio le the Bond No. on file with results in a multiple comple e filed only after all require Some Spring 517 BWPD rglass tanks ed State HU Order #SWI	Water Disposa ated starting date of ns and measured and n the BLM/ BIA. Req tion or recompletion in ements, including recla	any proposed work and appro- true vertical depths or pertin- uired subsequent reports shall in a new interval, a Form 316 mantion, have been completed Scented Kertect NMOCD APR 2 1 20 NMOCD ARTE	ent markers and be filed within 30 50-4 shall be filed , and the operate d EDT 14 SIA FOR				
 13. Describe Proposed or Completed If the proposal is to deepen dirk Attach the Bond under which the following completion of the involv testing has been completed. Final determined that the site is ready for final Method for Water Disposa 1) Name of formation produces 1) Name of formation produces 2) Amount of water produces 3) How water is stored on 4) How water is moved to 5) Disposal Facility: a) Facility owner name b) Name of facility or w c) Type of facility or w d) Location by 1/4,1/4, 	Convert to Injection Operation (clearly state all per ectionally or recomplete horizon work will performed or provid ed operations. If the operation Abandonment Notice shall be al inspection.) I ducing water on lease: B ced in barrels per day: 5 lease: 2 - 500 BBL fiber disposal facility: Trucket : COG Operating LLC vell name and number: S ell: WDW Section, Township & Ra APPROV	Plug back rtinent details including estim ntally, give subsurface locatio le the Bond No. on file with results in a multiple comple e filed only after all require Bone Spring 517 BWPD rglass tanks ed State HU Order #SWI ange: SESW Sec7-T19 ECT TO LIKE	Water Disposa ated starting date of ns and measured and n the BLM/ BIA. Req tion or recompletion in ements, including recla	any proposed work and appro- true vertical depths or pertin- uired subsequent reports shall in a new interval, a Form 316 mantion, have been completed STATION RECEIV APR 2 1 20 NMOCD ARTE	ent markers and be filed within 30 50-4 shall be filed , and the operato d EDT 14 SIA FOR				
 (3) Describe Proposed or Completed If the proposal is to deepen dir Attach the Bond under which the following completion of the involv testing has been completed. Final determined that the site is ready for fina Method for Water Disposa 1) Name of formation produces 1) Name of formation produces 2) Amount of water produces 3) How water is stored on 4) How water is moved to 5) Disposal Facility: a) Facility owner name b) Name of facility or w c) Type of facility or w d) Location by 1/4,1/4, Continued please see attact 	Convert to Injection Operation (clearly state all per ectionally or recomplete horizon work will performed or provid ed operations. If the operation Abandonment Notice shall be al inspection.) I ducing water on lease: B ced in barrels per day: 5 lease: 2 - 500 BBL fiber disposal facility: Trucket : COG Operating LLC vell name and number: S ell: WDW Section, Township & Ra APPROV	Plug back rtinent details including estim ntally, give subsurface locatio le the Bond No. on file with results in a multiple comple e filed only after all require Bone Spring 617 BWPD rglass tanks ed State HU Order #SWI ange: SESW Sec7-TIS ECT TO LIKE VAL BY STATE Title:	Water Disposa ated starting date of ns and measured and n the BLM/ BIA. Req tion or recompletion in ements, including recla	any proposed work and appro true vertical depths or pertin uired subsequent reports shall in a new interval, a Form 316 mantion, have been completed MADCO RECEIV APR 21 20 NMOCD ARTE SEE ATTACHED DITIONS OF APP	ent markers and be filed within 30 50-4 shall be filed, and the operato d EDT 14 SA FOR				

U U THIS SPACE FOR FEDERAL OR STATE OFFICE USE () V F ()									1					
Approved by:	/s/ Je	erry Blakley			Title:					Date:				
	proval, if any are attache applicant holds legal or e entitle the appli		rights in the s	ubject lease	Office:		APR	17	2014					
	Section 1001 AND Title ctitiousor fraudulent stateme						wingly and				ment or	agency o	of the	United
(Instructions on	bage 2)						CARLSB	AD FIE	LD OFFI	CE				

1) Name of formation producing water on lease: Bone Spring

- 2) Amount of water produced in barrels per day: 517 BWPD
- 3) How water is stored on lease: 2 500 BBL fiberglass tanks
- 4) How water is moved to disposal facility: Trucked
- 5) Disposal Facility:

J.

£

ي:-

- a) Facility Owner Name: Mesquite SWD, INC
- b) Name of facility or well name and number: Big Eddy SWD #1 SWD-1186
- c) Type of facility or well: WDW
- d) Location by 1/4,1/4, Section, Township & Range: SESE, Sec3-T20SR31E

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

4/16/2014 Approved subject to conditions of approval JDB:

Disposal of Produced Water From Federal Wells Conditions of Approval

Approval of the produced water disposal methodology is subject to the following conditions of approval:

1. This agency shall be notified of any change in your method or location of disposal.

2. Compliance with all provisions of Onshore Order No. 7.

- 3. This agency shall be notified of any spill or discharge as required by NTL-3A.
- 4. This agency reserves the right to modify or rescind approval whenever it determines continued use of the approved method may adversely affect the surface or subsurface environments.
- 5. All above ground structures on the lease shall be painted Shale Green (5Y 4/2), or as per approved APD stipulations. This is to be done within 90 days, if you have not already done so.
- 6. Any on-lease open top storage tanks shall be covered with a protective cover to prevent entry by birds and other wildlife.
- 7. This approval should not constitute the granting of any right-of-way or construction rights not granted by the lease instrument.
- 8. If water is transported via a pipeline that extends beyond the lease boundary, then you need to submit within 30 days an application for right-of-way approval to the Realty Section in this office if you have not already done so.

9. This **approval is for produced water disposal only** and any hydrocarbons removed from lease by this method will be subject to royalty payment as well as other enforcement actions as necessary.

10. Disposal at any other site will require prior approval.

11. Subject to like approval by NMOCD.

JDB2014