Form 3160-5 (August 2007)

1. Type of Well

3a. Address

Oil Well

300 N. Marienfeld, Suite 950

J-26-08S-22E 1980' FSL 1780' FEL

Midland, Texas 79701

Name of Operator
 Scythian, Ltd., a Texas Limited Partnership

Gas Well

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

N.M. OIL CONSE	RVATION DIVI	SION ORM APPROVED MB No. 1004-0137
811 S. FD	RST STREET	Expires: July 31, 2010

ly 31, 2010

O. LI	KOT OTKEFT	Expires: Ju
тгег	5. Arease Seria	l No.

SUNDRY NOTICES AND REPORTS ON WELLS	
Do not use this form for proposals to drill or to re-enter an	

abandoned well. Use Form 3160-3 (APD) for such proposals.

Other

SUBMIT IN TRIPLICATE - Other instructions on page 2.

ARTESIA, NIMINAI 22059 6. If Indian, Allottee or Tribe Name 7. If Unit of CA/Agreement, Name and/or No. 8. Well Name and No. April Federal #001 9. API Well No. 30-005-61276 10. Field and Pool or Exploratory Area Pecos Slope; Abo, West (Gas) 11. Country or Parish, State Chaves, New Mexico 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen Production (Start/Resume) Water Shut-Off Notice of Intent Well Integrity Alter Casing Fracture Treat Reclamation Other Corrective action Casing Repair New Construction Recomplete Subsequent Report to address "Surface Plug and Abandon Change Plans Temporarily Abandon Exceptions" Final Abandonment Notice Plug Back Convert to Injection Water Disposal

3b. Phone No. (include area code)

432-685-3602

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Specific to the BLM's (Roswell Office) Inspection on Scythian, Ltd's Pecos Slope Field:

"No Sign on Location" rectified by Scythian's Field Foreman, Chris Smith

Accepted to record ACO NMOCD9-3-2019

NM OIL CONSERVATION ARTESIA DISTRICT

AUG 28 2014

RECEIVED

	 are attached. Approval of this notice does not warrant or certion or equitable title to those rights in the subject lease which would be operations thereon. 	
Approved by	/S/ Angel Mayes	Assistant Field Manager, ands And Minerals Date 8-36-14
	THIS SPACE FOR FEDERA	AL OR STATE OFFICE USE
Signature TM	My a Clipton 10	ate 06/03/2013
14. I hereby certify that the s Name (Printed/Typed) Thomas		tle Agent and Attorney-In-Fact for Scythian, Ltd.

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.