Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT 5. Lease Serial No.

FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007

	NM 98122	
6.	If Indian, Allottee or Tribe Name	

SUNDRY NOTICES AND REPORTS ON WELLS			NM 98122		
Do not use this form for proposals abandoned well. Use Form 3160 - 3	to drill or to re	e-enter an	6. If Indian,	Allottee or Tribe Name	
SUBMIT IN TRIPLICATE- Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well Gas Well Other			Skelly Unit 8. Well Name and No.		
2. Name of Operator The Wiser Oil Company				IN	
3a Address	3b. Phone No. fino	lude area code)	9. API Well 30-015-0		
3504 West County Road Hobbs, New Mexico 88240	505 392-9707		10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		2 1 2005		rg Jackson 7-Rivers QN-GB-SA r Parish, State	
660' FNL & 1980' FEL Sec. 28-T17S-R31E Unit B				Eddy County, New Mexico	
12 CHECK ADDODDIATE DOVICE TO					
12. CHECK APPROPRIATE BOX(ES) TO			EPORT, OR	OTHER DATA	
TYPE OF SUBMISSION		TYPE OF ACTION			
Notice of Intent Acidize Alter Casing	Deepen	Production (St	art/Resume)	Water Shut-Off	
	Fracture Treat New Construction	Reclamation Recomplete		Well Integrity Other Clean Out	
Change Plans	Plug and Abando	<u> </u>			
Final Abandonment Notice Convert to Injection	Final Abandonment Notice				
testing has been completed. Final Abandonment Notices shall be determined that the site is ready for final inspection.) 5/13/05 MIRU PU. 5/16/05 ND WH. NU BOP. Released AD-1 pkr. POH Cleaned out to 3623'. Circulate hole clean. PC 5/17/05 POH tallying string. PBTD @ 3639'. RIH w/I 5/18/05 RU Gray WL. Perforated San Andres f/3633'. 3560'-65' & 3543'-50' 4 SPF (80 holes). Perfor & 3434'-40' 4 SPF (144 holes). POH & RD WI PSI. RD testers. Set pkr. @ 3336'. 5/19/05 Released pkr. RU Petro-Plex. Pickled tbg. w/. Acidized San Andres Grayburg 3638'-3434' w/. ISIP 1856. 5 min. 1833. 10 min. 1818. 15 min 5/20/05 Released pkr. POH LD 2-7/8'' workstring & pto 500 PSI. Held ok. Released pkr. Circulate 5/24/05 Ran integrity test. Pressured annulus to 500 PNMOCD called but did not witness. Gave ok 1	w/2-3/8" tbg. & pki DH w/7 stands. DC's. POH & LD D -38' & 3617'-24' 4 Sl ated Grayburg f/35: L. RU Monk testers 200 gals. 15% NE- /8200 gals. 15% NE- 1806. SI well. RO skr. RIH w/AD-1 pl pkr. fluid. Reset pl 'SI for 30 mins. Hel	r. RIH w/3-3/4" bit & I C's. PF (48 holes). POH. Po 16'-40' & 3510'-20' 4 SF RIH w/Arrowset pkr. E & reversed out to pit. FE anti-sludge acid w/r Petro Plex. tr. on 102 jts. 2-3/8" IF kr. Tested to 500 PSI. d ok. Test performed b	oC's on 2-3/8" Frorated Grayl F (56 holes). Pron 2-7/8" work Reset pkr. Prock salt diversion C tbg. Set pkr Held ok. RD Progray Nick Jimenz	work string. Tagged @ 3444'. burg f/3583'-88', 3577'-80', Perforated Grayburg f/3460'-90' k string hydrotesting to 6000 ressure annulus to 500 PSI. ions. Overflushed w/33 bbls. r. @ 3379'. Pressured annulus bu. with Gandy Corporation.	
14. Thereby certify that the foregoing is true and correct					
Name (Printed/Typed) Mary Jo Turner	Title	Production Analyst			
Signature Man On Tunan	Date		1005	-d . N	
THIS SPACE FOR	FEDERAL OF			Accepted for record - N	
Approved by Conditions of approval, if any, are attached. Approval of this notic	e does not unerent or	Title	D	ate	
Conditions of approval, it any, are attached. Approval of this holic	e does not wantame of	1			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to anymatter within its jurisdiction.

Office

(Instructions on page 2)

certify that the applicant holds legal or equitable title to those rights in the subject lease

which would entitle the applicant to conduct operations thereon.

