

NW COR SEC 32
NMSP-E (NAD 27)
Y = 398263.0' N
X = 662536.5' E
LAT.= 32°05'37.87"N
LONG.=103°48'30.53"W

TOP PERF
NMSP-E (NAD 83)
Y = 394399.7' N
X = 708376.2' E
LAT.= 32° 04' 59.29"N
LONG.= 103° 47' 38.38"W
NMSP-E (NAD 27)
Y = 394342.0' N
X = 667190.3' E
LAT.= 32.0830118"N
LONG.= 103.7935172"W

SW COR SEC 32
NW COR SEC 5
NMSP-E (NAD 27)
Y = 392939.4' N
X = 662556.5' E
LAT.=32°04'45.19"N
LONG.=103°48'30.60"W

SW COR SEC 5
NMSP-E (NAD 27)
Y = 387617.5' N
X = 662585.0' E
LAT.=32°03'52.62"N
LONG.=103°48'30.57"W

The map shows a grid of sections. Section 32 is on the left, and Section 5 is on the right. A vertical line separates them. A horizontal line runs through the middle. A dashed line runs vertically through Section 32. A well location is marked with a circle and a crosshair. Measurements include 2180' FNL, 660' FEL, EL.=3,286', 1,366' FROM SECTION 32 SOUTH LINE, 682' FROM SECTION 32 EAST LINE, MD=11,590', 351' FSL, 656' FEL, MD=17,935', 351', 656', and 4351'.

NE COR SEC 32
NMSP-E (NAD 27)
Y = 398291.5' N
X = 667847.4' E
LAT.= 32°05'37.89"N
LONG.= 103°47'28.79"W

PLU PHANTOM BANKS
32 25 31 USA - SHL
NMSP-E (NAD 83)
Y = 396166.3' N
X = 708386.9' E
LAT.= 32° 05' 16.77"N
LONG.= 103° 47' 38.15"W
NMSP-E (NAD 27)
Y = 396108.5' N
X = 667201.1' E
LAT.= 32.0878678"N
LONG.= 103.7934539"W

SE COR SEC 32/
NE COR SEC 5
NMSP-E (NAD 27)
Y = 392981.4' N
X = 667880.6' E
LAT.=32°04'45.34"N
LONG.=103°47'28.72"W

TERMINUS
NMSP-E (NAD 83)
Y = 388058.1' N
X = 708427.9' E
LAT.= 32° 03' 56.53"N
LONG.= 103° 47' 38.15"W
NMSP-E (NAD 27)
Y = 388000.5' N
X = 667241.7' E
LAT.= 32.0655787"N
LONG.= 103.7934537"W

SE COR SEC 5
NMSP-E (NAD 27)
Y = 387653.9' N
X = 667898.9' E
LAT.=32°03'52.62"N
LONG.=103°47'28.82"W

OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

Signature

Date

Tracie J. Cherry

Print Name

tjcherry@basspet.com

E-mail Address

SURVEYORS CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

JANUARY 28, 2014

Date of Survey

Signature and Seal of Professional Surveyor

The seal is circular with "JAMES E. TOMPKINS" around the top and "NEW MEXICO" around the bottom. In the center, it says "REGISTERED PROFESSIONAL LAND SURVEYOR" and "14729".

Job No. WTC50474

JAMES E. TOMPKINS 14729

Certificate Number

GENERAL OFFICES - FORT WORTH, TEXAS

NM OIL CONSERVATION

ARTESTA DISTRICT

BOPCO, L.P.

P.O. Box 2760
Midland, Tx 79702
(432) 683-2277
(432) 687-0329 (fax)

FEB 23 2015

RECEIVED

February 18, 2015

Oil Conservation Division
811 S. First St.
Artesia NM 88210

Re: Poker Lake Unit CVX JV PB 008H
WC G-06 S253002O; Bone Spring
30-015-42630


Gentlemen:

It was determined, after being submitted, the location of the top perforation had been mis-spotted. BOPCO, LP is submitting this revised NMOCD Form C102 showing the corrected location of the top perforation.

A Sundry Notice and revised C102 have also been submitted to the Bureau of Land Management this date.

If you have any questions or need additional information, please call me at 432/683-2277.

Sincerely,



Tracie J Cherry
Sr. Regulatory Analyst

Enclosures