Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BURFAGE AND MANAGEMENT

OCD	Artesia

FORM APPROVED OMB NO. 1004-0135

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill of to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on reverse side:					5. Lease Serial No. NMNM86024 6. If Indian, Allottee of Tribe Name			
					Type of Well Gas Well □ Other			
Name of Operator					9. API Well No. 30-015-43076-00-X1			
3a. Address 5 GREENWAY PLAZA STE 1 HOUSTON, TX 77046-0521	(include area code 5.57.17) ,	10. Field and Pool, of Exploratory CEDAR CANYON					
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, and State			
Sec 34 T23S R29E NWNW 210FNL 330FWL 32.267892 N Lat, 103.979625 W Lon					EDDY COUNTY, NM			
12. CHECK APPI	OPRIATE BOX(ES) TO	O INDICATE	NATURE OF	NOTICE, R	EPORT, OR OTHE	ER DATA		
TYPE OF SUBMISSION		•	ТҮРЕ О	F ACTION				
Notice of Intent	□ Acidize	☐ Dee	pen .	☐ Produc	tion_(Start/Resume)	□ Water Shut-	Off	
☐ Subsequent Report	☐ Alter Casing		ture Treat	☐ Reclan		☐ Well Integri	ty	
	☐ Casing Repair		Construction	□ Recom	•	Other Change to Original A		
☐ Final Abandonment Notice	☐ Change Plans	- ; •			arity Agandon PD		5	
12 D 3 D 4 O 1 1 1 O	Convert to Injection			□ Water I				
13. Describe Proposed or Completed Op If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f	ally or recomplete horizontally rk will be performed or provide Loperations. If the operation re pandonment Notices shall be fi	, give subsurface the Bond No. or sults in a multip	locations and meas n file with BLM/BL le completion or rec	ured and true v A. Required su completion in a	ertical depths of all perti- bsequent reports shall b new interval, a Form 31 n, have been completed	inent-markers and zor to filed within 30 days 60-4 shall be filed on I, and the operator has	nes. S Ice	
OXY USA Inc. respectfully red	quests approval for the fo	llowing chang	es to the drilling	j plan:	NM	1011 00		
Add DV tool and ACP 120' cement comes to surface duri cancelation cone for the DV to	below surface casing sho	435° be for continge we will inflate	ency second sta the ACP and th	ge cement joinen drop the	ob. If	ARTESIA DIST	RVATIC	
Add second stage continge		we do not circ	ulaté cèment to	surface dur	na	AUG 18 20) <i>15</i> .	
the first stage.	ney coment in the event			Surface dui	ilig	RECEIVED		
Intermediate Casing 7-5/8" 26.4# L-80 BT&C new	csg @ 0-3050', 9-7/8" ho	le w/ 10.0# m	ud SEE	ATTAC	HED FOR		•	
					S OF APPRO	OVAL	•	
14. I hereby certify that the foregoing is		240050	`			18/19/	18/15	
C	# Electronic Submission For OXY US	A INCORPORA	TED, sent to the	e Carlsbåd		Accepted/io	r recom	
Name (Printed/Typed) DAVID ST	tted to AFMSS for process	ing by CHRIS	,	on 08/10/201 LATORY AD		MMOC	D	
· ·	LVVAICI		THIC IXEGO	LATORT AL	WISOK			
Signature (Electronic S	Submission)		Date 08/10/2	2015	A 50 50 50			
,	THIS SPACE FO	OR FEDERA	AL OR STATE	OFFICE U	SE APPKU	IVEU		
Approved By			Title			Dat		
Approved By Conditions of approval, if any, are attached. Approval of this notice does not warrant or			Title		AUG 1-0	2015 Date	1.	
ertify that the applicant holds legal or equivalent to conduct the applicant to conduct the appl	uitable title to those rights in th	e subject lease	Office		/s/ Chris	Walls		
Fitle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations a	s to any matter w	erson knowingly an othin its jurisdiction	d willfully to m	ake to amy departingant CANLSDAU FIEL	BUFFICE.	d	

Additional data for EC transaction #312250 that would not fit on the form

32. Additional remarks; continued

Coll Rating (psi)-3400 Burst Rating (psi)-6020 SF Coll-5.30 SF Burst-1.37 SF Ten-3.58

Intermediate - Circulate cement to surface w/ 630sx HES light PP cmt w/ 5% Salt + .3% HR-800 + 6% / Bentonite, 12.9ppg 1.744 yield 824# 24hs CS 125% Excess followed by 200sx PP cmt, 14.8ppg 1.326 yield 1789# 24hr CS 125% Excess.

Contingency 2nd Stage - Circulate cement to surface w/ 100sx HES light PP cmt w/ 5% Salt + .3% HR-800 + 6% Bentonite, 12.9ppg 1.744 yield 824# 24hs CS 200% Excess followed by 200sx PP cmt w/ 2% CaCl2, 14.8ppg 1.326 yield 1789# 24hr CS 125% Excess.

Description of Cement Additives: Calcium Chloride, Salt (Accelerator); Bentonite (Light Weight Additive); HR-800 (Retarder)

The above cement volumes could be revised pending the caliper measurement.

PECOS DISTRICT CONDITIONS OF APPROVAL

OPERATOR'S NAME:

OXY USA Inc

LEASE NO.:

NM86024

WELL NAME & NO.:

10H-Cypress 34 Federal

SURFACE HOLE FOOTAGE: BOTTOM HOLE FOOTAGE

210'/N & 330'/W 180'/S & 820'/W

LOCATION:

Section 34, T. 23 S., R. 29 E., NMPM

COUNTY:

Eddy County, New Mexico

A. CASING

Changes to the approved APD casing program need prior approval if the items substituted are of lesser grade or different casing size or are Non-API. The Operator can exchange the components of the proposal with that of superior strength (i.e. changing from J-55 to N-80, or from 36# to 40#). Changes to the approved cement program need prior approval if the altered cement plan has less volume or strength or if the changes are substantial (i.e. Multistage tool, ECP, etc.). The initial wellhead installed on the well will remain on the well with spools used as needed.

Centralizers required on surface casing per Onshore Order 2.III.B.1.f.

Wait on cement (WOC) time prior to drilling out for a primary cement job will be a minimum 18 hours for a water basin, 24 hours in the potash area, or 500 pounds compressive strength, whichever is greater for all casing strings. DURING THIS WOC TIME, NO DRILL PIPE, ETC. SHALL BE RUN IN THE HOLE. Provide compressive strengths including hours to reach required 500 pounds compressive strength prior to cementing each casing string. IF OPERATOR DOES NOT HAVE THE WELL SPECIFIC CEMENT DETAILS ONSITE PRIOR TO PUMPING THE CEMENT FOR EACH CASING STRING, THE WOC WILL BE 30 HOURS. See individual casing strings for details regarding lead cement slurry requirements.

No pea gravel permitted for remedial or fall back remedial without prior authorization from the BLM engineer.

R-111-P potash Medium cave/karst Possible water flows in Castile and Salado. Posible lost circulation in Rustler, Salado and Delaware.

- 1. The 10 3/4 inch surface casing shall be set at approximately 300 feet (a minimum of 25 feet into the Rustler Anhydrite and above the salt) and cemented to the surface. If salt is encountered, the operator shall set the casing 25' above the salt.
 - a. If cement does not circulate to the surface, the appropriate BLM office shall be notified and a temperature survey utilizing an electronic type temperature survey with surface log readout will be used or a cement bond log shall be run to verify the top of the cement. Temperature survey will be run a minimum of six hours after pumping cement and ideally between 8-10 hours after completing the cement job.
 - b. Wait on cement (WOC) time for a primary cement job is to include the lead cement slurry.
 - c. Wait on cement (WOC) time for a remedial job will be a minimum of 4 hours after bringing cement to surface or 500 pounds compressive strength, whichever is greater.
 - d. If cement falls back, remedial cementing will be done prior to drilling out that string.

Formation below the 10-3/4" shoe to be tested according to Onshore Order 2.III.B.1.i. Test to be done as a mud equivalency test using the mud weight necessary for the pore pressure of the formation below the shoe and the mud weight for the bottom of the hole. Report results to BLM office.

- 2. The minimum required fill of cement behind the 7-5/8 inch intermediate casing, which shall be set in the basal anhydrite of the Castile formation at approximately 3050', is:
 - a. First stage to DV tool:
 - □ Cement to circulate. If cement does not circulate, contact the appropriate
 □ BLM office before proceeding with second stage cement job. Operator should
 □ have plans as to how they will achieve circulation on the next stage.

Operator has proposed a contingency DV tool at 435'. If operator circulates cement on the first stage, operator is approved to inflate the ACP and run the DV tool cancellation plug and cancel the second stage of the proposed cement plan. If cement does not circulate, operator will inflate ACP and proceed with the second stage.

- b. Second stage above DV tool:
- ⊠ Cement to surface. If cement does not circulate see B.1.a, c-d above.

Wait on cement (WOC) time for a primary cement job is to include the lead cement slurry due to cave/karst and potash.

Formation below the 7-5/8" shoe to be tested according to Onshore Order 2.III.B.1.i. Test to be done as a mud equivalency test using the mud weight necessary for the pore pressure of the formation below the shoe (not the mud weight required to prevent dissolving the salt formation) and the mud weight for the bottom of the hole. Report results to BLM office.

- 3. The minimum required fill of cement behind the $5-1/2 \times 4-1/2$ inch production casing is:
 - Cement to surface. If cement does not circulate, contact the appropriate BLM office.
- 4. If hardband drill pipe is rotated inside casing, returns will be monitored for metal. If metal is found in samples, drill pipe will be pulled and rubber protectors which have a larger diameter than the tool joints of the drill pipe will be installed prior to continuing drilling operations.
- 5. Whenever a casing string is cemented in the R-111-P potash area, the NMOCD requirements shall be followed.

CRW 081015